

38 Woodlands Industrial Park E1
 #05-18, Singapore 757700
 Tel: 64688834 Fax: 64622278
 E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2203-112
 DATE : 1-Mar-2022
 POLICY NO. : FWD PNPV2020-0001754-02
 VEHICLE REG. NO. : SMJ1193M
 VEHICLE MAKE : SWIFT SPORTS 1.4L TURBO MANUAL

TO Motor Claim Department
 China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	SPARE PARTS			
1	Rear Bumper Sport Version <i>de /</i>	1	\$ 750.00	\$ 750.00
2	Rear Bumper Clips <i>re /</i>	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH <i>X NN</i>	1	\$ 30.00	\$ 30.00
4	Rear Bumper Retainer LH <i>cut /</i>	1	\$ 30.00	\$ 30.00
6	Rear Bumper Extension LH (7) <i>X de /</i>	1	\$ 45.00	\$ 45.00
7	Rear Bumper Garnish LH (3) <i>X NN</i>	1	\$ 45.00	\$ 45.00
8	Rear Fog Lamp <i>X NN</i>	1	\$ 65.00	\$ 65.00
9	Rear License Lamp <i>X NNN</i>	1	\$ 45.00	\$ 45.00
11	Rear Fender LH <i>bt /</i>	1	\$ 550.00	\$ 550.00
12	Rear Fender Shield LH <i>3 X NN</i>	1	\$ 180.00	\$ 180.00
13	Rear Fender RH <i>repair X</i>	1	\$ 550.00	\$ 550.00
14	Rear Fender Shield RH <i>X NN</i>	1	\$ 180.00	\$ 180.00
15	Rear Fender Clips <i>re /</i>	10	\$ 5.00	\$ 50.00
16	Rear Fender Guard Garnish RH <i>X NN</i>	1	\$ 40.00	\$ 40.00
17	Rear Fender Guard Garnish LH <i>X NN</i>	1	\$ 40.00	\$ 40.00
18	Rear Tailgate Door <i>bt /</i>	1	\$ 880.00	\$ 880.00
19	Rear Tailgate Door WeatherStrip <i>re /</i>	1	\$ 90.00	\$ 90.00
20	Rear Tailgate Door Inner Trim <i>? X NN</i>	1	\$ 220.00	\$ 220.00
21	Rear Tailgate Balancer RH - 81800-63812 <i>X NN</i>	1	\$ 150.00	\$ 150.00
22	Rear Tailgate Balancer LH - 81800-63822 <i>X NN</i>	1	\$ 150.00	\$ 150.00
23	Rear Tailgate Door Lock Handle (Red) <i>X NN</i>	1	\$ 50.00	\$ 50.00
24	Rear Tailgate Door Lock <i>X NN</i>	1	\$ 200.00	\$ 200.00
25	Rear Tailgate Door Lock Latch <i>X NN</i>	1	\$ 40.00	\$ 40.00
26	Rear Tailgate Spoiler Assy <i>X NN</i>	1	\$ 600.00	\$ 600.00
27	Rear Emblem - S (Chrome) <i>re /</i>	1	\$ 40.00	\$ 40.00
28	Rear Emblem - Swift (Chrome) <i>re /</i>	1	\$ 45.00	\$ 45.00
29	Rear Emblem - Sports (Chrome Red) <i>re /</i>	1	\$ 45.00	\$ 45.00
30	Rear / End Panel Garnish <i>? X NN</i>	1	\$ 80.00	\$ 80.00
31	End Panel <i>bt /</i>	1	\$ 350.00	\$ 350.00
32	Spare Tyre Board Cover <i>X NN</i>	1	\$ 120.00	\$ 120.00
33	Rear Tools Sponge Box/Tray <i>X NN</i>	1	\$ 90.00	\$ 90.00

38 Woodlands Industrial Park E1
 #05-18, Singapore 757700
 Tel: 64688834 Fax: 64622278
 E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2203-112
 DATE : 1-Mar-2022
 POLICY NO. : FWD PNPV2020-0001754-02
 VEHICLE REG. NO. : SMJ1193M
 VEHICLE MAKE : SWIFT SPORTS 1.4L TURBO MANUAL

TO Motor Claim Department
 China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

Rasul - Hp 90010068
 8 days - L/S / 02/03/22 @ 1140
 Resurvey after repair

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
35	Rear Tail Lamp Assy RH <i>CRA /</i>	1	\$ 720.00	\$ 720.00
36	Rear Tail Lamp Assy LH <i>3 X M</i>	1	\$ 720.00	\$ 720.00
37	Rear Tail Lamp High Mount Stop <i>X M</i>	1	\$ 140.00	\$ 140.00
38	Rear Taillamp Inner Housing LH <i>bt /</i>	1	\$ 90.00	\$ 90.00
39	Rear Exhaust Tail Chrome Pipe LH <i>bt /</i>	1	\$ 200.00	\$ 200.00
42	Rear Exhaust Muffler <i>? X M</i>	2	\$ 720.00	\$ 1,440.00
43	Rear Exhaust Rubber Mount <i>X M</i>	2	\$ 30.00	\$ 60.00
Total Spare Parts				\$ 9,170.00
SPECIAL NETT				
44	Rear Windscreen Sealant <i>n /</i>	1	\$ 40.00	\$ 40.00
45	Rear Licence Plate <i>bt /</i>	1	\$ 35.00	\$ 35.00
46	Reverse Sensor <i>AW /</i>	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 275.00
LABOUR				
47	Spray painting Rear Bumper, Tailgate, Both Rear Fender Including Blending	1	\$ 1,000.00	\$ 1,000.00
48	Remove, Replace and Repair Accident Affected Area	1	\$ 1,000.00	\$ 1,000.00
49	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
50	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 100.00	\$ 100.00
51	Remove and Refit Rear Exhaust Pipe and Silencer, Re-align	1	\$ 100.00	\$ 100.00
52	Remove and Refit Rear Windscreen	1	\$ 100.00	\$ 100.00
53	Remove and Refit Rear Reverse Sensor	1	\$ 100.00	\$ 100.00
54	Anti-Rust Tuff Coat	1	\$ 40.00	\$ 40.00
55	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,570.00
Amount Before Excess				\$ 12,015.00
Add GST @ 7%				841.05
Total Amount Payable				\$ 12,856.05

3935
 X 15%
 X 3344.75
 275
 1000
 900
 60
 60
 60
 60
 60
 60
 2270
 X M

Estimate prepared by: Oscar Pong

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Please arrange this vehicle to be surveyed soonest possible. Thank you.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P - 3344.75
 S/N - 275.00
 L - 2270.00
 Suppl - 399.50
 T - 6289.25
 20%
 5031.40

L/S - \$5,050

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Supplementary Estimate**38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2203-112 (SUP)
DATE : 22-Feb-2022
POLICY NO. : FWD PNPV2020-0001754-02
VEHICLE REG. NO. : **SMJ1193M**
VEHICLE MAKE : SWIFT SPORTS 1.4L TURBO MANUAL**TO** Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033**FOR SURVEYOR****ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
<u>SPARE PARTS</u>				
1	Front Air Vent LH cra ✓	1	\$ 40.00	\$ 40.00
2	Front Air Vent RH cra ✓	1	\$ 40.00	\$ 40.00
3	Front Fender Inner Garnish LH cra ✓	1	\$ 300.00	\$ 300.00
4	Rear Tailgate Rubber Stopper nec ✓	1	\$ 10.00	\$ 10.00
5	Rear Spoiler Seal cut ✓	1	\$ 80.00	\$ 80.00
Total Spare Parts				\$ 470.00
<u>SPECIAL NETT</u>				
Total Special Nett				\$ -
<u>LABOUR</u>				
Total Labour				\$ -

**470
15%
399.50****Estimate prepared by: Oscar Pong**

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.

Total Labour	\$ -
Amount Before Excess	\$ 470.00
Add GST @ 7%	32.90
Total Amount Payable	\$ 502.90