

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKU 881 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00 ? photo. Xun	
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACCUM AND REGAS.	S/N \$ 1,400.00 ? photo. Xun	
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,200.00 1000. ✓	
5	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,000.00 1100 ✓	
6	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 8,852.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKU 881 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,987.00	cm ✓
2	FRONT BUMPER FIXING PARTS	1	\$ 195.00	R1 ✓
3	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 86.00	R1 ✓
4	FRONT BUMPER LOWER GRILLE - CENTER	1	\$ 179.00	? de ✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 571.00	? ✓
6	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 636.00	? } h ✓
7	FRONT BUMPER COVER TRIM - LH / RH	2	\$ 364.00	? } h ✓
8	FRONT BUMPER ADAPTER - LH / RH	2	\$ 84.00	? } h ✓
9	RADIATOR GRILLE	1	\$ 1,406.00	cm ✓
10	RADIATOR GRILLE CLOSING ELEMENT	1	\$ 210.00	? de ✓
11	CAUTION STICKER	1	\$ 16.00	? ne ✓
12	A/C STICKER	1	\$ 9.00	? ne ✓
13	FRONT BUMPER AIR GRILLE - RH	1	\$ 210.00	? } h ✓
14	FRONT BUMPER REINFORCEMENT	1	\$ 847.00	? } h ✓
15	FRONT BUMPER REINFORCEMENT FOAM	1	\$ 211.00	? } h ✓
16	FRONT BUMPER REINFORCEMENT COVER	1	\$ 136.00	? } h ✓
17	HORN - LOW TONE	1	\$ 213.00	X ✓
18	BONNET	1	\$ 3,134.00	R ✓
19	BONNET ATTACHMENT PARTS	1	\$ 172.00	X h ✓
20	BONNET EDGE PROTECTION	1	\$ 31.00	X h ✓
SUB TOTAL SPARE PARTS			\$ 10,697.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKU 881 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	BONNET CATCH HOOK - UPPER	1	\$	100.00	X
22	BONNET STRIKER - RH	1	\$	123.00	X
23	BONNET CATCH HOOK - LOWER	1	\$	71.00	X
24	BONNET LOCK	1	\$	228.00	X
25	BONNET BOWDEN CABLE	1	\$	64.00	X
26	BONNET BOWDEN CABLE COVER	1	\$	11.00	X
27	FRONT WHEEL HOUSING LINER - RH	1	\$	183.00	X
28	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$	93.00	X
29	HEADLIGHT - LH / RH	2	\$	10,910.00	?
30	HEADLIGHT LIFT CYLINDER - LH / RH	2	\$	312.00	?
31	HEADLIGHT LIFT CYLINDER HOSE	1	\$	78.00	?
32	LOCK CARRIER	1	\$	806.00	?
33	COOLANT	6	\$	282.00	?
34	RADIATOR AIR GUIDE - LH / RH	2	\$	56.00	?
35	RADIATOR AIR GUIDE SEAL	1	\$	9.00	?
36	RADIATOR AIR GUIDE - UPPER CENTRE	1	\$	14.00	?
37	A/C CONDENSER	1	\$	569.00	X
38	TEMPRETURE BRACKET	1	\$	21.00	?
39	FRONT NO. PLATE	S/N	\$	60.00	old
40	SUNDRIES		\$	300.00	X
TOTAL SPARE PARTS			:	\$	24,987.00
TOTAL LABOUR CHARGES			:	\$	8,852.00
GRAND TOTAL			:	\$	33,839.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Taufik 92495749
11/3/22 @ 3pm
Ex: to be advise & 04 days
Not Authorise
Resurvey before paint -
taufik@lkhauto.com

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT