



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0148/2022/TF
DATE : 1-Mar-22
WIP : 13843

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1/3/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. LIM CHEE SIONG
ADDRESS : BLK 8C UPPER BOON KENG ROAD
#14-540
SINGAPORE 383008
TELEPHONE : HP +65 9681 5881
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700093804-04
VEHICLE NO : **SKU 881 H**
MODEL CODE : A3 SEDAN 1.0 TFSI
MODEL YEAR : 27/12/2017
ENGINE NO : CHZ 600608
CHASSIS NO : WAUZZZ8V5J1030864
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Feb-22
PLACE OF ACCIDENT : PIE BEFORE ADAM RD EXIT

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKU 881 H

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	700.00	? photo.
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACCUM AND REGAS.	S/N \$	1,400.00	? photo.
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,200.00	1000.
5	TO RESPRAY FRONT BUMPER AND BONNET.	\$	2,000.00	1100
6	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 8,852.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKU 881 H

DAMAGED PARTS & PRICES				
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,987.00	OK ✓
2	FRONT BUMPER FIXING PARTS	1	\$ 195.00	?
3	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 86.00	?
4	FRONT BUMPER LOWER GRILLE - CENTER	1	\$ 179.00	?
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 571.00	?
6	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 636.00	?
7	FRONT BUMPER COVER TRIM - LH / RH	2	\$ 364.00	?
8	FRONT BUMPER ADAPTER - LH / RH	2	\$ 84.00	?
9	RADIATOR GRILLE	1	\$ 1,406.00	OK ✓
10	RADIATOR GRILLE CLOSING ELEMENT	1	\$ 210.00	?
11	CAUTION STICKER	1	\$ 16.00	?
12	A/C STICKER	1	\$ 9.00	?
13	FRONT BUMPER AIR GRILLE - RH	1	\$ 210.00	?
14	FRONT BUMPER REINFORCEMENT	1	\$ 847.00	?
15	FRONT BUMPER REINFORCEMENT FOAM	1	\$ 211.00	?
16	FRONT BUMPER REINFORCEMENT COVER	1	\$ 136.00	?
17	HORN - LOW TONE'	1	\$ 213.00	X
18	BONNET	1	\$ 3,134.00	RX
19	BONNET ATTACHMENT PARTS	1	\$ 172.00	X
20	BONNET EDGE PROTECTION	1	\$ 31.00	X
SUB TOTAL SPARE PARTS		:	\$ 10,697.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKU 881 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET CATCH HOOK - UPPER	1	\$ 100.00	X
22	BONNET STRIKER - RH	1	\$ 123.00	X
23	BONNET CATCH HOOK - LOWER	1	\$ 71.00	X
24	BONNET LOCK	1	\$ 228.00	X
25	BONNET BOWDEN CABLE	1	\$ 64.00	X
26	BONNET BOWDEN CABLE COVER	1	\$ 11.00	X
27	FRONT WHEEL HOUSING LINER - RH	1	\$ 183.00	X
28	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 93.00	X
29	HEADLIGHT - LH / RH	2	\$ 10,910.00	?
30	HEADLIGHT LIFT CYLINDER - LH / RH	2	\$ 312.00	?
31	HEADLIGHT LIFT CYLINDER HOSE	1	\$ 78.00	?
32	LOCK CARRIER	1	\$ 806.00	?
33	COOLANT	6	\$ 282.00	?
34	RADIATOR AIR GUIDE - LH / RH	2	\$ 56.00	?
35	RADIATOR AIR GUIDE SEAL	1	\$ 9.00	?
36	RADIATOR AIR GUIDE - UPPER CENTRE	1	\$ 14.00	?
37	A/C CONDENSER	1	\$ 569.00	X
38	TEMPRETURE BRACKET	1	\$ 21.00	?
39	FRONT NO. PLATE	S/N	\$ 60.00	did ✓
40	SUNDRIES		\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 24,987.00	
TOTAL LABOUR CHARGES		:	\$ 8,852.00	
GRAND TOTAL		:	\$ 33,839.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Tanpin 92495749
1/3/22 @ 3pm
Ex: to be advise
Not Authorise 04 days
Resurvey before paint
tanpin@khando.com

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT