

PROVI AUTOWORKS PTE LTD.

Blk 8 , Kaki Bukit Avenue 4 , #02-24

Premier @ Kaki Bukit Singapore 415875

Email: claims@PROVIAUTO.com

Tel: 6286 6060 Fax : 6286 7060

Office Use Only

Parts -25%	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	

TO:
Vehicle No : SLC 2447 Z
Make & Model : TOYOTA VIOS
DATE: 2/3/2022

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE	
1	BOOTLID	1	\$ 1,662.40	\$ 1,662.40	+
2	BOOTLID LOGO	1	\$ 89.00	\$ 89.00	+
3	BOOTLID EMBLEM(VIOS)	1	\$ 92.40	\$ 92.40	+
4	BOOTLID EMBLEM(E)	1	\$ 65.00	\$ 65.00	+
5	BOOTLID INNER LOCK	1	\$ 319.50	\$ 319.50	+
6	BOOTLID WEATHERSTRIP	1	\$ 198.60	\$ 198.60	X
7	REAR BUMPER	1	\$ 489.00	\$ 489.00	✓
8	REAR BUMPER SIDE RETAINER LH and	2	\$ 89.50	\$ 179.00	35
9	REAR BUMPER ATTACHMENT RETAINER new	2	\$ 78.90	\$ 157.80	+
10	REAR BUMPER REINFORCEMENT ? new	1	\$ 363.70	\$ 363.70	+
11	REAR BUMPER REFLECTOR LH	1	\$ 145.00	\$ 145.00	+
12	REAR BUMPER BRACKET LH	1	\$ 135.00	\$ 135.00	+
13	TAILLAMP LH ?	1	\$ 355.60	\$ 355.60	?
14	TAILLAMP LOWER BARCKET LH ?	1	\$ 67.20	\$ 67.20	+
15	REAR END PANEL	1	\$ 766.50	\$ 766.50	+
16	REAR END PANEL TOP GARNISH	1	\$ 217.90	\$ 217.90	+
17	REAR FLOOR PANEL TOP BOARD	1	\$ 499.00	\$ 499.00	+
18	REAR FENDER LH Repair	1	\$ 927.50	\$ 927.50	X
19	REAR WINDSCREEN MOULDING	1	\$ 295.30	\$ 295.30	+
20	REAR FENDER INNER COWLING LH	1	\$ 194.60	\$ 194.60	+
21	REAR FENDER AIR VENT LH	1	\$ 56.00	\$ 56.00	+
22	REAR WHEEL BEALRING LH	1	\$ 766.00	\$ 766.00	+
23	REAR SHOCK ABSOBER LH	1	\$ 256.00	\$ 256.00	+
24	REAR RIM LH	1	\$ 763.80	\$ 763.80	+
25	ROCKER PANEL LH	1	\$ 787.30	\$ 787.30	+
26	REAR DOOR LH	1	\$ 984.90	\$ 984.90	+
27	REAR DOOR FRAME SIDE BLACK STICKER LH	2	\$ 45.00	\$ 90.00	+
28	REAR DOOR OUTER MOULDING LH	1	\$ 198.00	\$ 198.00	+
29	REAR DOOR OUTER HANDLE LH	1	\$ 217.00	\$ 217.00	+
30	REAR DOOR OUTER HANDLE SIDE COVER LH	1	\$ 67.60	\$ 67.60	+

31	REAR DOOR INNER LOCK LH	1	\$ 466.90	\$ 466.90	X
32	REAR DOOR LOCK CATCH LH	1	\$ 56.00	\$ 56.00	X
33	REAR DOOR WEATHERSTRIP LH	1	\$ 198.00	\$ 198.00	X

2
NIP
New

Subtotal : \$ 12,127.50
Less 25% \$ 3,031.88
Parts Total : \$ 9,095.63

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE	
1	REAR BUMPER CLIPS <i>New</i>	1	\$ 50.00	\$ 50.00	30
2	TAILLAMP CLIPS <i>New</i>	1	\$ 30.00	\$ 30.00	10
3	REAR FENDER COWLING CLIPS	1	\$ 30.00	\$ 30.00	X
4	REAR FENDER SEALANT	1	\$ 80.00	\$ 80.00	X
5	REAR WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00	X
6	REAR WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	X
7	REAR END PANEL TOP GARNISH CLIPS	1	\$ 30.00	\$ 30.00	X
8	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00	X
9	ROCKER PANEL SEALANT	1	\$ 80.00	\$ 80.00	X
10	REVERSE SENSOR	1	\$ 350.00	\$ 350.00	X
11	REAR TYRE	1	\$ 450.00	\$ 450.00	X
SPECIAL NETT				\$ 1,390.00	

2
NIP
New

LABOUR FRONT REAR	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00 400
TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00 400
TUFF COAT	\$ 250.00 40
WIRING CHECK	\$ 100.00 30
REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 300.00 ✓
REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00 50
TRANFER BOOTLID MECHANISM	\$ 120.00 +
CONDUCT WATER LEAKAGE TEST	\$ 100.00 +
REMOVE AND INSTALL REAR DOOR PART	\$ 180.00 +
REMOVE AND INSTALL REAR WINDSCREEN	\$ 250.00 +
REMOVE AND INSTALL RESR UNDER CARRAIGE	\$ 600.00 +
TO CHECK FOUR WHEEL ALIGMENT	\$ 80.00 ✓
<hr/>	
LABOUR TOTAL	\$ 5,700.00
<hr/>	
	Total Parts Cost \$ 10,485.63
	Total Labour Cost \$ 5,700.00
	Total Repair Cost \$ 16,185.63

APPROVED DETAILS
NO. OF WORKING DAYS
PART BY PART OR LUMP SUM
DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

Adrian Ly
 r/s 03/03/22.
 03 Days.