

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22001943/TQCE2

Date: 24/06/2022

REFERENCE

Insured/Claimant: MARUMO OSAMU Policy No: 2070119595
Date of Loss: 23/02/2022 Nature of Claim: OD Claim No: 5097565122SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU6397B**
Make & Model: AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A) Engine No: CZD896678
Reg. Date: 22/08/2020 (Man. Year: 2020) Chassis No: WAUZZZF30L1112134
Colour: Orange Odometer: 11508 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$154,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R17 Rear Tyre Size: 215/65 R17
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,989.00	5,851.20	3,137.80	34.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,792.00	3,892.00	3,900.00	50.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,781.00	9,743.20	7,037.80	41.94
- Excess (S\$)	650.00	650.00	0.00	0.00
(S\$)	16,131.00	9,093.20	7,037.80	43.63
+ GST 7.00/7.00% (S\$)	1,129.17	636.52	492.65	43.63
Nett Amount (S\$)	17,260.17	9,729.72	7,530.45	43.63

INSPECTION

Date of Assignment: 01/03/2022
Date Inspected: 01/03/2022 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - RH	Bent	3,017.00 FS	*2,413.60 FS
2	1		*FRONT DOOR OUTER SEAL - RH	Necessary	185.00 FS	*147.60 FS
3	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	164.00 FS	*- FS
4	1		*FRONT DOOR CATCH - RH	Not Necessary	105.00 FS	*- FS
5	1		*TYRE PRESSURE DATA PLATE	Not Necessary	34.00 FS	*- FS
6	1		*FRONT DOOR LOWER MOLDING COVER - RH	Cut	283.00 FS	*226.00 FS
7	1		*FRONT DOOR WINDOW REGULATOR - RH	Not Necessary	302.00 FS	*- FS
8	1		*REAR DOOR - RH	Bent	3,127.00 FS	*2,501.60 FS
9	1		*REAR DOOR OUTER SEAL - RH	Necessary	151.00 FS	*120.40 FS
10	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	324.00 FS	*- FS
11	1		*REAR DOOR CATCH - RH	Not Necessary	105.00 FS	*- FS
12	1		*REAR DOOR HINGE HALF - RH UPPER	Not Necessary	47.00 FS	*- FS
13	1		*REAR DOOR HINGE HALF - RH LOWER	Not Necessary	42.00 FS	*- FS
14	1		*REAR DOOR SILL PANEL SEAL - RH	Not Necessary	151.00 FS	*- FS
15	1		*REAR DOOR LOWER MOLDING COVER - RH	Cut	270.00 FS	*216.00 FS
16	1		*REAR WHEEL ARCH COVER - RH	Cut	283.00 FS	*226.00 FS
17	1		*REAR DOOR SILL TRIM STRIP - RH	Not Necessary	99.00 FS	*- FS
18	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **8,989.00** **5,851.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRABSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	800.00	800.00
2	TO DISMANTLE AND RENEW RHS FRONT DOOR AND RHS REAR DOOR. TO REPAIR RHS B-PILLAR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,250.00
3	TO RESPRAY RHS FRONT DOOR, RHS REAR DOOR, HINGES, RHS B-PILLAR AND DOOR ENTRANCES	New	4,000.00	1,650.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (\$\$)	7,792.00
				3,892.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >