

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATEDATE: 28-Feb-22INSURANCE: CHINA TAIPING CP/PMODEL: Hyundai IoniqSURVEYOR: LKKVEHICLE NO.: SHD6550ZMVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$459.40
	Rear Bumper Reinforcement	1		\$394.80
	Rear Bumper Reinforcement Bracket LH/RH	2	\$138.10	\$276.20
	Rear Bumper Side Brackets LH/RH	2	\$55.80	\$111.60
	Rear Bumper Centre Moulding	1		\$451.25
	Rear Bumper Lower Centre Moulding	1		\$155.00
	Rear Bumper Under Cover	1		\$225.00
	Rear Bumper Cover Clips	10	\$2.20	\$22.00
	Rear Bumper Tow Cover	1		\$98.80
	BootLid Emblem – Hybrid	1		\$24.30
	BootLid Emblem – Ioniq	1		\$31.30
	BootLid	1		\$2,480.40
	SUB TOTAL			\$4,730.05
	LESS 20%			\$946.01
	DISCOUNTED TOTAL			\$3,784.04
	BootLid ComfortDelGro	1		\$30.00
	BootLid 65521111	1		\$30.00
	BootLid APPS	1		\$40.00
	Reverse Sensors	1		\$180.00
	Rear No.Plate With Trim Cover	1		\$55.00
	Rear Windscreen Sealant	2	\$46.00	\$92.00
	S/NETT TOTAL			\$427.00
	SPARE PARTS TOTAL			\$4,211.04
	Labour Charge			
	Panel Beating			\$800.00
	Spray Painting Charge			\$600.00
	Remove/Refix Reverse Sensor			\$120.00
	Remove/Refix Rear Windscreen Glasses			\$250.00
	TOTAL LABOUR			\$1,770.00
	ESTIMATE TOTAL			\$5,981.04

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 92495419
wp' 28/2/22 430
pp fixing before paint
Deleg
fayric@thank.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date/Time: 28.02.2022 07:13

Page : 1

JOB CARD Sales Order: 4178928

JC NO 305506673

am: ARC Repair TP(CLSO)1

OMER

S COMFORT TRANSPORTATION PTE LTD
OMER NO 7010045
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

OUNT CARD NO.


REGN NO.: SHD6550Z	MILEAGE
MAKE: HYUNDAI	FUEL E 1/2 F
MODEL IONIQ(G3)	DATE/TIME IN 25.02.2022 14:25
YR OF MANU. 19.12.2019	TARGET DATE
CHASSIS CODE KMHC851CVLU187636	COMPLETION DATE/TIME

JOB DESCRIPTION

Incident Date: 25.02.2022
TURE: 3P.25.02.2022

NO LABOR CODE
00010 PB

DESCRIPTION
PANEL BEATING-SHD6550Z



KED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

to: SHD6550Z LTMTS

Vehicle No.: SHD6550Z

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard