

TP M/G.
Ashes.

SMM3530U. 2019 June.

Honda Vezel 1496CC

RU11318748

Front Bumper	Deformed	745.60	/
Front Bumper Clips	new	30(SN)	/
Front Bumper Side Holder RH	Damaged	26.50	/
Front Bumper Reinforcement	2x4	321	X
Front Bumper Fog Lamp RH.	new	327.20	X
Front Bumper Fog Lamp Cover RH.		85.10	X
Front Bumper Lower Garnish.	deformed	386.20	/
Headlamp RH	Cracked	1784.50	/
Headlamp Lower Bracket RH.	cracked	39	/
Front RH Fender	Dented	582	/
Front RH Fender Inner Shield	deformed	132.40	/
Front RH Fender Inner Shield Clips	new	30(SN)	/
Front RH Fender Wheel Arc Garnish	Deformed	185.40	/
Front RH Fender Wheel Arc Garnish Clips	new	20(SN)	/

SMM 35304.

Front RH wheel Rim.	ut	850(SN) 400(SN)
Front RH Tyre	Hot new	300(SN) X
Front RH Lower Arm	Best	399.20 ✓
Front RH Shock Absorber	Best	398.40 ✓
Front RH Knuckle Arm	Damaged	482.30 ✓
Front RH Wheel Hub c/w Bearing.	2nd	193.50 ✓
Steering Rack and Pinion.	X4	1750.60 X
	SN 480	
	5355200	
	4284816	
Panel Beating		600 500
Spray Painting		600 400
Wiring.	1240	50 30
To spray tuff coat.		150 30
To dismantle front undercarriage		380 200
To perform wheel alignment.		150 80
		total: 6004
		L/S: A. BK.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

acknowledged by Repairer
Signature:

4,800
5 days