

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22001949/KEA3Q2**Date:** 01/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220009351
Claimant Vehicle No :	SMP2232X	Insured Vehicle No :	GBE6246T
Date of Loss:	28/02/2022	Nature of Claim:	TP
		Claim No:	9282873607SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP2232X		
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Engine No:	2ZR0E03446
Reg. Date:	16/09/2019 (Man. Year: 2019)	Chassis No:	ZWR800396700
Colour:	Metallic Pearl White	Odometer:	187332 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Falken 8 mm	Rear Left Side:	Falken 8 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Falken 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,446.15	4,596.29	2,849.86	38.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,720.00	1,470.00	1,250.00	45.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,166.15	6,066.29	4,099.86	40.33
Approved Total (Overridden) (\$\$)		4,850.00		
(\$\$)	10,166.15	4,850.00	5,316.15	52.29
+ GST 7.00/7.00% (\$\$)	711.63	339.50	372.13	52.29
Nett Amount (\$\$)	10,877.78	5,189.50	5,688.28	52.29
+ Loss of Use (5.0 x S\$85.00/day) (\$\$)		425.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		5,621.95		
Global Sum Settlement (\$\$)		5,620.00		

INSPECTION

Date of Assignment:	01/03/2022	
Date Inspected:	01/03/2022	Inspected At: Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** ADRIAN LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,712.85 FL	*1,645.00 FL
2	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	132.25 FL	*132.25 FL
3	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	172.80 FL	*172.80 FL
4	1		*REAR TAILGATE OUTER CHROME	Mtg Cracked	581.90 FL	*581.90 FL
5	1		*REAR TAILGATE TOYOTA LOGO	Necessary	121.10 FL	*121.10 FL
6	1		*REAR TAILGATE INNER LOCK	Repair	581.90 FL	*- FL
7	1		*REAR TAILGATE INNER RUBBER	Serviceable	371.85 FL	*- FL
8	1		*REAR TAILGATE INNER GARNISH	Mtg Cracked	371.75 FL	*371.75 FL
9	1		*REAR LH TAILLAMP	Cracked	781.55 FL	*781.55 FL
10	1		*REAR LH TAILLAMP LOWER GARNISH	Buckled	371.85 FL	*371.85 FL
11	1		*REAR LH TAILLAMP LOWER GARNISH SIDE RETAINER	Distorted	172.25 FL	*172.25 FL
12	1		*REAR LH TAILLAMP INNER PANEL	Repair	381.50 FL	*- FL
13	1		*REAR BUMPER	Buckled / Cracked	1,217.45 FL	*1,021.00 FL
14	1		*REAR BUMPER LH SIDE RETAINER	Distorted	172.10 FL	*172.10 FL
15	1		*REAR BUMPER LH SIDE REFECTOR	Serviceable	181.90 FL	*- FL
16	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
17	1		*REAR END PANEL LH CORNER PANEL	Repair	481.50 FL	*- FL
18	1		*REAR END PANEL INNER GARNISH	Serviceable	378.85 FL	*- FL
19	1		*REAR FENDER LH INNER GARNISH	Serviceable	731.35 FL	*- FL
20	1		*REAR FENDER LH TOP GARNISH	Mtg Cracked	481.50 FL	*481.50 FL
21	1		*SET REAR PARKING SENSOR	Serviceable	280.00 FS	*- FS
22	1		*SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,808.20	6,115.05
- List Item Discount on L Items 25.00/25.00% (S\$)	2,362.05	1,518.76
Total Parts (S\$)	7,446.15	4,596.29

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
2	WIRING	New	100.00	20.00
3	TUFFKOTE	New	100.00	30.00
4	SPRAY PAINTING	New	1,200.00	800.00
5	LABOUR CHARGES	New	1,200.00	500.00
Gross Labour Cost (\$)			2,720.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >