

A.S.S. REC. BY: Rail

REF:

NS/INC22001951/Rtc

369K

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHF 302Cat Workshop m/s STRIDESof 60, WOODLANDS LDPK E4Insured: NTUC

Policy No. _____


Claims No. MT/1163437-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHF 302C Yr Regn: 2020 / DEC

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS SDR A.B.A c.c. 1798Colour: MAROON A/C: Insured / Std / NI / NASp. Reading: 118 775 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU603091854Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / SRM / STD A/RM orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 27/02/22 D.O.I. 01/03/22Survey held at STRIDES

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

REAR UIC

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	cost of repair of L/S \$1,750.00 /- with 04 days of repair
	red: 21751.50;92%

Date/Time, File Pass to?

☐ : Preli. Report1) _____
Date/Time, File Return to?☐ : Final Report

2) _____

Days Of Repair: 4

Resurvey No. of Trip: _____

Report Format: _____

Lump Sum / L.S.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL



Case Details

Case Reference Number :
TAX/02/22/2073
Type of Repair : Accident Repair
Vehicle Registration Number : SHF302C

Company Type : Strides Taxi Pte Ltd
Estimation ID : EST-17606-ID
Assigned By : Taxi Claims Manager
Team

Insurance Company Name : NTUC Income Insurance Co-operative
Ltd
Accident Date and Time : 27/02/2022 05:20 AM
Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			COVER, RR BUMPER ASSY	1	332.70	332.70	25.00	249.52	Replace	0	0	Not Give	Xan
Standard	Main			COVER, RR BUMPER ASSY	1	485.60	485.60	25.00	364.20	Replace	1	364.20	Replace	de
Standard	Main			PAD, RR BUMPER, RH & LH, 3	2	11.00	22.00	25.00	16.50	Replace	2	16.50	Replace	ne
Standard	Main			PAD, RR BUMPER, RH & LH, 2	2	4.00	8.00	25.00	6.00	Replace	2	6.00	Replace	ne
Standard	Main			PAD, RR BUMPER, RH & LH, 1	2	4.00	8.00	25.00	6.00	Replace	2	6.00	Replace	ne
Standard	Main			PAD, RR BUMPER, CTR	3	11.00	33.00	25.00	24.75	Replace	3	24.75	Replace	ne
Standard	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.30	22.60	25.00	16.95	Replace	2	16.95	Replace	ne
Standard	Main			STOPPER, RR BUMPER, RH & LH	1	4.50	4.50	25.00	3.38	Replace	0	0	Not Give	Xan
Standard	Main			RETAINER, RR BUMPER, RH	1	132.60	132.60	25.00	99.45	Replace	0	0	Not Give	Xan
Standard	Main			RETAINER, RR BUMPER, LH	1	132.60	132.60	25.00	99.45	Replace	0	0	Not Give	Xan
Standard	Main			SEAL, RR BUMPER, RH	1	118.30	118.30	25.00	88.73	Replace	0	0	Not Give	Xan
Standard	Main			SEAL, RR BUMPER, LH	1	118.30	118.30	25.00	88.73	Replace	0	0	Not Give	Xan
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.50	45.00	25.00	33.75	Replace	10	33.75	Replace	ne

Total Spare Part Cost 14,576.73

Surveyor Total 912.75

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 14,576.73

Final Sur Total 912.75

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			GUARD, RR BUMPER, LOWER	1	374.50	374.50	25.00	280.88	Replace	1	280.88	Replace	de ✓
Standard	Main			COVER, GUARD RR BUMPER LOWER	1	22.00	22.00	25.00	16.50	Replace	1	16.50	Replace	MS ✓
Standard	Main			REAR BUMPER REFLECTOR ASSY, REFLEX, RH	1	39.00	39.00	25.00	29.25	Replace	0	0	Check	?
Standard	Main			REAR BUMPER REFLECTOR ASSY, REFLEX, LH	1	39.00	39.00	25.00	29.25	Replace	0	0	Not Give	X11
Standard	Main			REAR BUMPER GROMMET SCREW	2	2.20	4.40	25.00	3.30	Replace	0	0	Not Give	X11
Standard	Main			COVER, REAR FLOOR UNDER, RH	1	175.10	175.10	25.00	131.33	Replace	0	0	Check	?
Standard	Main			COVER, REAR FLOOR UNDER, LH	1	241.90	241.90	25.00	181.43	Replace	0	0	Not Give	X11
Standard	Main			COVER, REAR FLOOR UNDER CENTER	1	229.90	229.90	25.00	172.43	Replace	0	0	Not Give	X11
Standard	Main			LENS & BODY, REAR COMBINATION LAMP, RH	1	339.60	339.60	10.00	305.64	Replace	0	0	Not Give	X11
Standard	Main			LENS & BODY, REAR COMBINATION LAMP, LH	1	339.60	339.60	10.00	305.64	Replace	0	0	Not Give	X11
Standard	Main			COVER, REAR COMBINATION LAMP, RH	1	69.90	69.90	25.00	52.43	Replace	0	0	Not Give	X11
Standard	Main			COVER, REAR COMBINATION LAMP, LH	1	69.90	69.90	25.00	52.43	Replace	0	0	Not Give	X11
Standard	Main			SOCKET & WIRE SUB-ASSY, REAR COMBINATION LAMP, RH	1	52.30	52.30	10.00	47.07	Replace	0	0	Not Give	X11
Standard	Main			LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	1	261.00	261.00	10.00	234.90	Replace	0	0	Not Give	X11
Standard	Main			LENS & BODY, REAR COMBINATION LAMP, NO.2 LH	1	261.00	261.00	10.00	234.90	Replace	0	0	Not Give	X11
Standard	Main			LAMP ASSY, REAR, RH	1	293.60	293.60	10.00	264.24	Replace	0	0	Not Give	X11
Standard	Main			LAMP ASSY, REAR, LH	1	293.60	293.60	10.00	264.24	Replace	0	0	Not Give	X11
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check	?

Total Spare Part Cost 14,576.73

Surveyor Total 912.75

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			ANTENNA, ELECTRICAL KEY	1	72.00	72.00	10.00	64.80	Replace	0	0	Not Give	Xm
Standard	Main			PANEL SUB-ASSY, FENDER REAR RH	1	871.50	871.50	25.00	653.63	Replace	0	0	Not Give	Xm
Standard	Main			LINER, REAR FENDER, RH	1	139.80	139.80	25.00	104.85	Replace	0	0	Not Give	Xm
Standard	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	651.00	651.00	25.00	488.25	Replace	0	0	Not Give	Xm
Standard	Main			SPARE TYRE PANEL, PAN, REAR FLOOR	1	583.40	583.40	25.00	437.55	Replace	0	0	Not Give	Xm
Standard	Main			EXTENSION, REAR FLOOR SIDE PANEL, RH	1	78.30	78.30	25.00	58.72	Replace	0	0	Not Give	Xm
Standard	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	1,147.80	1,147.80	25.00	860.85	Replace	0	0	Not Give	Xm
Standard	Main			TAIL GATE WEATHERSTRIP, BACK DOOR	1	372.30	372.30	25.00	279.23	Replace	0	0	Not Give	Xm
Standard	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.1	1	27.30	27.30	25.00	20.48	Replace	0	0	Not Give	Xm
Standard	Main			TAIL GATE GLASS SUB-ASSY, BACK DOOR	1	1,656.70	1,656.70	25.00	1,242.53	Replace	0	0	Not Give	Xm
Standard	Main			TAIL GATE MOULDING GLASS, BACK DOOR	1	35.50	35.50	25.00	26.63	Replace	0	0	Not Give	Xm
Standard	Main			TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	1	761.40	761.40	25.00	571.05	Replace	0	0	Not Give	Xm
Standard	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	913.60	913.60	25.00	685.20	Replace	1	0	Repair	R
Standard	Main			TAILGATE TRIM, UPPER	1	52.10	52.10	25.00	39.08	Replace	0	0	Not Give	Xm
Standard	Main			TAILGATE TRIM, RH	1	95.60	95.60	25.00	71.70	Replace	0	0	Not Give	Xm
Standard	Main			TAILGATE TRIM, LH	1	95.60	95.60	25.00	71.70	Replace	0	0	Not Give	Xm
Standard	Main			TAILGATE TRIM, LOWER	1	225.20	225.20	100.00	0.00	Repair	0	0	Not Give	Xm
Standard	Main			TAILGATE BOARD ASSY	1	259.20	259.20	25.00	194.40	Replace	0	0	Not Give	Xm

Total Spare Part Cost 14,576.73

Surveyor Total 912.75

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 14,576.73

Final Sur Total 912.75

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			TAIL GATE BACK DOOR HINGE ASSY, LH	1	61.00	61.00	25.00	45.75	Replace	0	0	Not Give	X11
Standard	Main			TAIL GATE BACK DOOR HINGE ASSY, LH	1	61.00	61.00	25.00	45.75	Replace	0	0	Not Give	X11
Standard	Main			TAIL GATE LOCK ASSY, BACK DOOR	1	467.00	467.00	10.00	420.30	Replace	0	0	Not Give	X11
Standard	Main			TAIL GATE LOCK COVER, BACK DOOR	1	30.20	30.20	25.00	22.65	Replace	0	0	Not Give	X11
Standard	Main			AUTO TAILGATE SYSTEM	1	2,520.00	2,520.00	10.00	2,268.00	Replace	0	0	Not Give	X11
Standard	Main			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	54.60	54.60	25.00	40.95	Replace	1	40.95	Replace	rec /
Standard	Main			EMBLEM SUB-ASSY REAR	1	47.90	47.90	25.00	35.93	Replace	1	35.92	Replace	rec /
Standard	Main			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	54.60	54.60	25.00	40.95	Replace	1	40.95	Replace	rec /
Standard	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	913.60	913.60	25.00	685.20	Replace	0	0	Not Give	X11
Standard	Main			COVER, TAIL GATE BACK DOOR GARNISH	1	8.50	8.50	25.00	6.38	Replace	0	0	Not Give	X11
Standard	Main			SPOILER SUB-ASSY, REAR	1	1,575.40	1,575.40	25.00	1,181.55	Replace	0	0	Not Give	X11
Standard	Main			STICKER STRIDES TAXI WITH (GO GREEN LOGO) / (TAIL GATE)	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	rec /
Standard	Main			STICKER DECAL 6558888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	rec /
Total Spare Part Cost									14,576.73	Surveyor Total 912.75				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									14,576.73	Final Sur Total 912.75				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	1,014.00	300	
Total:			1,014.00	300.00	

Spray Cost Detail



No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR FENDER RH	378.00	0 X17	
2	Main	TO RESPRAY TAIL LAMP PANEL RH	180.00	0 X17	
3	Main	TO RESPRAY TAIL GATE	378.00	0 X17	
4	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100	
5	Main	TO RESPRAY REAR SPOILER	180.00	0 X17	
6	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0 X17	
7	Main	TO RESPRAY REAR BUMPER	378.00	200	
8	Main	TO RESPRAY REAR PANEL	180.00	0 X17	
Total:			2,034.00	300.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	0 X17	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0 X17	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0 X17	
4	Main	TO WASH AND VACUUM	60.00	0 X17	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0 X17	
6	Main	TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0 X17	
7	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0 X17	
8	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40	
Total:			796.00	40.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	14,576.73	912.75
Total Labour Cost	0.00	300.00

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spray Painting	0.00	300.00
Other	0.00	40.00
Overall Total	14,576.73	1,552.75
Lump Sum Repair Option	<input type="checkbox"/>	<input type="checkbox"/>
Lump Sum Total	0.00	1,552.75
Surveyor Approved Amount		1,552.75
No of Repair Days*	8	3
Remarks	-	PART BY PART REPAIR / RESURVEY BEFORE PAINT PHOTO .
Surveyor Name		Rasul
Signature		
Survey Date	01/03/2022	<input type="button" value="Save"/> <input type="button" value="Clear"/>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 28/02/2022 15:09 (SGT)
Date of Accident 27/02/2022 13:20 (SGT)
Exact Location of Accident SLE, Singapore
Additional Location Information SLE TOWARDS YISHUN
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHF302C

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner Strides Taxi Pte Ltd
Company Reg No 1XXXXX369K
Email Address AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No (Phone) +65-68662671
Alternative Phone No (Office) +65-68662672

VEHICLE PARTICULARS

Manufacturer Toyota
Model Prius
Variant -
Exact purpose for which vehicle was being used at time of accident -
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Taxi
Transmission Auto
CC 1800

INSURANCE COMPANY

Name of Insurance Company MS First Capital Insurance Ltd
Type of Coverage ThirdParty
Fleet Policy Yes
Policy Number D-21097466MFSH
Cover Note Number -

DRIVER

Name of Driver STARLING JAYA RAJ S/O M J RICHARD
NRIC No SXXXX760D

Date Of Birth	23/10/1956
Occupation	Outdoor
Date Of Driving Pass	23/11/1977
Driving experience	44 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-68662672
Alt. Phone Number	-
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Address	11
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	4
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	UNKNOWN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS TRAVELLING ALONG SLE TOWARDS YISHUN WITH ONE PASSENGER (MALE INDIAN) ON BOARD. THERE WAS A BREAKDOWN VEHICLE INFRONT OF MY TAXI, AS SUCH I APPLIED MY BRAKE TO STOPP. SUDDENLY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SKR4087Z HAD COLLIDED ONTO THE REAR OF MY TAXI. I SWERVED TO THE LEFT TO AVOID HITTING THE BREAKDOWN VEHICLE. AFTER I ALIGHTED THERE WERE 2 OTHER CARS BEHIND THE VEHICLE THAT HIT MY TAXI. I AM NOT SURE IF IT WAS A CHAIN COLLISION. IT WAS RAINING HEAVILY AT THAT POINT IN TIME.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKR4087Z
Vehicle Manufacturer	-
Vehicle Model	-

Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	-
Name of Driver	Private car
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLH4471M
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-


DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SMV9518U
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

IMPORTANT NOTICE

- ## 8. Consent under the Personal Data Protection Act (PDPA)

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Describe the Accident

We declare the foregoing particulars are true in every respect.

28-2-22

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	369K
Vehicle No:	SHF302C
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Mar 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Maroon
Manufacturing Year:	2020
Engine No:	2ZR2G90394
Chassis No:	JTDKB3FU603091854
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,807.00
Original Registration Date:	01 Dec 2020
First Registration Date:	01 Dec 2020
Transfer Count:	0
Actual ARF Paid:	\$14,530.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Nov 2028
PARF Rebate Amount:	\$10,897.00
COE Expiry Date:	30 Nov 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$29,843.00
COE Rebate Amount:	\$25,159.00
Total Rebate Amount:	\$36,056.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Mar 2022

OK