

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 16/03/2022

User ID PohSuan

Section A - Accident Details

Registration Number	SHF302C
Case Reference Number	TAX/02/22/2073
Registration Date	1/12/2020
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	STARLING JAYA RAJ S/O M J RICHARD
Type of Accident	Head to Rear
Accident Date and Time	27/2/2022 1:20 PM
Accident Reported Date and Time	28/2/2022 10:16 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24114141
Special Instruction to ARC, if any	TP/ REAR PORTION /TOWED \$40/NTUC
Prepared Date and Time	1/3/2022 8:37 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,314.00	\$400.00
Total Spray Cost	\$2,214.00	\$400.00
Total Spare Part Cost	\$15,006.25	\$1,342.29
Total Other Cost	\$796.00	\$40.00
TOTAL COST	\$19,330.25	\$2,182.29 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	8.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	04/03/2022 9:10 AM	04/03/2022 10:05 AM
Signature		
Remarks	Total number of repair days = 4 days. SUP = + 1 day.	PART BY PART REPAIR / RESURVEY BEFORE PAINT PHOTO .

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2203-0231	Invoice Number	
Quotation Date	16.03.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$1,014.00	\$300.00
TO REPAIR REAR END PANEL	\$300.00	\$100.00
Total Labour	\$1,314.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
TO RESPRAY TAIL LAMP PANEL RH	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$2,214.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$120.00	\$0.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$40.00
Total Other Costs	\$796.00	\$40.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52023-47030	COVER, RR BUMPER ASSY	0.00	\$332.70	0.00	\$0.00	Replace	Not Given
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$485.60	25.00	\$364.20	Replace	Replace
		52462-47130	PAD, RR BUMPER, RH & LH , 3	2.00	\$11.00	25.00	\$16.50	Replace	Replace
		52462-47030	PAD, RR BUMPER, RH & LH , 2	2.00	\$4.00	25.00	\$6.00	Replace	Replace
		52462-47020	PAD, RR BUMPER, RH & LH , 1	2.00	\$4.00	25.00	\$6.00	Replace	Replace
		52461-47070	PAD, RR BUMPER, CTR	3.00	\$11.00	25.00	\$24.75	Replace	Replace

X
✓
✓
✓
✓
✓
✓

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 16/03/2022
User ID PohSuan

		52191-47030	SEAL, RR BUMPER ARM, RH & LH	2.00	\$11.30	25.00	\$16.95	Replace	Replace	✓
		52599-68030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.50	0.00	\$0.00	Replace	Not Given	X
		52575-47060	RETAINER, RR BUMPER, RH	0.00	\$132.60	0.00	\$0.00	Replace	Not Given	X
		52576-47060	RETAINER, RR BUMPER, LH	0.00	\$132.60	0.00	\$0.00	Replace	Not Given	X
		52591-47080	SEAL, RR BUMPER , RH	0.00	\$118.30	0.00	\$0.00	Replace	Not Given	X
		52592-47080	SEAL, RR BUMPER , LH	0.00	\$118.30	0.00	\$0.00	Replace	Not Given	X
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.50	25.00	\$33.75	Replace	Replace	✓
		52453-47900	GUARD, RR BUMPER, LOWER	1.00	\$374.50	25.00	\$280.88	Replace	Replace	✓
		52169-47070	COVER, GUARD RR BUMPER LOWER	1.00	\$22.00	25.00	\$16.50	Replace	Replace	✓
		81910-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, RH	0.00	\$39.00	0.00	\$0.00	Replace	Check	X
		81920-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, LH	0.00	\$39.00	0.00	\$0.00	Replace	Not Given	X
		9018906029	REAR BUMPER GROMMET SCREW	0.00	\$2.20	0.00	\$0.00	Replace	Not Given	X
		58398-47050	COVER, REAR FLOOR UNDER , RH	0.00	\$175.10	0.00	\$0.00	Replace	Check	X
		58399-47030	COVER, REAR FLOOR UNDER , LH	0.00	\$241.90	0.00	\$0.00	Replace	Not Given	X
		66259-47010	COVER, REAR FLOOR UNDER CENTER	0.00	\$229.90	0.00	\$0.00	Replace	Not Given	X
		81551-47481	LENS & BODY, REAR COMBINATION LAMP , RH	0.00	\$339.60	0.00	\$0.00	Replace	Not Given	X
		81561-47471	LENS & BODY, REAR COMBINATION LAMP , LH	0.00	\$339.60	0.00	\$0.00	Replace	Not Given	X
		81497-47040	COVER, REAR COMBINATION LAMP, RH	0.00	\$69.90	0.00	\$0.00	Replace	Not Given	X
		81498-47040	COVER, REAR COMBINATION LAMP, LH	0.00	\$69.90	0.00	\$0.00	Replace	Not Given	X
		81555-47480	SOCKET & WIRE SUB-ASSY, REAR COMBINATION LAMP,	0.00	\$52.30	0.00	\$0.00	Replace	Not Given	X
		81457-47020	LENS & BODY, REAR COMBINATION LAMP, NO.2	0.00	\$261.00	0.00	\$0.00	Replace	Not Given	X
		81456-47020	LENS & BODY, REAR COMBINATION LAMP, NO.2	0.00	\$261.00	0.00	\$0.00	Replace	Not Given	X
		81580-47070	LAMP ASSY, REAR, RH	0.00	\$293.60	0.00	\$0.00	Replace	Not Given	X
		81590-47070	LAMP ASSY, REAR, LH	0.00	\$293.60	0.00	\$0.00	Replace	Not Given	X
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check	X
		89997-30100	ANTENNA, ELECTRICAL KEY	0.00	\$72.00	0.00	\$0.00	Replace	Not Given	X
		61601-47150	PANEL SUB-ASSY, FENDER REAR RH	0.00	\$871.50	0.00	\$0.00	Replace	Not Given	X
		65637-47060	LINER, REAR FENDER , RH	0.00	\$139.80	0.00	\$0.00	Replace	Not Given	X
		58307-47100	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$651.00	0.00	\$0.00	Replace	Not Given	X
		58311-47130	SPARE TYRE PANEL , PAN, REAR FLOOR	0.00	\$583.40	0.00	\$0.00	Replace	Not Given	X
		58315-47021	EXTENSION, REAR FLOOR SIDE PANEL , RH	0.00	\$78.30	0.00	\$0.00	Replace	Not Given	X
		67005-47530	TAIL GATE PANEL SUB-ASSY, BACK DOOR	0.00	\$1,147.80	0.00	\$0.00	Replace	Not Given	X
		67881-47051	TAIL GATE WEATHERSTRIP, BACK DOOR	0.00	\$372.30	0.00	\$0.00	Replace	Not Given	X
		56117-50140	DAM, BACK DOOR GLASS ADHESIVE, NO.1	0.00	\$27.30	0.00	\$0.00	Replace	Not Given	X
		68105-47292	TAIL GATE GLASS SUB-ASSY, BACK DOOR	0.00	\$1,656.70	0.00	\$0.00	Replace	Not Given	X
		75571-47011	TAIL GATE MOULDING GLASS, BACK DOOR	0.00	\$35.50	0.00	\$0.00	Replace	Not Given	X
		64801-47031	TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	0.00	\$761.40	0.00	\$0.00	Replace	Not Given	X
		76801-47170-A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$913.60	100.00	\$0.00	Replace	Repair	R
		64790-47060-C0	TAILGATE TRIM , UPPER	0.00	\$52.10	0.00	\$0.00	Replace	Not Given	X
		67937-47060-C0	TAILGATE TRIM , RH	0.00	\$95.60	0.00	\$0.00	Replace	Not Given	X
		67938-47060-C0	TAILGATE TRIM , LH	0.00	\$95.60	0.00	\$0.00	Replace	Not Given	X
		67751-47111-C0	TAILGATE TRIM , LOWER	0.00	\$225.20	0.00	\$0.00	Repair	Not Given	X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 16/03/2022

User ID PohSuan

		67750-47080-C0	TAILGATE BOARD ASSY	0.00	\$259.20	0.00	\$0.00	Replace	Not Given	X
		68810-47061	TAIL GATE BACK DOOR HINGE ASSY, LH	0.00	\$61.00	0.00	\$0.00	Replace	Not Given	X
		68810-47061	TAIL GATE BACK DOOR HINGE ASSY, LH	0.00	\$61.00	0.00	\$0.00	Replace	Not Given	X
		69350-47050	TAIL GATE LOCK ASSY, BACK DOOR	0.00	\$467.00	0.00	\$0.00	Replace	Not Given	X
		69321-47010	TAIL GATE LOCK COVER, BACK DOOR	0.00	\$30.20	0.00	\$0.00	Replace	Not Given	X
		TMKONG-TAILG	AUTO TAILGATE SYSTEM	0.00	\$2,520.00	0.00	\$0.00	Replace	Not Given	X
		75442-47200	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT	1.00	\$54.60	25.00	\$40.95	Replace	Replace	√
		75403-48010	EMBLEM SUB-ASSY REAR	1.00	\$47.90	25.00	\$35.93	Replace	Replace	√
		75441-47220	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT	1.00	\$54.60	25.00	\$40.95	Replace	Replace	√
		76801-47170-A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	0.00	\$913.60	0.00	\$0.00	Replace	Not Given	X
		76839-47030	COVER, TAIL GATE BACK DOOR GARNISH	0.00	\$8.50	0.00	\$0.00	Replace	Not Given	X
		76085-47916	SPOILER SUB-ASSY, REAR	0.00	\$1,575.40	0.00	\$0.00	Replace	Not Given	X
			STICKER STRIDES TAXI WITH (GO GREEN LOGO) / (	1.00	\$7.80	0.00	\$7.80	Replace	Replace	√
			STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	√
Total					\$18,516.00		\$912.76			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
		52023-47030	REAR BUMPER REINFORCEMENT	1.00	\$332.70	25.00	\$249.53	Replace	Replace
Total					512.70		429.53		

1,342.29
 + 400.00
 + 440.00

 2,182.29

√ cut
 √ bt