

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF503P*Not Authorized
McPerry B4 paint***AAD2202-**

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

28 FEB 2022**SHF503P**

JTDKB3FU803093346

200303878K

TOYOTA

PRIUS GEN 4

27/02/2022

GBD7074X/CHINA

15/01/2021

PART

- 1 COVER, FRONT BUMPER
- 1 BRACKET, FRONT BUMPER EXTENSION MOUNTING
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 SUPPORT, FRONT BUMPER SIDE, RH
- 1 EXTENSION, FRONT BUMPER, RH
- 1 COVER, FRONT BUMPER HOLE, RH
- 1 MOULDING, FRONT BUMPER SIDE, RH
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 EMBLEM ASSY, RADIATOR GRILLE
- 1 RIM
- 1 FENDER SUB-ASSY, FRONT RH
- 1 LINER, FRONT FENDER, RH

LIST

\$	<i>Bm</i>	521.00	✓
\$	<i>Sm</i>	110.50	X
\$	<i>R</i>	716.60	X
\$	<i>Sm</i>	80.20	X
\$	<i>Sm</i>	80.10	X
\$	<i>Sm</i>	120.10	X
\$	<i>Sm</i>	30.20	X
\$	<i>Sm</i>	95.60	X
\$	<i>Sm</i>	422.50	X
\$	<i>Sm</i>	178.60	X
\$	<i>Sm</i>	105.80	X
\$	<i>Sm</i>	1,900.10	1
\$	<i>Ry</i>	977.80	✓
\$	<i>Sm</i>	202.50	X
TOTAL \$		4,361.30	
25% \$		1,090.33	
\$		3,270.98	

Special Nett

1SET BUMPER CLIP FRT

1 TYRE

1 HUB CAB

1 FENDER LINER CLIP

1SET FRNT BUMPER RETAINER CLIP

\$	<i>Mr</i>	95.00	<i>Colan</i>
\$	<i>Sm</i>	350.00	X
\$	<i>Sm</i>	211.50	X
\$	<i>na</i>	65.00	X
\$	<i>na</i>	85.00	X
TOTAL \$		806.50	

TOTAL PARTS \$ 4,077.48

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF503P**AAD2202-****LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00 400l
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	nn 480.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00 30l
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00 500l
To Check Electrical Lighting Concerned.	\$	170.00 20l
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 220.00 X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	nn 380.00 X
TOTAL	\$	7,260.00

Over All Total \$ 11,337.48**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repaire

Signature:

Date:

(PART-BY-PART) Repair Days**25 DAYS****2 days**

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF503P**AAD2202-**

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SUPPLEMENTARY**SHF503P**

JTDKB3FU803093346

200303878K

TOYOTA

PRIUS **GEN 4**

27/02/2022

GBD7074X/CHINA

15/01/2021

PART

- 1 MIRROR ASSY, OUTER REAR VIEW, RH

LIST

	\$	<i>1436.60</i>	1,436.60	✓
TOTAL	\$		1,436.60	
25%	\$		359.15	
	\$		1,077.45	