

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF503P*Not Authorized***AAD2202-***Pe Sany B4 paint**3211-55*

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

28 FEB 2022**SHF503P**

JTDKB3FU803093346

200303878K

TOYOTA

PRIUS GEN 4

27/02/2022

GBD7074X/CHINA

15/01/2021

	PART
1	COVER, FRONT BUMPER
1	BRACKET, FRONT BUMPER EXTENSION MOUNTING
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER
1	ABSORBER, FRONT BUMPER ENERGY
1	SUPPORT, FRONT BUMPER SIDE, RH
1	EXTENSION, FRONT BUMPER, RH
1	COVER, FRONT BUMPER HOLE, RH
1	MOULDING, FRONT BUMPER SIDE, RH
1	GRILLE SUB-ASSY, RADIATOR
1	GRILLE, RADIATOR, LOWER NO.1
1	EMBLEM ASSY, RADIATOR GRILLE
1	RIM
1	FENDER SUB-ASSY, FRONT RH
1	LINER, FRONT FENDER, RH

	LIST
\$	<i>Bm</i> 521.00 ✓
\$	<i>Sm</i> 110.50 X
\$	<i>R</i> 716.60 X
\$	<i>Sm</i> 80.20 X
\$	<i>Sm</i> 80.10 X
\$	<i>Sm</i> 120.10 X
\$	<i>Sm</i> 30.20 X
\$	<i>Sm</i> 95.60 X
\$	<i>Sm</i> 422.50 X
\$	<i>Sm</i> 178.60 X
\$	<i>Sm</i> 105.80 X
\$	<i>Sm</i> 1,900.10 X
\$	<i>Ry</i> 977.80 ✓
\$	<i>Sm</i> 202.50 X
TOTAL	\$ 4,361.30
25%	\$ 1,090.33
\$	\$ 3,270.98

Special Nett

1SET BUMPER CLIP FRT
1 TYRE
1 HUB CAB
1 FENDER LINER CLIP
1SET FRNT BUMPER RETAINER CLIP

\$	<i>Mr</i> 95.00 <i>Car</i>
\$	<i>Sm</i> 350.00 X
\$	<i>Sm</i> 211.50 X
\$	<i>nn</i> 65.00 X
\$	<i>nn</i> 85.00 X
TOTAL	\$ 806.50

TOTAL PARTS \$ 4,077.48

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF503P**AAD2202-****LABOUR**

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00 400l
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	nn 480.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00 30l
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00 500l
To Check Electrical Lighting Concerned.	\$	170.00 20l
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 220.00 X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	nn 380.00 X

TOTAL \$ 7,260.00**Over All Total \$ 11,337.48****LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

(PART-BY-PART) Repair Days**25 DAYS****2 days**

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF503P

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SUPPLEMENTARY**PART**

- 1 MIRROR ASSY, OUTER REAR VIEW, RH

AAD2202-**SHF503P**

JTDKB3FU803093346

200303878K

TOYOTA

PRIUS GEN 4

27/02/2022

GBD7074X/CHINA

15/01/2021

		LIST	
	\$	<i>Ad/Lm</i>	1,436.60 ✓
TOTAL	\$		1,436.60
25%	\$		359.15
	\$		1,077.45