

KAY MOTOR

BLOCK 9 SIN MING INDUSTRIAL ESTATE
#01-46

SINGAPORE 575644

Tel: 6458 2283

Fax: 6459 8863

Email: kayautosg@yahoo.com

Loh Kham Hwa

28 February, 2022

Estimate To Repair Toyota Altis – SML 655T

1pc	front bumper
1pc	front bumper o/s garnish
1pc	front bumper fog lamp
1pc	front bumper o/s side retainer
1pc	o/s head lamp 2999.80
1pc	o/s front fender
1pc	o/s front fender inner shield
1pc	o/s front fender 'VVTi' emblem
1pc	o/s front door 1247.20
1pc	o/s rear door 1248
1pc	o/s rear fender inner shield
1pc	o/s front knuckle arm 521.50
1pc	o/s front lower arm 543.80
1pc	o/s front shock absorber 438.30
1pc	o/s front stay link

Wash Tank 140.80 Rd ✓

less 25%

RM	\$	531.60	✓
CM		229.40	✓
RM		310.40	X
Dir		68.20	✓
RM		3970.80	✓
RM		908.90	✓
Dir		227.80	✓
RM		46.50	✓
RM		1260.00	✓
RM		1248.00	✓
RM		68.20	X
RM		628.20	✓
Dir		732.50	✓
RM		468.10	✓
RM		237.10	X
			10935.70
			2733.93
			8201.77

- o/s front tyre rim
- Computerise check wheel alignment
- o remove & fit o/s front suspension.
- o remove & refit o/s front & rear doors glass & auto mechanism
- o repair & panelbeat o/s front inner panel, o/s rocker panel,
- o/s rear fender, rear bumper, dismantle & fit the above parts.
- putty & spray painting

RM	480.00sn	✓
	80.00	601
	280.00	7801
	120.00	✓
	950.00	8501
	1,480.00	12001

Total: \$ 11591.77

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: