



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2303064

INV Date 16/05/2023

Reference CC4/LPC22001963/Bpa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SGG 2459C
Insured Veh. GBD 1477G
Claim No. 21/22/22/VC05/025502
Policy No. Z/21/VC05/008524-001
Accident Date 28/02/2022
Inspection Date 02/03/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

CHT



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC22001963/Bpa3q2 Date: 16/05/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 1477G	Veh. Inspected	SGG 2459C	
Policy No.	Z/21/VC05/008524-001	Coverage (\$)	0.00	
Claim No.	21/22/22/VC05/025502	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	02/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MR2B23F3801145456	Colour	GREY	
Odometer	89776 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	5 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	5 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	5 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/02/2022	Inspection Date	02/03/2022	
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGG 2459C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID	TO REPAIR SEE LABOUR	1,453.80	-
1	BOOTLID LOGO	NECESSARY	108.90	108.90
1	BOOTLID EMBLEM 'VIOS'	NECESSARY	88.00	88.00
1	BOOTLID EMBLEM 'E'	NECESSARY	68.00	68.00
1	BOOTLID INNER LOCK	NOT DAMAGED	198.60	-
1	BOOTLID INNER STRIKER	NOT DAMAGED	96.40	-
1	BOOTLID LAMP RH	NOT DAMAGED	805.30	-
1	BOOTLID INNER TRIM BOARD	NOT DAMAGED	359.20	-
1	BOOTLID WEATHERSTRIP	NOT DAMAGED	286.30	-
2	BOOTLID HINGE @\$186.90	NOT DAMAGED	373.80	-
1	BOOTLID ANTENNA SENSOR	NOT DAMAGED	387.50	-
1	BOOTLID BUZZER	NOT DAMAGED	286.30	-
1	REAR BUMPER	DENTED	1,136.40	556.00
2	REAR BUMPER SIDE RETAINER @\$186.30	NECESSARY	372.60	170.00
1	REAR BUMPER REINFORCEMENT	NOT DAMAGED	354.20	-
1	REAR BUMPER REFLECTOR RH	BROKEN	279.20	179.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	753.90	-
1	REAR END PANEL TOP GARNISH	NOT DAMAGED	196.50	-
2	TAILLAMP @\$984.30	O/S BROKEN	1,968.60	676.00
2	TAILLAMP LOWER BRACKET @\$89.20	O/S BROKEN	178.40	70.00
1	TAILLAMP BASE PANEL RH	NOT DAMAGED	685.40	-
	LESS 25% DISCOUNT		-2,609.33	-478.98
			7,827.97	1,436.92
2	REAR BUMPER REVERSE SENSOR @\$210.00 (SN)	SHORT CIRCUIT	420.00	200.00
	LESS 25% DISCOUNT		-105.00	-
			315.00	200.00
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NOT NECESSARY	80.00	-

Report Ref No. CC4/LPC22001963/Bpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOTLID SEALANT (SN)	NOT NECESSARY	100.00	-
1	BOOTLID LAMP CLIPS (SN)	NOT NECESSARY	50.00	-
1	BOOTLID LAMP SEAL (SN)	NOT NECESSARY	60.00	-
1	BOOTLID INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
2	REAR BUMPER REVERSE SENSOR SEAL @\$48.00 (SN)	NOT NECESSARY	96.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	50.00	-
2	TAILLAMP CLIPS @\$50.00 (SN)	O/S NECESSARY	100.00	20.00
2	TAILLAMP SEAL @\$60.00 (SN)	O/S NECESSARY	120.00	20.00
1	TAILLAMP BASE PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
			956.00	70.00
	LABOUR			
	R&R BOOTLID COMPONENT.	NOT NECESSARY	150.00	-
	R&R REAR BUMPER REVERSE SENSOR.		100.00	60.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	180.00	-
	CHECK WIRING.	NOT NECESSARY	100.00	-
	UPHOLSTERY.	NOT NECESSARY	300.00	-
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BOOTLID AND REAR END PANEL.		1,600.00	800.00
	RUST PROOFING.	NOT NECESSARY	200.00	-
	SPRAY PAINTING.		1,600.00	600.00
			4,230.00	1,460.00
GRAND TOTAL			13,328.97	3,166.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,550.00

Report Ref No. CC4/LPC22001963/Bpa3q2

LIM TEOW GUAN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGG 2459C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGG 2459C

RE-INSPECTION

