

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SGG 2459 C**
 Model : Toyota Vios
 Year : 2018
 Chassis No : MR2B23F3801145456

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Bootlid	1	\$ 1,453.80	\$ 1,453.80
2	Bootlid logo	1	\$ 108.90	\$ 108.90
3	Bootlid emblem 'Vios'	1	\$ 88.00	\$ 88.00
4	Bootlid emblem 'E'	1	\$ 68.00	\$ 68.00
5	Bootlid inner lock	1	\$ 198.60	\$ 198.60
6	Bootlid inner striker	1	\$ 96.40	\$ 96.40
7	Bootlid lamp RH	1	\$ 805.30	\$ 805.30
8	Bootlid inner trim board	1	\$ 359.20	\$ 359.20
9	Bootlid weatherstrip	1	\$ 286.30	\$ 286.30
10	Bootlid hinge	2	\$ 186.90	\$ 373.80
11	Bootlid antenna sensor	1	\$ 387.50	\$ 387.50
12	Bootlid buzzer	1	\$ 286.30	\$ 286.30
13	Rear bumper	1	\$ 1,136.40	\$ 1,136.40
14	Rear bumper side retainer	2	\$ 186.30	\$ 372.60
15	Rear bumper reinforcement	1	\$ 354.20	\$ 354.20
16	Rear bumper reflector RH	1	\$ 279.20	\$ 279.20
17	Rear bumper reverse sensor	2	\$ 210.00	\$ 200.00 420.00
18	Rear end panel	1	\$ 753.90	\$ 753.90
19	Rear end panel top garnish	1	\$ 196.50	\$ 196.50
20	Taillamp RH 1	2	\$ 984.30	\$ 1,968.60
21	Taillamp lower bracket RH 1	2	\$ 89.20	\$ 178.40
22	Taillamp base panel RH	1	\$ 685.40	\$ 685.40
			Parts Sub Total :	\$ 10,857.30
25%			Discount :	\$ 2,714.33
			PARTS TOTAL :	\$ 8,142.98

DDXR
 NEC
 NDX
 NDX
 NDX
 NDX
 DDV
 NECV
 NDX
 BRV
 SCV
 DDXR
 NDX
 BRV
 BRV
 NDX

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Bootlid sealant	1	\$ 100.00	\$ 100.00
3	Bootlid lamp clips	1	\$ 50.00	\$ 50.00
4	Bootlid lamp seal	1	\$ 60.00	\$ 60.00
5	Bootlid inner trim board clips	1	\$ 50.00	\$ 50.00
6	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00
7	Rear bumper reverse sensor seal	2	\$ 48.00	\$ 96.00
8	Rear end panel sealant	1	\$ 100.00	\$ 100.00
9	Rear end panel top garnish clips	1	\$ 50.00	\$ 50.00
10	Taillamp clips	1 RH 2	\$ 50.00	\$ 20.00 100.00
11	Taillamp seal	1 RH 2	\$ 60.00	\$ 20.00 120.00
12	Taillamp base panel sealant	1	\$ 100.00	\$ 100.00
SPECIAL NETT TOTAL :				\$ 956.00

NNX
NECV
NECV
NNX
NECV
NECV
NNX

Nos.	LABOUR	S\$
1	R&R bootlid component	\$ 450.00
2	R&R rear bumper reverse sensor	\$ 60.00 100.00
3	Conduct water leakage test	\$ 180.00
4	Check wiring	\$ 100.00
5	Upholstery	\$ 300.00
6	Panel beating	\$ 800.00 1,600.00
7	Rust proofing	\$ 200.00
8	Spray painting	\$ 600.00 1,600.00
LABOUR TOTAL :		\$ 4,230.00

NNX
/ NNX
NNX
NNX
NNX
/ NNX
/

Survey Resurvey
2/3/2022 3/3/2022
TGM km TGM km
1400hrs 1420 hrs

All external
damages only

PARTS TOTAL : \$ 8,142.98
SPECIAL NETT TOTAL : \$ 956.00
LABOUR TOTAL : \$ 4,230.00
GRAND TOTAL : \$ 13,328.98

Lamp sum repair
Repair days 6

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: