

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 5695411
H/P 91082728

Fax : 64816131

Liew Yu Keong
42 Jalan Setia 2/9
Taman Setia Indah
81100 Johor Bahru Johor

*Not Authored
11 Payer @ 4050/hr
Paying After Paint
5 days*

Vehicle No : JSL 8229
Make/Model : Honda BR-V
Year : 2017

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate assy	1760	
1 pc	Rear tail-gate glass moulding		
1 pc	Rear tail-gate centre reflector		
2 pcs	Rear tail-gate reflector	\$487.10	
1 pc	Rear tail-gate emblem : H		
1 pc	Rear tail-gate emblem : BR-V		
1 pc	Rear tail-gate emblem : I-VECT		
1 pc	Rear tail-gate outer chrome garnish		
1 pc	Rear tail-gate inner lock		
1 pc	Rear tail-gate inner lock sensor		
1 pc	Rear tail-gate inner trim board		
2 pcs	Rear no plate lamp	\$65.10	
1 pc	Rear o/s tail-gate lamp		
1 pc	Rear boot rubber		
1 pc	Rear end panel		
1 pc	Rear end panel inner garnish		
1 pc	Rear o/s fender inner trim board		
1 pc	Rear spare tyre panel top cover board		
1 pc	Rear bumper		
2 pcs	Rear bumper side retainer	\$55.10	
2 pcs	Rear bumper reflector	\$137.10	
1 pc	Rear bumper lower garnish		
1 pc	Rear o/s side bumper		
2 pcs	Rear reverse sensor	\$325.10	
2 pcs	Rear exhaust silencer		

By	\$1,950.20	✓
Re	\$165.20	✓
Re	\$387.50	X
Re	\$974.20	X
Re	\$65.70	✓
Re	\$60.10	✓
Re	\$70.20	✓
Re	\$205.70	✓
Re	\$285.60	✓
Re	\$225.10	X
Re	\$455.90	X
Re	\$130.20	X
Re	\$550.10	X
Re	\$255.10	X
Re	\$487.60	X
Re	\$185.90	X
Re	\$467.10	X
Re	\$255.70	X
Re	\$875.10	✓
Re	\$110.20	X
Re	\$274.20	X
Re	\$287.20	✓
Re	\$355.10	✓
Re	\$650.20	2000
Re	\$975.10	X
	\$10,704.20	

Less 20 % \$2,140.84
balance c/f \$8,563.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Accepted by Repairer

Signature

Date

8229

balance b/f \$8,563.36

S Nett

1 pc Rear tail-gate glass sealant
1 pc Rear reverse camera
20 pcs Rear bumper clip
1 pc Rear no plate

in *gain*
\$55.00
in \$300.00 *x*
\$3.00 *in* \$60.00 *✓*
in \$40.00 *✓*
\$455.00

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,000.00 *500*

To putty and spray paint

\$1,000.00 *700*

Check & reconnect wiring.

\$30.00 *20*

To respray anti-rust proofing treatment

\$100.00 *30*

Remove/refit rear windscreen to facilitate repair

\$120.00 *✓*

Remove/refit rear tail-gate mechanism to new door.

\$120.00 *60*

Remove/renew rear exhaust silencer.

in \$120.00 *x*

Remove/refit rear boot upholstery to facilitate repair.

\$100.00 *60*

Total

\$11,608.36