

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22001968/ATY3E2

Date: 06/04/2022

REFERENCE

Insured/Claimant: CHAN LYE YOONG Policy No: DMPCSNW00205562106

Date of Loss: 18/02/2022 Nature of Claim: OD Claim No: SNM22D201314/C01/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX8822K**
Make & Model: AUDI A5, 2.0 (A) Engine No: CDN322994
Reg. Date: 31/10/2013 (Man. Year: 2013) Chassis No: WAUZZZ8T8DA053283
Colour: Bronze Odometer: 99199 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$56,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	1,250.00	1,250.00	0.00	0.00
Nett Amount (S\$)	-1,250.00	-1,250.00	0.00	0.00

INSPECTION

Date of Assignment: 02/03/2022

Date Inspected: 04/03/2022 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 0.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$56,000.00
OMV :	\$50,481.00
PARF Rebate (1) :	\$31,826.00
Quota Premium Paid :	\$93,889.00
COE Rebate (2) :	\$15,432.00
Total Rebate (1) + (2) = :	\$47,258.00

The total amount incurred will be Market Value \$56,000.00 minus Total Rebate \$47,258.00 = \$8,742.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:		
Parts:	N/A	AUDI A5 2.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX8822K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >