

Submit to ins

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

CH/WH

Name : Shariffudin Bin Wanjor
Mastan (90070173)

Accident Date : 17-Feb-22

Vehicle No : FBK6947Y

Vehicle Model : Honda CB400SF

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	R \$ 196.00 X
2	Fork inner tubes	17 \$ 1,020.00 X
2	Fork outer tuber	SWC \$ 1,040.00 X
1	Fork under bracket	17 \$ 335.00 X
1	Fork outer cover	17 \$ 90.00 X
1	Front sport rim	R \$ 1,100.00 X
2	Front brake discs	o/s Deyeb \$ 1,120.00 17C
1	Front rim shaft	17 \$ 68.00 X
1	Front rim bearing	17 \$ 58.00 X
		\$ 5,027.00
	Less 10%	\$ 502.70
		\$ 4,524.30

Special Nett Items

1	Number plate (1 set)	17 \$ 38.00 X
2	Fork oils	17 \$ 30.00 X
2	Fork oil seals	17 \$ 56.00 X
1	Steering cone (1 set)	17 \$ 125.00 X
		\$ 249.00

S/No. Labour

1	To provide towing service (LOD)	\$ 17 - X
2	To check wiring and reset headlamp focusing	\$ 17 80.00 X
3	To provide labour	\$ 120 320.00
		\$ 400.00

565.50

P/P \$ 445.50

Grand Total

\$ 5,173.30

Singapore Dollars: Five Thousand One Hundred Seventy-Three and Cents: Thirty only

2-495

102

445.50

120

565.50

Not Allowed
1 days.
9/3/22
Zahid A. H. Khan

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and

EROFIA MOTOR TRADING PTE LTD

Acknowledged by Repairer

Signature:

Date: