



Pte Ltd

TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
ROC number : 201015366H
REPAIR PERFORMA INVOICE

FIRST CAPITAL

Vehicle number	GBK1687E
Make / Model	TOYOTA DYNA
Chassis number	JTFAT35YX0K214694
Accident date	1-3-22
Reference	2203-01

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	TAILGATE	1227.60 / DT
2	TAILGATE LOCK ASSY	435.60 ? XNV
4	TAILGATE HINGE	431.20 XXXX Xr
2	TAILGATE SIDE BRACKET	165.00 XSK
2	TAILGATE STOPPER	83.60 XSC
1	TAILGATE LOWER MEMBER	585.80 ? / PT
1	TAILGATE EMBLEM - DYNA	38.50 / nec
2	TAILLAMP	484.00 ? / Scr
2	TAILLAMP PANEL	198.00 ? / DT
1	REAR NUMBER PLATE BRACKET	217.80 / BT ISS
2	REAR NUMBER PLATE LAMP	105.60 XNV
1	SPARE TYRE CARRIER	277.20 ? / BT
1	SPARE TYRE BRACKET	194.70 ? Xr
1	EXHAUST SILENCER	680.13 ? / BT 547.5
1	EXHAUST MOUNTING	85.80 ? / nec 45.10
1	FRONT BUMPER	822.80 Xr
2	FRONT BUMPER BRACKET	561.00 XSV
1	FRONT BUMPER REINFORCEMENT	533.50 ? XNV
1	FRONT GRILLE ASSY	629.20 / rut 517
1	FRONT GRILLE EMBLEM	75.90 / nec
1	FRONT PANEL INNER	733.70 ? XNV
1	FRONT PANEL OUTER	1314.50 / DT 986
1	FRONT PANEL EMBLEM - DYNA	71.50 / nec
2	FRONT HEADLAMP	2357.40 ? - Cut 1696
2	CORNER PANEL	250-S 501.60 XXXX DT: RH CH Src
1	WIPER PANEL	361.90 / DT 314
1	WIPER LINK	404.80 ? XSC
1	AIRCON BLOWER	2491.50 ? - Cut 1218
1	RADIATOR	2024.00 ? XNV
		18093.83
Less 25%		4523.46
		13570.37
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1	TAILGATE STICKER - 70KM/H	50.00 XXXX 25 nec
1	TAILGATE STICKER - 6 PAX	50.00 25 nec
1	REAR NUMBER PLATE	80.00 40 BT
1 SET	REVERSE SENSOR	250.00 200 Cut
1	COMPANY SICKER	400.00 XXXX nec 150
1	TAILGATE STEP PANEL (AFTER MARKET)	350.00 BT PTC nec 180



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 ROC number : 201015366H
 REPAIR PERFORMA INVOICE

FIRST CAPITAL

Vehicle number	GBK1687E
Make / Model	TOYOTA DYNA
Chassis number	JTFAT35YX0K214694
Accident date	1-3-22
Reference	2203-01

Qty	Particulars	Unit Price - SGD \$	
	<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT WING MIRROR LH	660.11	Scr
1	COOLING COIL	1637.79	cut
		2297.90	
	Less 25%	574.48	
		1723.42	
	<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1	REAR NUMBER PLATE HOLDER	150.00	DT
	Subtotal	150.00	
	Balance C/F	1873.42	
	<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	R&R COOLING COIL	200.00	SO
	Subtotal	200.00	
	Grand total	2073.42	

482 365
 114.1

1	FLOOR WOODEN BOARD	800.00	XSV
1	FRONT NUMBER PLATE	80.00	XSV
1 SET	FRONT GRILLE CLIP	50.00	25
Subtotal		2110.00	
Balance C/F		15680.37	
<u>LABOUR AND MISCELLANEOUS CHARGES</u>			
1	CHECK WIRING AND LIGHTNING SYSTEM	120.00	30
2	R&R FRONT DASHBOARD	400.00	7.100
3	R&R AIRCON BLOWER	250.00	7.50
4	R&R AIRCON CONDENSER AND TOP UP GAS	200.00	7.80
5	R&R RADIATOR AND TOP UP COOLANT	200.00	7.80
6	REMOVE AND RENEW REAR EXHAUST	200.00	7.80
7	PANEL BEATING ON AFFECTED AREAS	2000.00	800
8	SPRAY PAINTING ON AFFECTED AREAS	2000.00	800
9	APPLY ANTI RUST ON AFFECTED AREAS	150.00	30
Subtotal		5520.00	
Grand total		21200.37	

Thwan

82235769

3/2/22 1700

US 6days up

7663.56

7650

8900

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: