



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22001974/Vqy3e2	
			Date: 11/05/2022	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHD 6199E	Veh. Inspected	GBK 1687E
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/03/22/2001	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	02/03/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA DYNA 150	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	JTFAT35YX0K214694	Colour	SILVER
	Odometer	38703 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	BRIDGESTONE	6 mm
	L/H Front Tyre	195 R15C	BRIDGESTONE	6 mm
	R/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm
	L/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	01/03/2022	Inspection Date	02/03/2022
	Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	