

Date : 3/3/2022

Reference: SJY 1701D

Make: 530I

To Whom It May Concern

Dear Sir,

RE: VEHICLE :: SJY 1701D**CHASSIS NO.: WBAJA52090G885542****ENGINE NO.: 13339918**

Name of insured :: Phang Yew Kit

Date of accident.: 28/2/2022

TP Ergo.
Veron.

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT FENDER LH <i>Dented</i>	1850.00 ✓ <i>885</i>
2	1	FRT FENDER INNERSHIELD LH <i>new</i>	330.00 +
3	1	FRT DOOR LH <i>Dented</i>	3590.00 ✓ <i>2387</i>
4	1	FRT DOOR HINGE UPP LH <i>new</i>	200.00 +
5	1	FRT DOOR HINGE LOW LH <i>new</i>	230.00 +
6	1	FRT DOOR CHECKER LH - Link Check <i>new</i>	330.00 +
7	1	FRT DOOR LOCK LH <i>new</i>	390.00 +
8	1	FRT DOOR LOCK CATCHER LH - Striker <i>new</i>	78.00 +
9	1	FRT DOOR RUBBER BEADING LH - Body Side <i>new</i>	460.00 + <i>245</i>
10	1	FRT DOOR WEATHER STRIP LH <i>new</i>	495.00 ✓ <i>174</i>
11	1	FRT DOOR OUTER HANDLE LH <i>new</i>	495.00 +
12	1	FRT DOOR OUTER HANDLE KNOB LH <i>new</i>	290.00 +
13	1	FRT DOOR GLASS OUTER MLDG LH <i>new</i>	380.00 +
14	1	FRT DOOR POWER WINDOW REGULATOR ASSY LH <i>new</i>	930.00 +

3791

Parts Total: 10,048.00

Less 10% 1,507.20

Total : 8,540.80

3411.90

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. Per day \$ 650	1500.00 <i>500</i>
2	Carry out spray painting on accident affected area. (LHF Door & fender ,) Per Panel	800.00 <i>500</i>
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	80.00 <i>30</i>
4	Transfer of internal mechanism from old door panel to new door panel	150.00 <i>80</i>

Labour Total : 2,530.00

1110

Other

<u>No.</u>	<u>Other Description</u>
1	SEALANT <i>for</i>

Price (SGD)

40.00 *+*

Other Total : 40.00

Total : \$11,110.80

Gst (7%) : \$777.76

GRAND TOTAL: \$11,888.56

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully


Service Advisor

Ronnie Tan Hp 94577916

DID: 6844 1985 Fax:6844 5185

*Adrian Lj**P/P, L/S 04/03/22**? ?**03 Days.**Total: 4521.90.*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: