Date: 9/3/22
Date:
To: AIGINSUMANCE Ptehtal
78 Shon ton way \$107-16
Singapore 079120

WITHOUT PREJUDICE

Dear Sir/Madam.

Accident Involving SDF707R & SMN 8261 H along Bukittimah Road on 1/3/22

I/We the owner of vehicle number SDF707 R , which was/were involved in the above mentioned accident.

I/We enclosed herewith all the relevant documents for your consideration to claim against you for the loss incurred by me/us as follows:

Total Amount	\$30	777 -75		
6) Others	\$			
5) Surveyor reports	\$			
4) LTA search fees	\$			
3) Police reports	\$			
2) Loss of use for 3 days @ \$ 8 0 - per day	\$ 400 - 00			
1) Cost of repairs (NVoice: 27027	\$3,5	577-75		

From the circumstances of the accident, it is patently obvious that your insured driver is solely responsible for the said accident. Therefore, please advice whether you are prepared to settle my/our claims as outlined above.

If there is a settlement, I/we hereby authorize you to pay whatever settlement sum to my/our repairer, M/s Jin Huat & Co., 176 Sin Ming Drive, #05-01 Sin Ming Autocare Complex, Singapore 575721, being the outstanding repair bill due to them which I/we have not settled to date.

Your immediate and co-operation to this matter will be greatly appreciated.

Pang Say Rong S0101013A

LETTER OF AUTHORITY

TO WHOM IT MAY CONCERN

On 3 >2 along Bukit Timah Road
INVe, Pang Say Kong NRIC No: 50101013A
of Singapore
owner of Motor Vehicle No: $50 \pm 707 \text{R}$ do hereby authorize M/s Jin Huat & Co as my authorized representative to write, negotiate and settle claim on my behalf regarding my claim against the party/parties involved in the above mentioned accident. All future correspondence should be addressed Jin Huat & Co , 176 Sin Ming Drive , #05-01 Sin Ming Autocare , Singapore 575721 .
In view of the above, I hereby authorize the party to pay direct to my representative.
I also authorize this Company to sign documents on my behalf relating to this accident, report this accident to my Insurance Company and/or any other related Authorities.
Dated this day of March 2072
Owner's Signature :
Name & NRIC No PANG SAY KONG SO101013 A
Witnessed by :
Name : Alice Tain III 100

JIN HUAT & CO

176 Sin Ming Drive, #05-01 Sin Ming Autocare Singapore 575721

Tel: 6453 2151; Fax: 6456 3060 email: jinhuat1951@gmail.com Co. Reg. No: 020403/00C

Invoice No: 27027

Date: 08 March 2022

Payment Terms: On receipt of invoice

Pages: 1 of 1

INVOICE

To:

Mr Pang Say Kong

Ms Pang See Leng

16 Jalan Bingka Singapore 588914

Contact:

9833 3683

Vehicle No:

SDF 707 R

Model:

Toyota CHR

Insurer

UOI Insurance

Accident Details:	Qty	The same of the sa	STREET, SQUARE, SQUARE	Unit Price		tal Price
Date of Accident: 01 March 2022						
T/P claim against Vehicle No. SMN 8261 H						
nsured with AIG Insurance						
Parts:			-			
Front bumper	1	pc	\$	385.00	\$	385.00
LH front fender	1	рс	\$	325.00	\$	325.00
LH front wheel arch garnish	1	рс	\$	190.00	\$	190.00
H front side retainer	1	рс	\$	59.00	\$	59.00
LH H/lamp - HID	1	рс	\$	2,140.00	\$	2,140.00
LH H/lamp bracket holder	1	pc	\$	85.00	\$	85.00
H front bumper sensor	1	рс	\$	235.00	\$	235.00
Clips	10	рс	\$	1.80	\$	18.00
Less 25% discount on parts (items 1 to 8)	1	lot	-\$	859.25	-\$	859.25
abour:						
abour to repair and replace parts	1	lot	\$	400.00	\$	400.00
Spray painting & underseal (Pearl White)	1	lot	\$	600.00	\$	600.00
			+			
	H H/lamp bracket holder H front bumper sensor lips Less 25% discount on parts (items 1 to 8) abour: abour to repair and replace parts	H H/lamp bracket holder H front bumper sensor lips 10 Less 25% discount on parts (items 1 to 8) abour: abour to repair and replace parts 1	H H/lamp bracket holder H front bumper sensor lips 1 pc lips 10 pc Less 25% discount on parts (items 1 to 8) abour: abour: abour to repair and replace parts 1 lot	H H/lamp bracket holder H front bumper sensor I pc \$ H front bumper sensor I pc \$ I pc \$ Less 25% discount on parts (items 1 to 8) Abour: Abour to repair and replace parts I lot \$	H H/lamp bracket holder H front bumper sensor I pc \$ 85.00 H front bumper sensor I pc \$ 235.00 lips I pc \$ 235.00 I pc \$ 1.80 Less 25% discount on parts (items 1 to 8) Abour: abour: abour to repair and replace parts I lot \$ 400.00	H H/lamp bracket holder 1 pc \$ 85.00 \$ H front bumper sensor 1 pc \$ 235.00 \$ lips 10 pc \$ 1.80 \$ Less 25% discount on parts (items 1 to 8) 1 lot -\$ 859.25 -\$ abour: abour to repair and replace parts 1 lot \$ 400.00 \$

All Cheques must be crossed and made payable to JIN HUAT & Co

Electronic Payment: OCBC Ltd - A/c No: 656-818010-001

PayNow: UEN No: 02040300C

JIN HUAT & CO

Alice Tan