

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22001984/APA3Q2**Date:** 11/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100071395
Claimant Vehicle No :	SLX1654M	Insured Vehicle No :	SJD8171Y
Date of Loss:	24/01/2022	Nature of Claim:	TP
		Claim No:	4387528502SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX1654M	Engine No:	21405170B48B20A
Make & Model:	BMW 520I, 2.0 (A)	Chassis No:	WBAJA12080WC08967
Reg. Date:	19/03/2018 (Man. Year: 2017)	Odometer:	106664 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,935.47	2,936.56	11,998.91	80.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,170.00	1,070.00	6,100.00	85.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,105.47	4,006.56	18,098.91	81.88
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	22,105.47	3,200.00	18,905.47	85.52
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		3,536.45		
Global Sum Settlement (S\$)		3,500.00		

INSPECTION

Date of Assignment:	02/03/2022	
Date Inspected:	02/03/2022	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,650.85 FL	*1,650.85 FL
2	1		*REAR BUMPER CENTER MOULDING	Deformed	381.15 FL	*381.15 FL
3	1		*REAR BUMPER REFLECTOR	N/S Cracked	150.00 FL	*75.00 FL
4	1		*REAR BUMPER TOWING COVER	Not Necessary	55.70 FL	*- FL
5	4		*REAR BUMPER SENSOR	Damaged (2 PCS ONLY)	947.40 FL	*440.00 FL
6	4		*REAR BUMPER SENSOR HOLDER	Necessary	248.20 FL	*100.00 FL
7	1		*REAR BUMPER SENSOR WIRE HARNESS	Not Necessary	1,475.65 FL	*- FL
8	1		*REAR BUMPER BOTTOM CENTER COVER GARNISH	Torn	197.95 FL	*197.95 FL
9	1		*REAR BUMPER REINFORCEMENT	Not Necessary	774.25 FL	*- FL
10	1		*REAR BUMPER REINFORCEMENT COVER GARNISH	Cracked	168.45 FL	*168.45 FL
11	1		*REAR BUMPER TOP BEAM	Cracked	395.00 FL	*205.00 FL
12	2		*REAR BUMPER SIDE BRACKET (PLASTIC)	Not Necessary	281.50 FL	*- FL
13	2		*TAIL LAMP	Not Necessary	1,188.50 FL	*- FL
14	2		*TAIL LAMP SIDE GARNISH	Not Necessary	78.90 FL	*- FL
15	1		*REAR FENDER INNER TRIM RH	Not Necessary	764.65 FL	*- FL
16	1		*REAR FENDER INNER STORAGE BOX RH	Not Necessary	294.75 FL	*- FL
17	1		*BOOT LID	Not Necessary	1,692.45 FL	*- FL
18	1		*BOOT LID EMBLEM 528I	Not Necessary	97.60 FL	*- FL
19	1		*BOOT LID LOGO	Not Necessary	69.55 FL	*- FL
20	1		*BOOT LID TOP LOCK	Not Necessary	79.85 FL	*- FL
21	1		*BOOTLID SMART OPENER MODULE	Not Necessary	468.85 FL	*- FL
22	1		*BOOT LID WEATHERSTRIP	Not Necessary	215.35 FL	*- FL
23	1		*BOOT LID SENSOR DETECTOR	Not Necessary	414.75 FL	*- FL
24	1		*BOOT LID LOWER LOCK	Not Necessary	376.45 FL	*- FL
25	1		*REAR END PANEL	Not Necessary	817.35 FL	*- FL
26	1		*REAR END PANEL TOP GARNISH	Not Necessary	195.00 FL	*- FL
27	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	683.55 FL	*- FL
28	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
29	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
30	1		*SET REAR BUMPER BOTTOM COVER GARNISH CLIP	Necessary	50.00 FS	*10.00 FS
31	1		*SET TAIL LAMP CLIP	Not Necessary	60.00 FS	*- FS
32	1		*SET TAIL LAMP SIDE GARNISH CLIP	Not Necessary	50.00 FS	*- FS
33	1		*BOOT LID SEALANT	Not Necessary	150.00 FS	*- FS
34	1		*SET BOOT LID INSULATOR CLIP	Not Necessary	80.00 FS	*- FS
35	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
36	1		*REAR END PANEL INSULATION SEAL	Not Necessary	250.00 FS	*- FS
37	1		*SET REAR END PANEL TOP GARNISH CLIP	Not Necessary	30.00 FS	*- FS
38	1		*SET REAR FLOOR STORAGE GARNISH CLIP	Not Necessary	50.00 FS	*- FS
39	1		*REVERSE CAMERA	Not Necessary	550.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,643.65	3,258.40
- List Item Discount on L Items 5.00/10.00% (\$\$)	708.18	321.84

Total Parts (\$\$)	14,935.47	2,936.56
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,800.00	400.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	500.00
3	TUFF COAT	New	250.00	50.00
4	WIRING CHECK	New	380.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	380.00	40.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	150.00	50.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	100.00	0.00
8	TRANSFER BOOT LID MECHANISM	New	150.00	0.00
9	RESET BOOT LID SYSTEM	New	350.00	0.00
10	RESET BRAKE SMART OPEN MODULE SENSOR	New	280.00	0.00
11	REAR CHASSIS ALIGNMENT	New	250.00	0.00
12	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPEFICIATION ETC	New	1,200.00	0.00
Gross Labour Cost (\$\$)			7,170.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >