

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 02.03.2022

WBAJA12080WC08967

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLX1654M**
MODEL : **BMW 520i**
DATE OF ACCIDENT : 24.01.2022
TIME OF ACCIDENT : 17:30HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Rebond</i>	1	\$ 1,650.85	\$ 1,650.85
2	REAR BUMPER CENTER MOUDLING <i>Rebond</i>	1	\$ 381.15	\$ 381.15
3	REAR BUMPER REFLECTOR <i>1H cruld</i>	2	\$ 75.00	\$ 150.00
4	REAR BUMPER TOWING COVER <i>Not Nec</i>	1	\$ 55.70	\$ 55.70
5	REAR BUMPER SENSOR <i>2 pieces damaged</i>	4	\$ 236.85	\$ 947.40
6	REAR BUMPER SENSOR HOLDER <i>Nec</i>	4	\$ 62.05	\$ 248.20
7	REAR BUMPER SENSOR WIRE HARNESS <i>Not Nec</i>	1	\$ 1,475.65	\$ 1,475.65
8	REAR BUMPER BOTTOM CENTER COVER GARNISH <i>Not Nec</i>	1	\$ 197.95	\$ 197.95
9	REAR BUMPER REINFORCEMENT <i>Nec</i>	1	\$ 774.25	\$ 774.25
10	REAR BUMPER REINFORCEMENT COVER GARNISH <i>Rebond</i>	1	\$ 168.45	\$ 168.45
11	REAR BUMPER TOP BEAM <i>cruld</i>	1	\$ 395.00	\$ 395.00
12	REAR BUMPER SIDE BRACKET (PLASTIC) <i>Nec</i>	2	\$ 140.75	\$ 281.50
13	TAIL LAMP <i>2</i>	2	\$ 594.25	\$ 1,188.50
14	TAIL LAMP SIDE GARNISH <i>MP</i>	2	\$ 39.45	\$ 78.90
15	REAR FENDER INNER TRIM RH <i>Nec</i>	1	\$ 764.65	\$ 764.65
16	REAR FENDER INNER STORAGE BOX RH	1	\$ 294.75	\$ 294.75
17	BOOT LID <i>2</i>	1	\$ 1,692.45	\$ 1,692.45
18	BOOT LID EMBLEM '528i'	1	\$ 97.60	\$ 97.60
19	BOOT LID LOGO <i>Not Nec</i>	1	\$ 69.55	\$ 69.55
20	BOOT LID TOP LOCK <i>Nec</i>	1	\$ 79.85	\$ 79.85
21	BOOTLID SMART OPENER MODULE	1	\$ 468.85	\$ 468.85
22	BOOT LID WEATHERSTRIP	1	\$ 215.35	\$ 215.35
23	BOOT LID SENSOR DETECTOR	1	\$ 414.75	\$ 414.75
24	BOOT LID LOWER LOCK	1	\$ 376.45	\$ 376.45
25	REAR END PANEL	1	\$ 817.35	\$ 817.35
26	REAR END PANEL TOP GARNISH <i>Not Nec</i>	1	\$ 195.00	\$ 195.00

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLX1654M**
 MODEL : **BMW 520i**
 DATE OF ACCIDENT : **24.01.2022**
 TIME OF ACCIDENT : **17:30HRS**

27	REAR FLOOR PANEL TOP BOARD <i>Neu</i>	1	\$ 683.55	\$ 683.55	<i>+</i>
----	---------------------------------------	---	-----------	-----------	----------

3218.40
2896.56

TOTAL PRICE \$ 14,163.65
 LESS 5% \$ 708.18
SUB TOTAL PRICE \$ 13,455.47

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PALTE <i>Neu</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
2	REAR BUMPER CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
3	REAR BUMPER BOTTOM COVER GARNISH CLIP (SET) <i>Neu</i>	1	\$ 50.00	\$ 50.00	<i>10</i>
4	TAIL LAMP CLIP (SET) <i>Neu</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
5	TAIL LAMP SIDE GARNISH CLIP (SET) <i>Neu</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
6	BOOT LID SEALANT <i>Neu</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
7	BOOT LID INSULATOR CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
8	REAR FENDER INNER TRIM CLIPS (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
9	REAR END PANEL INSULATION SEAL <i>Neu</i>	1	\$ 250.00	\$ 250.00	<i>+</i>
10	REAR END PANEL TOP GARNISH CLIP (SET) <i>Neu</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
11	REAR FLOOR STORAGE GARNISH CLIP (SET) <i>Neu</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
12	REVERSE CAMERA <i>Neu</i>	1	\$ 550.00	\$ 550.00	<i>+</i>

TOTAL \$ 1,480.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	<i>400</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	<i>500</i>
3	TUFF COAT	\$ 250.00	<i>50</i>
4	WIRING CHECK	\$ 380.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 380.00	<i>40</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 150.00	<i>50</i>
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 100.00	<i>+</i>
8	TRANSFER BOOTLID MECHANISM	\$ 150.00	<i>+</i>
9	RESET BOOD LID SYSTEM	\$ 350.00	<i>+</i>
10	RESET BRAKE SMART OPEN MODULE SENSOR	\$ 280.00	<i>+</i>

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLX1654M**
MODEL : **BMW 520i**
DATE OF ACCIDENT : **24.01.2022**
TIME OF ACCIDENT : **17:30HRS**

11	REAR CHASSIS ALIGNMENT	\$ 250.00	X
12	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 1,200.00	X

1070

TOTAL \$ 7,170.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 14,935.47
TOTAL LABOUR COST : \$ 7,170.00
TOTAL REPAIR COST : \$ 22,105.47

Adrian
L/S 02/03/22
03 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP: 8297 9787

Total: 4006.56
L/S: 3.2k

3.2k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: