

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22001985/KTY3E2

Date: 06/04/2022

REFERENCE

Insured/Claimant: SURIYAMURTHY DHINAKARAN Policy No: DMPCSNW00247892100

Date of Loss: 27/02/2022

Nature of Claim: OD

Claim No: SNM22D201442/C01/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMR6504A**
Make & Model: BMW 520I, 2.0 L AT D/AB 2WD 4DR GAS/D NAV (A) Engine No: A9200440N20B20B
Reg. Date: 29/05/2013 (Man. Year: 2013) Chassis No: WBAXG12030DX53315
Colour: Metallic Silver Odometer: 133813 km
Engine Capacity: 1997 cc
Market Value/New Car Price: S\$46,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,024.00	15,600.00	7,424.00	32.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	423.50	371.00	52.50	12.40
Paintwork Labour	424.26	397.18	27.08	6.38
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,871.76	16,368.18	7,503.58	31.43
Approved Total (Overridden) (S\$)		12,900.00		
- Excess (S\$)	0.00	750.00	-750.00	
(S\$)	23,871.76	12,150.00	11,721.76	49.10
+ GST 7.00/7.00% (S\$)	1,671.02	850.50	820.52	49.10
Nett Amount (S\$)	25,542.78	13,000.50	12,542.28	49.10

INSPECTION

Date of Assignment: 02/03/2022 Present Location: Ding Auto Pte Ltd (HQ)
Date Inspected: 03/03/2022 Inspected At: Ding Auto Pte Ltd (HQ)
176 Sin Ming Drive #04-06, Sin Ming Autocare
Singapore 575721
Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Apr 2022)
Parts:	143	BMW 520I 2.0 L AT D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR6504A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		23,024.00 F	*15,600.00 F
F=Franchise part.						
Total Parts (S\$)					23,024.00	15,600.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	259.00	234.50
2	Total Paint Materials	New	165.26	162.68
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	423.50	371.00
Gross Labour Cost (\$\$)			847.76	768.18

Report was unsubmitted during this print-out.

< END OF ESTIMATES >