

ASS. REC. BY:

REF:

CT2/22001985/K+

C

Kenneth

CS/CTI22001985/Kty3 ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TPRES/ODRES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. DMPCSNW00247892100

Claims No. SNM22D201442/C01/TAYHP

Sum Insured:

Excess:


750

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

846k

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMR 6504A

Yr Regn:

03, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 520i

c.c

1997

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading:

133813

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBA XG 12030DX 53315

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

R:

225/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

27/2/22

D.O.I.

3/3/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/3 TIR @ 12,900. Conf

RED: 10971.76;45%

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trlp:

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Estimate Repair

Ding Auto Pte Ltd
Sin Ming Industrial Est. Sec C, Blk
10, #01-20
575645



Insurer Reference:
Repairer Reference: 046477
Date calculated: 01/03/2022 1:47 PM

Full Report
Registration: SMR6504A
Printed: 01/03/2022 1:48 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Ding Auto	Currency:	SGD
Claim Reference:		Date of Incident:	27/02/22
Estimated Repair Time:	12	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle
 Manufacturer: BMW
 Model: 5 SERIES F10
 Sub Model: 520 I
 Model Sheet Number: 01 4A 01
 Registration: SMR6504A
 VIN number:
 Odometer: 133811
Model Specs
 AIR CON AUTO 2-ZONES 2.0 LTR 180KW

Not Insured
11 Rm @ 12, 900
Heavy After Pain
Ex @ 750
8 days

Labour

Code	Description	Time Base 12 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	ADD/TIME FOR MAIN WORK		2.0	7.00
NO NUMBER	R + R L/F SUSPENSION CROSS BRACE		2.0	7.00
NO NUMBER	R + R R/F SUSPENSION CROSS BRACE		2.0	7.00
64 511)	R + R FRONT PANEL SUPPORT		1.0	3.50
51 64 533	RENEW BOTH FRONT PANEL SUPPORTS (FRT BUMPER SUPPORT REMOVED) INCLUDES: HEADLAMP, AIR GUIDE RADIATOR AND DEFORMATION ELEMENT REMOVE AND REFIT		21.0	73.50
51 23 621)	R + R BOTH BONNET LOCKS		3.0	10.50
51 11 656	R + R FRONT BUMPER		9.0	31.50
51 11 566	R + R BOTH FRONT BUMPER CARRIERS		7.0	24.50
51 11 592	RENEW FRONT BUMPER COVER (FRONT BUMPER REMOVED)		6.0	21.00
51 64 521)	RENEW REAR CONNECTING STRUT (REMOVED) INCLUDES: CONVERT SUSPENSION CROSS BRACE		3.0	10.50
65 76 607	R + R CENTRE BUMPER SENSOR		1.0	3.50
65 76 626)	R + R FRONT BUMPER SENSOR		1.0	3.50
63 12 524	RENEW L/HEADLAMP (REMOVED)		4.0	14.00

Code	Description	WU	Price SGD
63 12 524	RENEW R/HEADLAMP (REMOVED)	4.0	14.00
63 99 647)	RENEW BOTH FRT PARKING LIGHT LED MODULES	3.0	10.50
51 71 540	R + R L/FRT WHEELHOUSE COVER	7.0	24.50
41 61 510	R + R BONNET	4.0	14.00
41 61 503	REPLACE BONNET (WITH BONNET REMOVED)	10.0	35.00
41 61 571)	RENEW L/BONNET HINGE	3.0	10.50
41 61 572)	RENEW R/BONNET HINGE	3.0	10.50
51 76 530	R + R REAR BONNET SEAL	1.0	3.50
51 76 535)	R + R L/F MOUNT	1.0	3.50
64 50 510	DRAIN/REFILL AIR CONDITIONING	6.0	21.00
17 11 510	R + R RADIATOR INCLUDES: R + R ELECTRIC FAN DRAIN + REFILL COOLANT	13.0	45.50
64 53 551)	R + R AIR CONDITIONING CONDENSER	2.0	7.00
17 51 550)	R + R AIR INTERCOOLER	2.0	7.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		10.10	121.0
Total of Labour			423.50

Paint

Paint Work		Time Basis 12 WU/h	
Code	Description - MF	WU	Price SGD
99 68 529	FRONT BUMPER COVER PAINTING STAGE 2	16.0	56.00
LE 0313	FRT TOWING EYE COVER PAINTING STAGE 2	3.0	10.50
99 61 529	BONNET PAINTING STAGE 2	30.0	105.00
LE 0633	L/WASHER NOZZLE TRIM PAINTING STAGE 2	2.0	7.00
LE 0634	R/WASHER NOZZLE TRIM PAINTING STAGE 2	2.0	7.00
99 99 000	ADDITIONAL TIME FOR ONE MAIN WORK INCLUDES: MIX COLOUR AND SPRAY COLOUR SAMPLE	21.0	73.50
Total Paint		Hrs 6.20	WU 74.0
			Price SGD 259.00
Material Cost - Paint			Price SGD
New Part Painting			151.79
Material-constant Metal			13.47
Total			165.26

Spare Parts

				prices as at 2022-02-16	
Code	Description	Part Number	Part Source	Price SGD	
0257 ✓	FRONT NUMBER PLATE	KNPL3	Original	✓ B	35.00 ✓
0260 ✓	FRT NO PLATE BRKT	51 11 7 331 726	Original	B	35.00 ✓
0283 ✓	FRONT BUMPER COVER	51 11 7 332 676	Original	✓ B	1,450.00 ✓
0303 ✓	FRT BUMPER GRILLE	51 11 7 331 724	Original	✓ Cpt	85.00 ✓
0305 ✓	L/AIR INTAKE TRIM	51 11 7 331 763	Original	Sm	30.00 ✗
0306 ✓	R/AIR INTAKE TRIM	51 11 7 331 764	Original	Sm	30.00 ✗

Code	Description	Part Number	Part Source	Price SGD
0307 ✓	L/BUMPER AIR GRILLE	51 11 7 331 727	Original	mi 40.00 ✓
0308 ✓	R/BUMPER AIR GRILLE	51 11 7 331 728	Original	sm 40.00 X
0313	FRT TOWING EYE COVER	51 11 7 332 682	Original	sm 55.00 X
0321	L/BRACKET	51 11 7 263 325	Original	nm X Di 22.00 ✓
0322	R/BRACKET	51 11 7 263 325	Original	sm 22.00 X
0325 ✓	L/F AIR DUCT	51 74 7 903 889	Original	nd 60.00 ✓
0326 ✓	R/F AIR DUCT	51 74 7 903 890	Original	rd 60.00 ✓
0334 ✓	FRT LWR BUMPER SUPP	51 11 7 203 078	Original	Di 150.00 ✓
0336 ✓	FRT UPP BUMPER SUPP	SEE GUIDE NO. 0333	Original	r 660.00 ✓
0340 ✓	FRT UPP IMPACT DAMP	51 11 7 331 748	Original	rd 110.00 ✓
0367 ✓	L/F VENT DUCT	51 74 7 331 783	Original	sm 50.00 X
0368 ✓	R/F VENT DUCT	51 74 7 331 784	Original	sm 50.00 X
0415 ✓	L/F GRILLE	51 13 7 412 323	Original	cm 80.00 ✓
0416 ✓	R/F GRILLE	51 13 7 412 324	Original	cm 80.00 ✓
0431 ✓	GRILLE BADGE	51 14 7 057 794	Original	rd 70.00 ✓
0463	L/F SUSPN BUFFER	51 23 7 162 448	Original	sm 25.00 X
0464	R/F SUSPN BUFFER	51 23 7 162 448	Original	sm 25.00 X
0465	BONNET ADJUSTER	51 76 7 183 752	Original	sm 15.00 X
0471 ✓	BONNET	41 61 7 207 194	Original	✓ Bu 1,900.00 ✓
0475	L/BONNET HINGE	41 00 7 270 883	Original	r 90.00 X
0476	R/BONNET HINGE	41 00 7 270 884	Original	r 90.00 X
0481 ✓	SOUND INSULATION	51 48 6 989 301	Original	Dis 220.00 X
0485 ✓	FRT CTR BUMP SENSOR	65 77 9 241 032	Original	rd 190.00 ✓
0487 ✓	FRT BUMPER SENSOR	65 76 9 318 777	Original	✓ r 280.00 ✓
0491 ✓	L/UPPER LOCK	51 23 7 183 763	Original	Dis 60.00 ✓
0492 ✓	R/UPPER LOCK	51 23 7 183 764	Original	Dis 60.00 ✓
0494	SAFETY LATCH	51 23 7 183 765	Original	r 120.00 X
0503 ✓	L/BONNET LOCK	51 23 7 206 453	Original	Dis 160.00 X
0504 ✓	R/BONNET LOCK	51 23 7 183 762	Original	Br 160.00 X
0561 ✓	LEFT HEADLAMP ASSY	63 11 7 343 913	Original	nd cm 2,750.00 ✓
0562 ✓	RIGHT HEADLAMP ASSY	63 11 7 343 914	Original	cm 2,750.00 ✓
0567	L LED-MODUL SET	63 11 7 343 876	Original	sm 550.00 X
0568	R LED-MODUL SET	63 11 7 343 876	Original	sm 550.00 X
0571 ✓	L/HEADLAMP SEAL	63 11 7 240 367	Original	nm 40.00 X
0572 ✓	R/HEADLAMP SEAL	63 11 7 240 368	Original	nm 40.00 X
0591	L/HEADLAMP MOULDING	63 11 7 349 295	Original	sm 50.00 X
0592	R/HEADLAMP MOULDING	63 11 7 349 296	Original	sm 50.00 X
0593 ✓	L/F HEADLAMP BRACKET	41 35 7 207 209	Original	sm 90.00 X
0594 ✓	R/F HEADLAMP BRACKET	41 35 7 207 210	Original	Dis sm 90.00 ✓
0633	L/WASHER NOZZLE TRIM	51 11 7 332 683	Original	sm 40.00 X
0634	R/WASHER NOZZLE TRIM	51 11 7 332 684	Original	mi 40.00 ✓
0747	L/F SUPPORT	51 76 7 019 803	Original	r 70.00 X
0841 ✓	L/F W-HOUSE CVR FRT	51 71 7 186 727	Original	cm 130.00 X
0843 ✓	L/F W-HOUSE RR COVER	51 71 7 186 723	Original	cm 130.00 X
0845 ✓	L/F LIP	51 75 7 312 829	Original	sm 75.00 X
1009 ✓	RADIATOR AIR GUIDE	51 64 7 332 892	Original	cm 560.00 ✓
1017 ✓	FRT CONNECTING STRUT	51 64 7 200 689	Original	sm 220.00 ✓
1018 ✓	RR CONNECTING STRUT	51 64 4 868 863	Original	Pvc 150.00 ✓
1019 ✓	L/F PANEL SUPPORT	51 64 7 187 095	Original	r 25.00 X
1020 ✓	R/F PANEL SUPPORT	51 64 7 187 096	Original	r 25.00 X
1021 ✓	L/SPACER BRACKET	51 11 7 207 931	Original	sm 25.00 X
1022 ✓	R/SPACER BRACKET	51 11 7 207 932	Original	sm 25.00 X
1187 ✓	L/F PANEL SUPPORT	51 64 7 200 793	Original	Br 230.00 ✓
1188 ✓	R/F PANEL SUPPORT	51 64 7 200 794	Original	Br 230.00 ✓

Code	Description	Part Number	Part Source	Price SGD
1209 ✓	L/F CROSS BRACE	51 71 7 180 317	Original	25.00 X
1210 ✓	R/F CROSS BRACE	51 71 7 180 318	Original	25.00 X
4465 ✓	CONDENSER	64 53 6 805 453	Original	1,100.00 X
7761 ✓	RADIATOR	17 11 8 672 014	Original	600.00 X
7768 ✓	UPP RADIATOR BRACKET	17 11 7 645 650	Original	90.00 X
7769 ✓	L/RADIATOR BRACKET	17 11 7 618 771	Original	95.00 X
7770 ✓	R/RADIATOR BRACKET	17 11 7 618 772	Original	95.00 X
7771 ✓	L/LWR RADIATOR BRKT	17 11 7 575 247	Original	35.00 X
7772 ✓	R/LWR RADIATOR BRKT	17 11 7 575 248	Original	35.00 X
7789	ELECTRIC FAN CPL	17 41 8 642 161	Original	1,080.00 X
8727 ✓	INTERCOOLER	17 11 7 618 768	Original	480.00 X
8781 ✓	L/F AIR DUCT	51 75 7 185 167	Original	50.00 X
8782 ✓	R/F AIR DUCT	51 75 7 185 168	Original	50.00 X
9645 ✓	LOW TONE HORN	61 33 7 279 782	Original	80.00 X
9646 ✓	HIGH TONE HORN	61 33 7 279 781	Original	80.00 X
1000 ✓	FRT PARKING SENSOR	PARKING SENSOR	Original	640.00 X
1001	H/LAMP LED LH	HEADLAMP MODULE	Original	700.00 X
1002	H/LAMP LED CORNER LH	HEADLAMP MODULE	Original	940.00 X
1003	H/LAMP LED LIGHT LH	HEADLAMP MODULE	Original	680.00 X
1004	H/LAMP LED DRIVER LH	HEADLAMP MODULE	Original	600.00 X
f: OEM Parts				0.00
n: Non-OEM Parts				23,024.00
u: Used parts				
Savings				
Subtotal				
Total				23,024.00

Final Calculation

	SGD	SGD
Parts		
Total Parts	23,024.00	23,024.00
Labour Time Base 12 WU/h		
Total 121.0 WU X 42.00 SGD/h		
Total of Labour	371.00 423.50	423.50
Paint Work Time Base 12 WU/h		
Labour Cost 74.0 WU X 42.00 SGD/h		
Material Cost	224.50 259.00	
Total Paint Including Material	162.68 165.26	424.26
Repair Cost Excludes GST		23,871.76
GST (+7.0%)		1,671.02
Repair Cost Included GST		25,542.78

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	040J
Vehicle Details	
Vehicle No.:	SMR6504A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Mar 2022
Vehicle Make:	B.M.W.
Vehicle Model:	520I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	A9200440N20B20B
Chassis No.:	WBAXG12030DX53315
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$41,566.00
Original Registration Date:	29 May 2013
First Registration Date:	29 May 2013
Transfer Count:	1
Actual ARF Paid:	\$45,193.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 May 2023
PARF Rebate Amount:	\$24,856.00
Intended COE Rebate Details	
COE Expiry Date:	28 May 2023
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$66,701.00
COE Rebate Amount:	\$8,158.00
Total Rebate Amount:	\$33,014.00

The information contained herein is correct as at 28 Feb 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	28/02/2022 17:04 (SGT)
Date of Accident	27/02/2022 21:47 (SGT)
Exact Location of Accident	Upper Serangoon Rd, Singapore
Additional Location Information	ALONG UPPER SERANGOON ROAD TOWARDS SENGKANG/PUNGGOL.
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMR6504A
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	SURIYAMURTHY DHINAKARAN
NRIC No	SXXXX040J
Email Address	dhinakar_2009@yahoo.com.sg
Mobile Phone No	(Phone) +65-91677020
Alternative Phone No	(Office) +65-69138328

VEHICLE PARTICULARS

Manufacturer	BMW
Model	520i
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1998

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMPCSNW00247892100
Cover Note Number	-

DRIVER

Name of Driver	SURIYAMURTHY DHINAKARAN
----------------	-------------------------



NRIC No	SXXXX040J
Date Of Birth	07/06/1978
Occupation	Outdoor
Date Of Driving Pass	29/06/2018
Driving experience	3 YEARS AND 8 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91677020
Alt. Phone Number	(Office) +65-69138328
Email Address	dhinakar_2009@yahoo.com.sg
Address	9 RIVERVALE CRESCENT #09-31 SINGAPORE
Address complement	-
Postcode	545086
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO THE SKETCH PLAN.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD6077Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	TEO HOCK SENG
NRIC No	SXXXX992Z
Contact Number	(Phone) +65-97668949

Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SFY8368J
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection or investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/PIN No:



SKETCH PLAN

Church of the Nativity of the Blessed Virgin Mary

Hongkong Ave 8

Vehicle A : SMR 6504A
Vehicle B : SHP 60772
Vehicle C : SPY 8368J

A B C

To Serangkang/Punggol

Upper Serangoon Road.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On stated date & time, whilst I was travelling along Upper Serangoon Road heading Serangkang. Suddenly my front vehicle 'B' was about to move when traffic light turned green but stopped abruptly which cause me panicked and I jammed my vehicle 'A' brake but still unable to stop on time and collided into my front vehicle 'B' which cause my front vehicle's bumper and bonnet badly damaged.

No injury was reported.

DECLARATION

/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time

Company Chop (If applicable)

Driver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's Signature

Name

NRIC/IN No.

