

Hiap Hong

GBK3471 Y.

TP Chin

Toyota Hiace

Xiao Chun

GDH2011024138

Rear RH Body Panel. Repair	1864.90 +
Rear RH Body Panel Glass Sealant.	50(SN) +
Rear RH Wheel Rim.	250(SN) +
Rear RH Wheel Rim Cover.	150(SN) ✓
Sliding Door RH. Dented	1712.40 ✓
Rear Bumper	651.20 ✓
Rear Bumper Clips.	30(SN) ✓
Rear Bumper Side Holder RH. Cracked	34.90 ✓

2358.50

1788.87

SN: 180

GBK3471Y.

Panel Beating

Spray Painting

Wiring

To remove reverse sensor

To spray tuffcoat

To remove upholstery

To remove fender glass

To transfer sliding door fittings

To perform wheel alignment.

~~1000~~ 500

~~1000~~ 700

~~50~~ 30

~~100~~ 50

~~150~~ 60

~~150~~ 30

120 X

~~150~~ 80

~~150~~ 80

1330

Total: 3508.87

L/S: 2.8K.

04 Days.

2.8K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: