

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

SOH WEI CHONG
BLK 684B EDGEDALE PLAINS #15-637
SINGAPORE 822684

Contact : 97966887

TAX INVOICE

Repair Code : CLM17106

Date in : 02/03/2022

Vehicle Num. : SJJ2228B

Model : HONDA ODYSSEY 2.4 EXV-S CVT SR

Chassis/Eng# : JHMRC1890HC203624/K24W72041271

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR AIRCON COOLING UNIT <i>new</i>	1	876.80	876.80
REAR BUMPER <i>Dehd</i>	1	568.30	✓ 568.30
REAR BUMPER LOWER GARNISH L/R <i>new</i>	2	112.00	224.00
REAR BUMPER REFLECTOR L/R <i>new</i>	2	45.90	91.80
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	19.10	✓ 38.20
REAR END PANEL <i>Dented</i>	1	460.80	✓ 460.80
REAR END PANEL ANTENNA SENSOR <i>changed</i>	1	159.30	✓ 159.30
REAR END PANEL BUZZLE SENSOR	1	80.00	✓ 80.00
REAR END PANEL INNER TOP GARNISH <i>Dehd</i>	1	103.60	✓ 103.60
REAR FENDER INNER TRIM GARNISH L/R <i>Dehd</i>	2	763.60	✓ 1,527.20
REAR FLOOR PANEL <i>Repair</i>	1	1119.00	1,119.00
REAR FLOOR PANEL LOWER JACK BRACKET <i>new</i>	1	198.00	198.00
REAR FLOOR PANEL TRIM CARPET <i>new</i>	1	394.00	394.00
REAR FLOOR PANEL VERTICAL MEMBER <i>Repair</i>	1	210.70	210.70
REAR TAILGATE <i>Distorted</i>	1	1216.80	✓ 1,216.80
REAR TAILGATE 'H' LOGO <i>new</i>	1	26.30	✓ 26.30
REAR TAILGATE INNER PULL GARNISH <i>Dehd</i>	1	28.70	✓ 28.70
REAR TAILGATE INNER TRIM GARNISH <i>changed</i>	1	206.30	✓ 206.30

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

SOH WEI CHONG
BLK 684B EDGEDALE PLAINS #15-637
SINGAPORE 822684

Contact : 97966887

TAX INVOICE

Repair Code : CLM17106

Date in : 02/03/2022

Vehicle Num. : SJJ2228B

Model : HONDA ODYSSEY 2.4 EXV-S CVT SR

Chassis/Eng# : JHMRC1890HC203624/K24W72041271

REAR TAILGATE LOCK	1	185.40	✓	185.40
REAR TAILGATE LOCK STRIKER	1	27.50	✗	27.50
REAR TAILGATE LOCK STRIKER COVER	1	32.00	✓	32.00
REAR TAILGATE LOWER CHROME MOULDING	1	175.50	✓	175.50
REAR TAILGATE REFLECTOR L/R	2	386.20	✓	772.40
REAR TAILGATE RUBBER STOPPER L/R	2	28.00	✗	56.00
REAR TAILGATE SEAL COVER L/R	2	18.00	✗	36.00
REAR TAILGATE WEATHER STRIP	1	117.40	✓	117.40
REAR TAILGATE WINDSCREEN GLASS MOULDING	1	195.00	✓	195.00
REAR TAILLAMP LOWER GARNISH L/R	2	76.80	✓	153.60
Subtotal before discount				9,280.60
Percentage discount 20%				1,856.12
Sub-total 1				7,424.48
REAR BUMPER CLIPS - SET	1	50.00	30	50.00
REAR BUMPER REVERSE SENSOR - SET	1	450.00	200	450.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	30.00	20	30.00
REAR FLOOR PANEL INSULATOR MAT	1	280.00	✗	280.00
REAR NUMBER PLATE	1	25.00	✗	25.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

SOH WEI CHONG
BLK 684B EDGEDALE PLAINS #15-637
SINGAPORE 822684

Contact : 97966887

TAX INVOICE

Repair Code : CLM17106

Date in : 02/03/2022

Vehicle Num. : SJJ2228B

Model : HONDA ODYSSEY 2.4 EXV-S CVT SR

Chassis/Eng# : JHMRC1890HC203624/K24W72041271

REAR NUMBER PLATE HOLDER	1	50.00	50.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET	1	50.00	50.00
REAR TAILGATE LOWER CHROME MOULDING CLIPS - SET	1	30.00	30.00
REAR TAILGATE WINDSCREEN GLASS SEALANT	1	80.00	80.00
REAR TAILLAMP CLIPS L/R - SET	2	20.00	40.00
Subtotal before discount			1,085.00
Percentage discount 0%			0.00
Sub-total 2			1,085.00
Parts-total			8,509.48

LABOUR

To remove, change air con parts, vacuums, refill air con gas.	120.00
To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	60.00
To remove, reinstall tailgate windscreen	120.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	100.00
To remove and reinstall exhaust pipe.	100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1000.00
To apply anti-rust chemical on repaired and replaced panel.	60.00
To remove, reinstall tailgate mechanism and check for function	80.00

Labour Total

3,960.00

Parts & Labour Total

12,469.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from LKK Auto Consultants

*** This is a computer-generated document which requires no signature.***

Adrian Ling
03/03/22
07 Days
H/S.
total: 7567.44
H/S: 61K ✓