

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LING SHU SIE
 15 YISHUN CLOSE #12-32
 SINGAPORE 768011

Contact : 86854667

TP Chiam
 Veron

TAX INVOICE

Repair Code : CLM17105

Date in : 01/03/2022

Vehicle Num. : SMQ9981R

Model : HONDA SHUTTLE 1.5G CVT

Chassis/Eng# : GK81202536/L15B5462909

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT RH DOOR <i>Dented</i>	1	757.20	✓ 757.20
FRONT RH DOOR BLACK TAPE (FRONT) <i>new</i>	1	35.80	✓ 35.80
FRONT RH DOOR BLACK TAPE (REAR) <i>new</i>	1	35.80	✓ 35.80
FRONT RH DOOR CHECKER <i>new</i>	1	48.00	+ 48.00
FRONT RH DOOR GLASS OUTER MOULDING <i>new</i>	1	75.60	+ 75.60
FRONT RH DOOR HINGE (LOWER) <i>new</i>	1	45.00	+ 45.00
FRONT RH DOOR HINGE (TOP) <i>new</i>	1	45.00	+ 45.00
FRONT RH DOOR INNER RUBBER STOPPER L/R <i>new</i>	2	18.50	+ 37.00
FRONT RH DOOR INNER TRIM BOARD <i>new</i>	1	580.00	+ 580.00
FRONT RH DOOR KEY CLINDER <i>new Dented</i>	1	105.00	✓ 105.00
FRONT RH DOOR KEY CLINDER COVER <i>new</i>	1	18.50	✓ 18.50
FRONT RH DOOR LOCK STRIKER <i>new</i>	1	27.50	+ 27.50
FRONT RH DOOR MECHANISM LOCK <i>Dented</i>	1	263.30	✓ 263.30
FRONT RH DOOR OUTER HANDLE <i>new</i>	1	322.70	+ 322.70
FRONT RH DOOR WEATHER STRIP <i>new</i>	1	78.00	+ 78.00
FRONT RH DOOR WEATHER STRIP (LOWER) <i>new</i>	1	60.00	+ 60.00
FRONT RH DOOR WINDOW GLASS <i>new</i>	1	480.00	+ 480.00
REAR AXLE <i>new</i>	1	1080.40	+ 1,080.40

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LING SHU SIE
 15 YISHUN CLOSE #12-32
 SINGAPORE 768011

Contact : 86854667

TAX INVOICE

Repair Code : CLM17105
 Date in : 01/03/2022
 Vehicle Num. : SMQ9981R
 Model : HONDA SHUTTLE 1.5G CVT
 Chassis/Eng#: GK81202536/L15B5462909

REAR BUMPER <i>Regrs</i>	1	1150.20	+	1,150.20
REAR BUMPER RH SIDE RETAINER <i>new</i>	1	23.50	+	23.50
REAR RH DOOR <i>Piston</i>	1	799.50	✓	799.50
REAR RH DOOR BLACK TAPE (FRONT) <i>new</i>	1	35.80	✓	35.80
REAR RH DOOR CHECKER <i>new</i>	1	48.00	+	48.00
REAR RH DOOR GLASS CHANNEL <i>new</i>	1	34.20	+	34.20
REAR RH DOOR GLASS CHANNEL WEATHER STRIP <i>new</i>	1	165.00	✓	165.00
REAR RH DOOR GLASS OUTER MOULDING <i>new</i>	1	85.60	+	85.60
REAR RH DOOR GLASS REGULATOR WITH MOTOR <i>new</i>	1	195.50	✓	195.50
REAR RH DOOR HINGE (BOTTOM) <i>Bent</i>	1	45.00	✓	45.00
REAR RH DOOR HINGE (TOP) <i>Bent</i>	1	45.00	✓	45.00
REAR RH DOOR INNER RUBBER STOPPER L/R <i>new</i>	2	18.50	+	37.00
REAR RH DOOR INNER TRIM BOARD <i>Cracked</i>	1	495.00	✓	495.00
REAR RH DOOR MECHANISM LOCK <i>new</i>	1	210.00	✓	210.00
REAR RH DOOR OUTER FRAME GARNISH <i>new</i>	1	28.80	+	28.80
REAR RH DOOR WEATHER STRIP <i>new</i>	1	78.00	+	78.00
REAR RH DOOR WEATHER STRIP (LOWER) <i>new</i>	1	48.00	+	48.00
REAR RH DOOR WEATHER STRIP (VERTICAL) <i>new</i>	1	65.00	✓	65.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LING SHU SIE
15 YISHUN CLOSE #12-32
SINGAPORE 768011

Contact : 86854667

TAX INVOICE

Repair Code : CLM17105

Date in : 01/03/2022

Vehicle Num. : SMQ9981R

Model : HONDA SHUTTLE 1.5G CVT

Chassis/Eng#: GK81202536/L15B5462909

REAR RH FENDER <i>Regi</i>	1	1010.90	+	1,010.90
REAR RH FENDER GLASS MOULDING <i>Regi</i>	1	45.00	+	45.00
REAR RH WHEEL BEARING <i>Regi</i>	1	321.40	+	321.40
Subtotal before discount				9,061.20
Percentage discount 20%				1,812.24
Sub-total 1				7,248.96
FRONT RH DOOR INNER SOUND INSULATOR MAT <i>Regi</i>	1	400.00	+	400.00
FRONT RH DOOR INNER TRIM BOARD CLIPS - SET <i>Regi</i>	1	50.00	+	50.00
FRONT RH DOOR SUN VERSION - SET <i>Regi</i>	1	350.00	+	350.00
REAR BUMPER CLIPS - SET <i>Regi</i>	1	80.00	+	80.00
REAR RH DOOR INNER SOUND INSULATOR MAT <i>Regi</i>	1	400.00	+	400.00
REAR RH DOOR INNER SPEAKER <i>Regi</i>	1	300.00	+	300.00
REAR RH DOOR INNER TRIM BOARD CLIPS - SET <i>Regi</i>	1	50.00	+	50.00
REAR RH FENDER GLASS SEALANT <i>Regi</i>	1	80.00	+	80.00
REAR RH FENDER INNER SOUND INSULATOR MAT <i>Regi</i>	1	400.00	+	400.00
REAR RH SPORT RIM <i>Regi</i>	1	800.00	+	800.00
REAR RH TYRE 195/50R16 <i>Regi</i>	1	400.00	+	400.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LING SHU SIE
15 YISHUN CLOSE #12-32
SINGAPORE 768011

Contact : 86854667

TAX INVOICE

Repair Code : CLM17105
Date in : 01/03/2022
Vehicle Num. : SMQ9981R
Model : HONDA SHUTTLE 1.5G CVT
Chassis/Eng# : GK81202536/L15B5462909

Subtotal before discount	3,310.00
Percentage discount 0%	0.00
Sub-total 2	3,310.00
Parts-total	10,558.96

LABOUR

- To remove, reinstall fender glass
- To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.
- To road test driving, check and resetting wheel alignments system.
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
- To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

120.00	120.00
80.00	320.00
80.00	100.00
40.00	80.00
160.00	160.00
800.00	1,200.00
600.00	1,200.00
60.00	120.00
3,300.00	3,300.00
13,858.96	13,858.96

*** This is a computer-generated document which requires no signature.***

page 4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Adrian L
4/5 03/03/22.

05 Days.

total: 5692.24

4/8: 4.5K ✓