

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
--	---

Attn: Nor Azian Binte Noordin

Date: 15 Jun 2022

Preliminary Advice

Insured	: FBH6825G		
Vehicle No			
TP Vehicle No	: GBL6137M	Accident Date	: 22/02/2022
Make	: NISSAN NV350 CARAVAN	Assignment Date	: 03/03/2022
Date of Inspection	: 17/05/2022	Est. Duration of Repair	: 2
Inspection At	: CHENG HOE MOTOR PTE LTD (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,172.47
Revised Amount	:S\$	1,280.31
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,280.31

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	60,000.00

COE / PARF Rebate	:S\$ 21,619.00
Salvage Value	:S\$
Margin for Repair	:S\$ 38,381.00

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items)
stated are subject to consistency check, part prices and labour cost.