



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22002015/Aqy3m4 Date: 25/01/2023 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHB 5105T	Veh. Inspected	SMT 3267T	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/02/22/2077	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	03/03/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA SIENTA	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	NHP1707100808	Colour	BLUE	
Odometer	106651 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/50 R16	YOKOHAMA	6 mm	
L/H Front Tyre	195/50 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	195/50 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	195/50 R16	YOKOHAMA	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	26/02/2022	Inspection Date	04/03/2022	
Survey held at	ACE AUTOLUTION PTE LTD 13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ CENTRE SINGAPORE 417807			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	