



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

TP SMT.

Xiao Chen.

Page No. 1

Vehicle No. SMT3267T TOYOTA SIENTA

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	REAR TAILGATE <i>Distorted.</i>		1020.50	✓
2	REAR TAILGATE DAMPER LH & RH @\$300.00 <i>Abn nu</i>		600.00	+
1	REAR TAILGATE LOGO <i>Neu</i>		80.00	✓
1	REAR TAILGATE EMBLEM <i>Neu</i>		75.00	✓
2	REAR TAILGATE LAMP LH & RH @\$355.20 <i>Rt ut</i>		710.40	355.20.
1	REAR TAILGATE LOCK <i>Damaged.</i>		235.60	✓
2	REAR TAILGATE STOPPER LH & RH @\$94.40 <i>Neu</i>		188.80	X.
1	REAR TAILGATE WEATHERSTRIP <i>At</i>		215.00	✓
1	REAR TAILGATE WIPER MOTOR <i>Neu</i>		266.40	X.
1	REAR TAILGATE INNER HANDLE HOLDER <i>Dehd.</i>		78.00	✓
1	REAR BUMPER <i>Dehd.</i>		938.80	678
2	REAR BUMPER SIDE RETAINER LH & RH @\$75.00 <i>Neu</i>		150.00	80.
2	REAR BUMPER SIDE GARNISH LH & RH @\$128.50 <i>Rt ut</i>		257.00	128.50
1	REAR BUMPER CENTRE GARNISH <i>At</i>		438.50	225
1	REAR BUMPER ANTENNA KEYLESS <i>Orked.</i>		155.00	✓
1	REAR END PANEL (INNER) <i>Dented</i>		398.00	✓
1	REAR END PANEL (OUTER) <i>Dented.</i>		287.70	✓
1	REAR END PANEL TOP GARNISH <i>Dehd</i>		166.00	✓
2	REAR TAILLAMP LH & RH @\$688.50 <i>Rt ut</i>		1377.00	450.
2	REAR TAILLAMP PANEL LH & RH @\$339.20 <i>Rt ut</i>		678.40	X.
1	REAR WINDSCREEN MOULDING <i>Neu</i>		321.00	188.
2	REAR FENDER LH & RH @\$1020.00 <i>Rt ut</i>		2040.00	X.
2	REAR FENDER INNER TRIM LH & RH @\$342.10 <i>Dehd</i>		684.20	✓
1	REAR FLOOR PANEL <i>Rt ut</i>		912.00	X.
1	REAR FLOOR PANEL BOARD <i>Dehd</i>		889.00	348.
			less	
			25%	25%
			13162.30	
			3290.58	
			9871.73	
SPECIAL NETT ITEMS				
1 SET	REAR BUMPER CLIPS <i>Neu</i>		100.00	30
1	REAR END PANEL SEALANT <i>Neu</i>		450.00	60
1 SET	REAR CAR PLATE WITH COVER <i>Neu</i>		550.00	X.
1	REAR BODY SEALANT <i>Neu</i>		100.00	X.
1	REAR BUMPER LOWER LID <i>Dehd</i>		650.00	680.
			890.	
			Reverse Sensor <i>300.</i>	
			Total Parts	
			11721.73	

Dmgd

200



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

Page No. 2

Vehicle No. SMT3267T TOYOTA SIENTA

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	OUR ASSESSMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1800.00	1000
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1400.00	1000
3	To remove, fix wiring system at accident damage areas and check for proper function	150.00	30
4	To remove and replace reverse sensor	150.00	50
5	To perform anti-rust treatment on affected areas	120.00	80
6	To remove and refix rear car seat	250.00	X.
7	To remove and refix rear windscreen	150.00	120
8	To conduct water seepage test	120.00	X.
	Labour Total :	4140.00	
	TOTAL (PARTS & LABOUR):	15861.73	

total 7541.52

L/S: GK

07 Days

GK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: