

SMC 9657B. 2018 July.
 TP Chim Kia Sorento 2199cc
 Xiao Tony KNAPH81BMJS465517

Rear Number Plate	30(SN) x
Rear Number Plate Holder	30(SN) x
Rear Bumper Distorted	605.90 ✓
Rear Bumper Low Cover, Behind	24.10 ✓
Rear Bumper Clips.	50(SN) 30(SN) 3040.
Rear Bumper Side Holder x 02 RH	304 x 2 = 60.80 125.50
Rear Bumper Reflector x 02 RH and	129.9 x 2 = 259.80
Rear Bumper Reflector Grille x 02 RH and	68 x 2 = 136.68
Rear Bumper Lower Garnish (Black)	565.40 ✓
Rear Bumper Lower Diffuser (Grey)	Distorted 194.20 ✓
Rear Bumper Reinforcement Dented	359.40 ✓
Reverse Sensor x 04 2 pieces Dented	410 205 x 4 = 820
Reverse Sensor Holder x 04. New	18 x 4 = 72 ✓
Reverse Sensor Wire Harness. New	358.40 x
Rear End Panel Dented	681.50 ✓
Rear End Panel Top Garnish. Cracked	188.30 ✓

SMC9657B.

Rear End Panel Top-Garnish Clips ^{Nec} 20(SN) ✓

Rear End Panel Sealant ^{Nec} 60(SN) ✓

Taillamp x 02 ^{RH curved, LH ut} 751 x 2 = 1502 ✓

Taillamp Panel RH ^{Regis} 294.10 +

Tailgate ^{Distorted} 1445.50 ✓

Tailgate Lock ^{Dmgd} 652.40 ✓

Tailgate Weatherstripe ^{ut} 185.40 ✓

Tailgate Reflector x 02 ^{RH curved, LH ut} 493.1 x 2 = 986.20 ✓

Tailgate Auto Damper x 02 ^{x 4 ut} 874 x 2 = 1748 ✓

Tailgate Inner Trim Board ^{ut} 425.80 ✓

Tailgate Inner Trim Board Clips. ^{per} 30(SN) ✓

Tailgate Glass ^{Shattered} 894.90 ✓

Tailgate Glass Moulding ^{Nec} 135.90 ✓

Tailgate Glass Sealant ^{Nec} 60(SN) ✓

Tailgate Glass Solar Film. ^{Nec} 200(SN) ✓

Tailgate Wiper Motor ^{Dmgd} 280(SN) ✓

Tailgate Wiper Arm. ^{curled} 398.40 ✓

98.50 ✓

SMC 9657B.

Tailgate Inner Side Trim x 02	¹⁴ m	201 x 2 = 402	X
Rear Video Recorder.	Missing	480(SN)	380(SN)
Kia Logo	} Mer	69.20	✓
Sorento Wording.		38.40	✓
Cycle and Carriage Logo		35.90	✓
Eco Dynamic Emblem.		42.90	✓
Floor Panel Top Board	M m	345.80	X
Utility Tools Box.	Quilted	324.90	✓
Rear Exhaust Pipe.	Bent	1177.10.	✓
Rear Exhaust Pipe Mounting	16 M	35.40	X
Rear Exhaust Pipe Gasket.	m	30.40	✓
Rear Fender Inner Trim Board x 02	¹⁴ m	552 x 2 = 1104	X
Rear Fender Inner Trim clips.	¹⁴ m	60(SN)	X

11772.90

10595.61

9475.52

S.N: 780

SMC9657B.

Panel Beating,

Spray Painting,

Wiring,

To remove reverse sensor

To spray tuff coat

To remove upholstery.

To transfer tailgate fittings.

To replace tailgate g/l's

To replace video recorder

To remove exhaust pipe.

To vacuum and clean up glass splinters.

~~1200~~ 900

~~1200~~ 800

~~50~~ 30

~~100~~ 60

~~150~~ 60

~~150~~ 60

~~150~~ 60

~~180~~ 120

~~100~~ 50

~~150~~ 80

~~150~~ 60

2280

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 13655.61.

W/S 10.9K.

07 Days

10.9K