

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0150/2022/JT  
**DATE** : 1-Mar-22  
**WIP** : 13725

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 3/3/22**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

**OWNER'S NAME** : MS CAROLYN JOYCE TIEMANN  
**ADDRESS** : 19 TAMAN SERASI  
#09-25  
SINGAPORE 257723  
**TELEPHONE** : HP +65 98249252  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 7210046972  
**VEHICLE NO** : **SMZ 7820 M**  
**MODEL CODE** : AUDI Q3 1.4 TFSI S TRONIC  
**MODEL YEAR** : 18/5/2021  
**ENGINE NO** : CZD C39824  
**CHASSIS NO** : WAUZZZF31M1117022  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 28-Feb-22  
**PLACE OF ACCIDENT** : PEOPLE'S PARK COMPLEX  
PARKING LOT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 7820 M**

| S/N                             | NATURE OF JOBS                                                                                                                                                               | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|---------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|-------------------------------|
| 1                               | TO REMOVE AND RENEW REAR PARKING AID AND REAR LID KICK SENSOR.                                                                                                               | S/N \$ 360.00        | ✓ ✓                           |
| 2                               | TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.                                                                      | S/N \$ 400.00        | 280 ✓                         |
| 3                               | TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY. | S/N \$ 1,400.00      | ✗                             |
| 4                               | TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.                  | S/N \$ 1,400.00      | ✗                             |
| 5                               | TO REMOVE AND RENEW LHS 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER.                                                                                                  | S/N \$ 300.00        | ✗                             |
| <b>SUB TOTAL LABOUR CHARGES</b> |                                                                                                                                                                              | <b>: \$ 3,860.00</b> |                               |

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 7820 M**

| S/N                         | NATURE OF JOBS                                                                                                                                                                      | ESTIMATED CHARGES          | SURVEYOR'S RECOMMENDATIONS                                                                             |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------|--------------------------------------------------------------------------------------------------------|
| 6                           | TO INSTALL SOLAR FILM FOR LHS 1/4 GLASS.                                                                                                                                            | S/N \$ 400.00              | +                                                                                                      |
| 7                           | TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO CUT OUT AND WELD REAR FENDER AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ <del>8,800.00</del>     | 1500 ✓                                                                                                 |
| 8                           | TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, DOOR HANDLE, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE AND REAR END PANELLING.                             | S/N \$ <del>7,000.00</del> | $  \begin{array}{r}  3 \times 550 = 1650 \\  1 \text{ handle} = 100 \\  \hline  1750  \end{array}  $ ✓ |
| 9                           | TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.                                                                                                                                | S/N \$ 280.00              | ✓ ✓                                                                                                    |
| 10                          | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                                                      | S/N \$ 192.00              | ✓ ✓                                                                                                    |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                     | <b>: \$ 20,532.00</b>      |                                                                                                        |

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 7820 M**

|                              |                                                           |     | DAMAGED PARTS & PRICES |           |
|------------------------------|-----------------------------------------------------------|-----|------------------------|-----------|
| S/N                          | PARTS DESCRIPTION                                         | QTY | S/NETT                 | REMARKS   |
| 1                            | REAR BUMPER <i>Repair</i>                                 | 1   | \$ 1,738.00            | +         |
| 2                            | REAR BUMPER FIXING PARTS <i>new</i>                       | 1   | \$ 220.00              | +         |
| 3                            | REAR BUMPER SPOILER <i>new</i>                            | 1   | \$ 510.00              | ✓ 408     |
| 4                            | REAR BUMPER BRACKET <i>new</i>                            | 1   | \$ 53.00               | +         |
| 5                            | REAR LIGHT REFLECTOR - LH <i>new</i>                      | 1   | \$ 46.00               | +         |
| 6                            | REAR BUMPER GUIDE SECTION - LH <i>new</i>                 | 1   | \$ 71.00               | +         |
| 7                            | REAR WHEEL ARCH COVER - LH / RH <i>LH missing, RH new</i> | 2   | \$ 566.00              | ✓ 452     |
| 8                            | REAR FENDER - LH <i>Repair</i>                            | 1   | \$ 3,640.00            | +         |
| 9                            | QUARTER WINDOW - LH <i>new</i>                            | 1   | \$ 683.00              | +         |
| 10                           | PRIMER <i>new</i>                                         | 1   | \$ 22.00               | +         |
| 11                           | REAR END PANEL                                            | 1   | \$ 329.00              | +         |
| 12                           | REAR WHEEL HOUSING LINER <i>new</i>                       | 1   | \$ 262.00              | +         |
| 13                           | REAR WHEEL SPOILER - LH <i>new</i>                        | 1   | \$ 44.00               | +         |
| 14                           | REAR DOOR - LH <i>Distorted</i>                           | 1   | \$ 3,127.00            | ✓ 2501.60 |
| 15                           | REAR DOOR OUTER SEAL - LH <i>new</i>                      | 1   | \$ 151.00              | ✓ 120.40  |
| 16                           | REAR DOOR CATCH - LH <i>? damaged</i>                     | 1   | \$ 120.00              | ? 96      |
| 17                           | REAR SILL PANEL SEAL - LH <i>new</i>                      | 1   | \$ 151.00              | +         |
| 18                           | REAR DOOR COVER - LH <i>new</i>                           | 1   | \$ 270.00              | ✓ 216     |
| 19                           | REAR DOOR HANDLE - LH <i>Repair</i>                       | 1   | \$ 222.00              | +         |
| 20                           | REAR DOOR HOUSING - LH <i>new</i>                         | 1   | \$ 31.00               | +         |
| <b>SUB TOTAL SPARE PARTS</b> |                                                           | :   | <b>\$ 12,256.00</b>    |           |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 7820 M**

|                             |                                             |     | DAMAGED PARTS & PRICES |           |
|-----------------------------|---------------------------------------------|-----|------------------------|-----------|
| S/N                         | PARTS DESCRIPTION                           | QTY | S/NETT                 | REMARKS   |
| 21                          | REAR DOOR WINDOW REGULATOR - LH <i>from</i> | 1   | \$ 302.00              | +         |
| 22                          | REAR DOOR WINDOW MOTOR - LH                 | 1   | \$ 299.00              | +         |
| 23                          | ALUMINIUM RIM <i>cut</i>                    | 1   | \$ 1,414.00            | ✓ 1131.20 |
| 24                          | RUBBER VALVE <i>new</i>                     | 4   | \$ 15.00               | X         |
| 25                          | 1/4 GLASS SEALANT                           | S/N | \$ 100.00              | +         |
| 26                          | STONE CHIP                                  | S/N | \$ 180.00              | +         |
| 27                          | METAL FILLER POWDER <i>new</i>              | S/N | \$ 280.00              | +         |
| 28                          | ARYLIC SEALANT                              | S/N | \$ 180.00              | +         |
| 29                          | CAVITY WAX                                  | S/N | \$ 140.00              | +         |
| 30                          | SUNDRIES <i>?</i> nec                       |     | \$ 400.00              | ? 12      |
| <b>TOTAL SPARE PARTS</b>    |                                             | :   | <b>\$ 15,566.00</b>    |           |
| <b>TOTAL LABOUR CHARGES</b> |                                             | :   | <b>\$ 20,532.00</b>    |           |
| <b>GRAND TOTAL</b>          |                                             | :   | <b>\$ 36,098.00</b>    |           |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian Lj  
03/03/22

Not Authorised, 06 Days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT