

## Case Details

Case Reference Number : TAX/03/22/2005  
Type of Repair : Accident Repair  
Vehicle Registration Number : SHB5913C

Company Type : Strides Taxi Pte Ltd  
Estimation ID : EST-17626-ID  
Assigned By : Tan Lee Ge #

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd  
Accident Date and Time : 01/03/2022 01:30 AM  
Vehicle Age(In Months) : -

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

| BOM Type | Costing Type | Portion | Material Number | SMRT Recommendation          |     |                         |                |        |                 |                 | Surveyor Approval |                          |                | Remarks |
|----------|--------------|---------|-----------------|------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|---------|
|          |              |         |                 | Part Name                    | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace |         |
| Standard | Main         |         |                 | COVER, RR BUMPER ASSY        | 1   | 332.70                  | 332.70         | 25.00  | 249.52          | Replace         | 0                 | 0                        | Not Give       | X11     |
| Standard | Main         |         |                 | COVER, RR BUMPER ASSY        | 1   | 485.60                  | 485.60         | 25.00  | 364.20          | Replace         | 1                 | 364.20                   | Replace        | de      |
| Standard | Main         |         |                 | PAD, RR BUMPER, RH & LH, 3   | 2   | 11.00                   | 22.00          | 25.00  | 16.50           | Replace         | 2                 | 16.50                    | Replace        | we      |
| Standard | Main         |         |                 | PAD, RR BUMPER, RH & LH, 2   | 2   | 4.00                    | 8.00           | 25.00  | 6.00            | Replace         | 2                 | 6.00                     | Replace        | rec     |
| Standard | Main         |         |                 | PAD, RR BUMPER, RH & LH, 1   | 2   | 4.00                    | 8.00           | 100.00 | 0.00            | Replace         | 2                 | 0.00                     | Replace        | we      |
| Standard | Main         |         |                 | PAD, RR BUMPER, CTR          | 3   | 11.00                   | 33.00          | 25.00  | 24.75           | Replace         | 3                 | 24.75                    | Replace        | we      |
| Standard | Main         |         |                 | SEAL, RR BUMPER ARM, RH & LH | 2   | 11.30                   | 22.60          | 25.00  | 16.95           | Replace         | 2                 | 16.95                    | Replace        | we      |
| Standard | Main         |         |                 | STOPPER, RR BUMPER, RH & LH  | 1   | 4.50                    | 4.50           | 25.00  | 3.38            | Replace         | 0                 | 0                        | Not Give       | X11     |
| Standard | Main         |         |                 | RETAINER, RR BUMPER, RH      | 1   | 132.60                  | 132.60         | 25.00  | 99.45           | Replace         | 0                 | 0                        | Not Give       | X11     |
| Standard | Main         |         |                 | RETAINER, RR BUMPER, LH      | 1   | 132.60                  | 132.60         | 25.00  | 99.45           | Replace         | 0                 | 0                        | Not Give       | X11     |
| Standard | Main         |         |                 | SEAL, RR BUMPER, RH          | 1   | 118.30                  | 118.30         | 25.00  | 88.73           | Replace         | 0                 | 0                        | Not Give       | X11     |
| Standard | Main         |         |                 | SEAL, RR BUMPER, LH          | 1   | 118.30                  | 118.30         | 25.00  | 88.73           | Replace         | 0                 | 0                        | Not Give       | X11     |

Total Spare Part Cost 2,356.07

Surveyor Total 743.03

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 2,356.07

Final Sur Total 743.03

| SMRT Recommendation   |              |         |                 |                                                    |     |                         |                |        |                 | Surveyor Approval |                   |                          |                |         |
|-----------------------|--------------|---------|-----------------|----------------------------------------------------|-----|-------------------------|----------------|--------|-----------------|-------------------|-------------------|--------------------------|----------------|---------|
| BOM Type              | Costing Type | Portion | Material Number | Part Name                                          | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace   | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| Standard              | Main         |         |                 | CLIPS<br>PIECE, FRT<br>& RR<br>BUMPER              | 10  | 4.50                    | 45.00          | 25.00  | 33.75           | Replace           | 10                | 33.75                    | Replace ▾      | nee     |
| Standard              | Main         |         |                 | GUARD, RR<br>BUMPER,<br>LOWER                      | 1   | 374.50                  | 374.50         | 25.00  | 280.88          | Replace           | 1                 | 280.88                   | Replace ▾      | see     |
| Standard              | Main         |         |                 | COVER,<br>GUARD RR<br>BUMPER<br>LOWER              | 1   | 22.00                   | 22.00          | 25.00  | 16.50           | Replace           | 0                 | 0                        | Not Give ▾     | Xan     |
| Standard              | Main         |         |                 | REAR<br>BUMPER<br>REFLECTOR<br>ASSY,<br>REFLEX, RH | 1   | 39.00                   | 39.00          | 25.00  | 29.25           | Replace           | 0                 | 0                        | Not Give ▾     | Xan     |
| Standard              | Main         |         |                 | REAR<br>BUMPER<br>REFLECTOR<br>ASSY,<br>REFLEX, LH | 1   | 39.00                   | 39.00          | 25.00  | 29.25           | Replace           | 0                 | 0                        | Not Give ▾     | Xan     |
| Standard              | Main         |         |                 | REAR<br>BUMPER<br>GROMMET<br>SCREW                 | 2   | 2.20                    | 4.40           | 25.00  | 3.30            | Replace           | 0                 | 0                        | Not Give ▾     | Xan     |
| Standard              | Main         |         |                 | COVER,<br>REAR<br>FLOOR<br>UNDER<br>CENTER         | 1   | 229.90                  | 229.90         | 25.00  | 172.43          | Replace           | 0                 | 0                        | Not Give ▾     | Xan     |
| Standard              | Main         |         |                 | SENSOR<br>REVERSE                                  | 1   | 180.00                  | 180.00         | 0.00   | 180.00          | Replace           | 0                 | 0                        | Check ▾        | ?       |
| Standard              | Main         |         |                 | ANTENNA,<br>ELECTRICAL<br>KEY                      | 1   | 72.00                   | 72.00          | 10.00  | 64.80           | Replace           | 0                 | 0                        | Not Give ▾     | Xan     |
| Standard              | Main         |         |                 | END PANEL<br>SUB-ASSY,<br>BODY<br>LOWER<br>BACK    | 1   | 651.00                  | 651.00         | 25.00  | 488.25          | Replace           | 0                 | 0                        | Not Give ▾     | Xan     |
| Total Spare Part Cost |              |         |                 |                                                    |     |                         |                |        | 2,356.07        | Surveyor Total    |                   | 743.03                   |                |         |
| Lump Sum Discount (%) |              |         |                 |                                                    |     |                         |                |        | 0.00            | Lump Sum Dis (%)  |                   | 0                        |                |         |
| Final Spare Part Cost |              |         |                 |                                                    |     |                         |                |        | 2,356.07        | Final Sur Total   |                   | 743.03                   |                |         |

Labour's Cost Detail

| S.No.  | Costing Type | Job Scope              | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO REPAIR REAR PORTION | 676.00                  | 200                     |         |
| Total: |              |                        | 676.00                  | 200.00                  |         |

Spray Cost Detail

| S.No. | Costing Type | Job Scope              | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|-------|--------------|------------------------|-------------------------|-------------------------|---------|
| 1     | Main         | TO RESPRAY REAR BUMPER | 378.00                  | 200                     |         |

Total:

| S.No.  | Costing Type | Job Scope             | SMRT<br>Recommendation(\$) | Surveyor<br>Adjustment(\$) | Remarks |
|--------|--------------|-----------------------|----------------------------|----------------------------|---------|
| 2      | Main         | TO RESPRAY REAR PANEL | 180.00                     | 0 <i>X11</i>               |         |
| Total: |              |                       | 558.00                     | 200.00                     |         |

**Other Cost Detail**

| S.No.  | Costing Type | Job Scope                                  | SMRT<br>Recommendation(\$) | Surveyor<br>Adjustment(\$) | Remarks |
|--------|--------------|--------------------------------------------|----------------------------|----------------------------|---------|
| 1      | Main         | TO WASH AND VACUUM                         | 60.00                      | 0 <i>X11</i>               |         |
| 2      | Main         | TO APPLY RUST-PROOFING ON<br>AFFECTED AREA | 100.00                     | 0 <i>X11</i>               |         |
| 3      | Main         | TO REPLACE SUNDRY PARTS                    | 100.00                     | 0 <i>X11</i>               |         |
| 4      | Main         | TO TEST AND REFIX REVERSE<br>SENSOR SYSTEM | 120.00                     | 40                         |         |
| Total: |              |                                            | 380.00                     | 40.00                      |         |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Summary**

|                          | Estimator Assesment(\$)  | Surveyor Assesment(\$)                        |
|--------------------------|--------------------------|-----------------------------------------------|
| Total Spare Part Detail  | 2,356.07                 | 743.03                                        |
| Total Labour Cost        | 676.00                   | 200.00                                        |
| Total Spray Painting     | 558.00                   | 200.00                                        |
| Other                    | 380.00                   | 40.00                                         |
| Overall Total            | 3,970.07                 | 1,183.03                                      |
| Lump Sum Repair Option   | <input type="checkbox"/> | <input type="checkbox"/>                      |
| Lump Sum Total           | 0.00                     | 1,183.03                                      |
| Surveyor Approved Amount |                          | 1,183.03                                      |
| No of Repair Days*       | 4                        | 2                                             |
| Remarks                  | -                        | PART BY PART REPAIR / RESURVEY BEFORE PAINT . |
| Surveyor Name            |                          | Rasul                                         |

Signature



Save

Clear

Survey Date

03/03/2022