



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300819

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 13/02/2023  
Reference CC3/CTI22002020/Vpa3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SHD 6653K  
Insured Veh. SKA 8243C  
Claim No. SNM22D201064/C02  
Policy No. DMPCSNW00064242100  
Accident Date 10/02/2022  
Inspection Date 10/02/2022

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (8%)</b>	<b>32.00</b>
<b>Grand Total</b>	<b>432.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI22002020/Vpa3q2 Date: 13/02/2023 Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKA 8243C	Veh. Inspected	SHD 6653K	
Policy No.	DMPCSNW00064242100	Coverage (\$)	0.00	
Claim No.	SNM22D201064/C02	Excess (\$)	0.00	
Assign From		Assign Date	10/02/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES BENZ E220	c.c	2143	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WDD2120012B318536	Colour	WHITE	
Odometer	645610 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MICHELIN	5 mm	
L/H Front Tyre	205/65 R16	MICHELIN	5 mm	
R/H Rear Tyre	205/65 R16	MICHELIN	5 mm	
L/H Rear Tyre	205/65 R16	MICHELIN	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	10/02/2022	Inspection Date	10/02/2022	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6653K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DENTED	1,510.00	1,510.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	1,150.00	-
2	REAR BUMPER RETAINER MOUNTING LH/RH @\$115.00	NECESSARY	230.00	230.00
2	REAR BUMPER BRACKET LH/RH @\$135.00	NECESSARY	270.00	270.00
1	REAR BUMPER LOWER COVER	SCRATCHED	325.00	325.00
1	REAR BUMPER TOWING COVER	SERVICEABLE	175.00	-
1	TAIL LAMP LH	SERVICEABLE	1,280.00	-
1	BOOT LAMP LH	SERVICEABLE	655.00	-
	LESS 20% DISCOUNT		-1,119.00	-467.00
			4,476.00	1,868.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER SENSOR (SN)	CUT	388.00	388.00
			438.00	438.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		760.00	400.00
	SPRAY PAINTING CHARGE.		600.00	250.00
	REMOVE/REFIX REVERSE SENSOR .		90.00	20.00
	CHECK WIRING.		60.00	20.00
			1,510.00	690.00
	<b>GRAND TOTAL</b>		<b>6,424.00</b>	<b>2,996.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,400.00</b>

Report Ref No. CC3/CTI22002020/Vpa3q2

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SHD 6653K

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SHD 6653K**

**RE-INSPECTION**

