Our Job Ref No : 305504662  Date : 17/02/22		ENGINEERING  ComfortDelGro Engineering Pte Lte
		59 Loyang Drive Singapore 50896 Fax: 6546 8156
FINA	ALIZATION FORM	_
To	LKK	Fax :
Attn	THEARN	
Vehic	icle Reg No. : SHD6653K	10/02/22
The :	survey and estimates of the repairs of the ab	bove-mentioned vehicle are as follows:-
Z	The repair job shall bill to:	CHINA SKA8243C
2.	The finalized amount shall be:	
	(a) Spare Parts after List discount	
	(b) Labour Charges	-
	Total for Part-By-Part Repair Cos	<u> </u>
	(c.) Lumpsum Repair (if applicable)  Total for Lumpsum repair cost after  Final Lumpsum Repair cost	r Less: \$2,400.00
3.	Estimated normal period for repairs:	working days.
4.	We shall treat the above amount as Corworking days	rrect and Confirmed if there is no reply from you within 7
5.	Thank you for your assistance.	We confirm the estimates and finalized amount
	Signature :	Signature :
	Name : CHIANG	Name : TWJ44
	Tel : 62148314	Date : \(\lambda \lambda \rangle 3 \rangle 2 \rangle \)
		7

ltem	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
Rental Rate P/Day		YES		
Loss of Income Paid	-	N		
3. Survey Fees	2	-		
4. LTA Search Fee	\$7.49/\$2.00			
<ol><li>Medical Fees (on behalf of driver, if applicable)</li></ol>				
6 Overrun			L	

Remarks:			

## COMFORTDELGRO ENGINEERING PTE LTD

## **REPAIR ESTIMATE\***

**VEHICLE NO** 

SHD6653K

MAKE :

DATE 10/02/22 09:05 AM

CHIANG/CHINA

			CHIANG/CHINA	
DEL	MERC E5			
Qty	Parts Description/ Labour	Туре	Unit Price	Amount
	1 REAR BUMPER			\$1,510.00
	1 REAR BUMPER REINFORCEMENT		4	\$1,150.00
	2 REAR BUMPER RETAINER MOUNTING LH/RH		\$115.00	\$230.00,
	2 REAR BUMPER BRACKET LH/RH		\$135.00	\$270.00
	1 REAR BUMPER LOWER COVER			\$325.00
	1 REAR BUMPER TOWING COVER			\$175.00
	1 TAIL LAMP LH			\$1,280.00
	1 BOOT LAMP LH			\$655.00
	SUB TOTAL			\$5,595.00
	LESS 20%			\$1,119.00
	1			\$4,476.00
	1 REAR BUMPER MAT			\$50.00/
	1REAR BUMPER SENSOR			\$388.00
				\$438.00
				Ş438.00
	Lahaun Chausa			
	Labour Charge			
	Panel Beating			\$760.00
	Spray Painting Charge			\$600.00
	Remove/Refix Reverse Sensor			\$90.00
	Check Wiring TOTAL LABOUR			\$60.00
	TOTAL LABOUR			\$1,510.00
	ESTIMATE TOTAL			\$6,424.00
	Thur 82235769	LKK	Auto Consultants hence n	
	10/2/22 1648 US bett after repair phoso 2 days wp			
	10126 1013	• To dis	play damaged part(a) during	
	US bett after main no			
	/ //wito		party survey is on a "Without Pi gal modification(s) is allowed	ejudice" basis
	2 days wp	Suppl	smentary item(s) is allowed	1
	3 1		a approval from insura	nce Company
		Acknowl	edged by Repairer	
		Signatur Cate:	e:	
	This is an initial estimate based on a visual inspection of the	above ve	hicle. The final renair o	uantum will
	be prepared after the vehicle is surveyed by a motor Survey	or annoi-	tod by the income	adiituili Will