

REF: *AG/22002021/kp*

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKK9039S
Accident Date : 28-Feb-2022

Our Ref : 022037 (AIG) / CHAN

HO ANN SING
BLK 526 SERANGOON NORTH AVE 4
#14-116
Singapore 550526

Not Withheld
Repairing After Paint
11 Lys 8400d
5 days

No. : 06545

Date : 01-Mar-2022

PAGE : 1

ESTIMATED COST OF REPAIR FOR TOYOTA HARRIER 2.0 ELEGANCE SGD6886S

1 pc Tail gate	<i>My</i> 1,369.50	—
1 pc Tail gate inner lock	<i>My</i> 571.10	—
1 pc Tail gate rubber <i>341.60</i>	<i>Od/My</i> 410.40	—
2 pcs Tail gate glass moulding (side @ S\$ 30.50	<i>My</i> 61.00	—
1 pc Tail gate glass moulding (Low)	<i>My</i> 50.70	—
1 pc Tail gate "HARRIER" emblem	<i>My</i> 62.20	—
1 pc Rear bumper fascia <i>1381.</i>	<i>My</i> 1,395.10	—
1 pc Rear bumper lower spoiler	<i>Od/My</i> 586.30	—
1 pc Rear bumper sponge	<i>CM</i> 142.40	—
2 pcs Rear bumper spoiler reflector @ S\$ 54.50	<i>My</i> 109.00	✓
1 pc Rear end panel	<i>R</i> 715.50	✓
1 pc End panel top garnish	<i>My</i> 425.40	✓

5,898.60

Less 25% : 1,474.65

- 1 pc Rear bumper reverse sensor(set)
- 1 pc Rear bumper clip (set)
- 1 pc Rear w/s glass selant

Short 4,423.95 *200sn*
300.00 *sn 7*
My 40.00 *sn*
My 60.00 *sn*

To remove & refix rear windscreen glass and conduct water leak test.

120l
150.00

To remove roof lining, front and rear seats, trim board and carpet

120.00 *60l*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Con't Page 2 ...

REF:

AG/22002021/kp

ASSIGNMENT

Aspire 3

DDR4

Faster



Precision touchpad



802.11ac

Faster

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKK9039S

Page : 2

To apply undersealing

60.00 300

To putty and spray replaced parts

600/700.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

700.00 300

Total : S\$ 6,553.95

Singapore Dollars Six Thousand Five Hundred and
Fifty Three and Cents Ninety Five Only