

11/1/17

REPAIR ESTIMATE

Vehicle No. : SHA7994K

Mako : HYUNDAI

Model : IONIQ(G2)

Date: 10/02/22

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	ANTENNA SMARTKEY			\$40.50
1	REAR BUMPER FOG LAMP			\$201.50
1	LICENCE LAMP			\$85.30
	SUB TOTAL			\$1,654.75
	LESS 20%			\$330.95
	DISCOUNTED TOTAL			\$1,323.80
	REAR FENDER ADVERTISEMENT LOGO RH			\$100.00
	REAR FENDER ADVERTISEMENT LOGO LH			\$100.00
	REAR NUMBER PLATE WITH TRIM COVER		-10%	\$55.00
	REAR BUMPER REVERSE SENSOR		-10%	\$180.00
				\$435.00
	Labour Charge			
	PANEL BEATING			\$400.00
	SPRAY PAINTING CHARGE			\$300.00
	CHECK ALL LIGHTING			\$60.00
	REMOVE/REFIX REVERSE SENSOR			\$80.00
	TOTAL LABOUR			\$840.00
	ESTIMATE TOTAL			\$2,598.80

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Therun 82235769
10/2/22 1630
L/S after repair photo
delays w/p

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No Illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Our Job Ref No : 305504473

Date : 11/02/22

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508089
Fax: 0548 0150

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr Thevan

09/0/2022

Vehicle Reg No. : SHA7994K CTPL

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC FBQ9591M
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges \$0.00
 - Total for Part-By-Part Repair Cost
 - (c.) Lumpsum Repair (if applicable)
 - Total for Lumpsum repair cost after Less: 20% \$1,450.00
 - Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Ms. Loke YY

Tel : 62148355

Fax : 65468156

Signature : 

Name : Thevan

Date : 10/3/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: