

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7994K

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|-------------|------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR BUMPER COVER | CUT | 459.40 | 459.40 |
| 10 | REAR BUMPER CLIPS | NECESSARY | 22.00 | 22.00 |
| 1 | REAR BUMPER CENTRE MOULDING ASSY | SCRATCHED | 451.25 | 451.25 |
| 1 | REAR BUMPER REINFORCEMENT | SERVICEABLE | 394.80 | - |
| 1 | ANTENNA SMARTKEY | SERVICEABLE | 40.50 | - |
| 1 | REAR BUMPER FOG LAMP | SERVICEABLE | 201.50 | - |
| 1 | LICENCE LAMP | SERVICEABLE | 85.30 | - |
| | LESS 20% DISCOUNT | | -330.95 | -186.53 |
| | | | 1,323.80 | 746.12 |
| | NETT ITEMS | | | |
| 1 | REAR NUMBER PLATE WITH TRIM COVER (N) | BENT | 55.00 | 55.00 |
| 1 | REAR BUMPER REVERSE SENSOR (N) | CUT | 180.00 | 180.00 |
| | LESS 10% DISCOUNT | | - | -23.50 |
| | | | 235.00 | 211.50 |
| | SPECIAL NETT ITEMS | | | |
| 1 | REAR FENDER ADVERTISEMENT LOGO RH (SN) | NECESSARY | 100.00 | 100.00 |
| 1 | REAR FENDER ADVERTISEMENT LOGO LH (SN) | NECESSARY | 100.00 | 100.00 |
| | | | 200.00 | 200.00 |
| | LABOUR | | | |
| | PANEL BEATING. | | 400.00 | 350.00 |
| | SPRAY PAINTING CHARGE. | | 300.00 | |
| | CHECK ALL LIGHTING. | | 60.00 | 20.00 |
| | REMOVE/REFIX REVERSE SENSOR. | | 80.00 | |
| | | | 840.00 | 640.00 |
| | GRAND TOTAL | | 2,598.80 | 1,797.62 |





Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 1,450.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | | · |
| (CONFIRMED) | | |

Report Ref No. NS/INC22002022/Vtcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser