

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 07 Mar 2022

Preliminary Advice

Vehicle No : SMM7507L Accident Date : 26/02/2022
Make : HYUNDAI AVANTE Policy No. :
DMPCSNW00124862101
Assignment Date : 03/03/2022 Excess : S\$500.00
Date of Inspection : 04/03/2022 Est. Duration of Repair : 11
Inspection At : HUA MENG SPRAY PAINTING WORKSHOP (HQ)
NO 1 KAKI BUKIT AVENUE 6, #01-61 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,143.64
Revised Amount	:S\$	17,067.96
Check Items (Estimated)	:S\$	5,553.92
Total	:S\$	22,621.88

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	75,000.00
COE / PARF Rebate	:S\$	31,950.00

Salvage Value	:S\$
Margin for Repair	:S\$ 43,050.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.