

48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2203-120 TG
DATE : 3-Mar-2022
POLICY NO. : P10616316R00
VEHICLE REG. NO. : SLE110Y
VEHICLE MAKE : KIA STONIC 1.0 DCT

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Front Bumper	1	\$ 550.00	\$ 550.00
X 2	Front Bumper Clips	10	\$ 5.00	\$ 50.00
X 3	Front Bumper Retainer RH	1	\$ 25.00	\$ 25.00
X 4	Front Bumper Retainer LH	1	\$ 25.00	\$ 25.00
INV 5	Front Lower Bumper - 86512H8400	1	\$ 450.00	\$ 450.00
INV 6	Front Lower Bumper Clips	10	\$ 5.00	\$ 50.00
INV 7	Front Bumper Lower Skid Plate - 86565H8400	1	\$ 80.00	\$ 80.00
X 8	Front Bumper Upper Rubber Strip - 86570H8400	1	\$ 35.00	\$ 35.00
X 9	Front Reinforcement	1	\$ 590.00	\$ 590.00
X 10	Front Reinforcement Stiffener - 86571H8400	1	\$ 135.00	\$ 135.00
X 11	Front Sponge	1	\$ 98.00	\$ 98.00
X 12	Front Tow Eye Cover	1	\$ 18.00	\$ 18.00
13	Front Grille Assy	1	\$ 395.00	\$ 395.00
INV 14	Front Lower Grille Assy	1	\$ 136.00	\$ 136.00
INV 15	Front Grille Clips	10	\$ 5.00	\$ 50.00
16	Front Bumper Air Intake Moulding - 86522H8400	1	\$ 95.00	\$ 95.00
X 17	Head Lamp RH	1	\$ 2,000.00	\$ 2,000.00
18	Head Lamp LH	1	\$ 2,000.00	\$ 2,000.00
X 21	Fog Lamp LH - 92201H8000	1	\$ 215.00	\$ 215.00
X 22	Fog Lamp Cover LH - 86523H8030	1	\$ 78.00	\$ 78.00
X 23	Radiator Top Garnish	1	\$ 50.00	\$ 50.00
24	Front Fender RH	1	\$ 380.00	\$ 380.00
X 25	Front Fender Enclosure RH - 84126H8400	1	\$ 50.00	\$ 50.00
INV 26	Front Fender Shield RH	1	\$ 75.00	\$ 75.00
27	Front Fender Arc Garnish RH	1	\$ 60.00	\$ 60.00
X 28	Front Fender Arc Garnish LH	1	\$ 60.00	\$ 60.00
INV 29	Front Fender Shield Clips	10	\$ 5.00	\$ 50.00
30	Rear Fender Arc Garnish RH	1	\$ 60.00	\$ 60.00
INV 31	Rear Fender Shield RH	1	\$ 75.00	\$ 75.00
INV 32	Rear Fender Shield Clips	10	\$ 5.00	\$ 50.00
INV 33	Side Sill RH	1	\$ 390.00	\$ 390.00
INV 34	Side Sill Special Clips	5	\$ 6.00	\$ 30.00

ARC**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2203-120 TG

DATE : 3-Mar-2022

POLICY NO. : P10616316R00

VEHICLE REG. NO. : SLE110Y

VEHICLE MAKE : KIA STONIC 1.0 DCT

TO Motor Claim Department
 China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
X 35	Side Mirror Motor Assy RH X (11)	1	\$ 628.00	\$ 628.00
X 39	A-Pillar Triangle Garnish RH X (11)	1	\$ 30.00	\$ 30.00
40	Front Door RH / 00	1	\$ 959.00	\$ 959.00
X 41	Front Door Upper Hinge RH ? X nn	1	\$ 45.00	\$ 45.00
X 42	Front Door Lower Hinge RH ? X nn	1	\$ 45.00	\$ 45.00
X 43	Front Door Checker RH X nn	1	\$ 40.00	\$ 40.00
X 44	Front Door Striker RH - 81450A9100 X nn	1	\$ 32.00	\$ 32.00
X 45	Front Door Handle Assy RH ? X nn	1	\$ 150.00	\$ 150.00
X 46	Front Door Handle Cover RH ? X nn	1	\$ 30.00	\$ 30.00
X 47	Front Door Handle Base RH ? X nn	1	\$ 40.00	\$ 40.00
X 48	Front Door Lock Assy RH ? X nn	1	\$ 180.00	\$ 180.00
X 49	Front Door Window Regulator RH ? X nn	1	\$ 200.00	\$ 200.00
X 50	Front Door Speaker RH ? X nn	1	\$ 350.00	\$ 350.00
X 51	Front Door Trim RH ? X nn	1	\$ 600.00	\$ 600.00
52	Front Door Outside Weatherstrip RH - 82220H8000	1 X	\$ (11) 40.00	\$ 40.00
53	Front Door Upper Black Tape RH / MC	1	\$ 22.00	\$ 22.00
54	Front Door Side Black Tape RH / MC	1	\$ 22.00	\$ 22.00
55	Front Door Side Rubber Weatherstrip - 82140H8000	1 / 11	\$ 90.00	\$ 90.00
X 56	Front Door Body Side Rubber Weatherstrip RH - 82120H8000 X	1 nn	\$ 90.00	\$ 90.00
X 57	Front Door Window Run Channel Rubber Seal RH - 82540H8000 X	1 nn	\$ 95.00	\$ 95.00
58	Front Door Lower Garnish RH / RT	1	\$ 130.00	\$ 130.00
X 59	Front Door Electrical Wiring Harness Assy RH X (11)	1	\$ 700.00	\$ 700.00
60	Rear Door RH / 00	1	\$ 959.00	\$ 959.00
X 61	Rear Door Upper Hinge RH ? X nn	1	\$ 45.00	\$ 45.00
62	Rear Door Lower Hinge RH ?	1 BT	\$ 45.00	\$ 45.00
X 63	Rear Door Checker RH X nn	1	\$ 40.00	\$ 40.00
X 64	Rear Door Striker RH X nn	1	\$ 35.00	\$ 35.00
65	Rear Door Handle Assy RH ?	1 BR	\$ 150.00	\$ 150.00
66	Rear Door Handle Cover RH ?	1 BR	\$ 45.00	\$ 45.00
X 67	Rear Door Handle Base RH ? X nn	1	\$ 40.00	\$ 40.00
X 68	Rear Door Lock Assy RH ?	1 BT	\$ 180.00	\$ 180.00
X 69	Rear Door Window Regulator RH ? X nn	1	\$ 200.00	\$ 200.00
X 70	Rear Door Speaker RH ? X nn	1	\$ 350.00	\$ 350.00

ARC**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586

Tel: 64688834 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2203-120 TG

DATE : 3-Mar-2022

POLICY NO. : P10616316R00

VEHICLE REG. NO. : SLE110Y

VEHICLE MAKE : KIA STONIC 1.0 DCT

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
X 71	Rear Door Trim RH X nn	1	\$ 600.00	\$ 600.00
X 72	Rear Door Outside Weatherstrip RH - 83220H8410 X nn	1	\$ 55.00	\$ 55.00
X 73	Rear Door Upper Black Tape RH / MC	1	\$ 22.00	\$ 22.00
X 74	Rear Door Side Black Tape RH / MC	1	\$ 22.00	\$ 22.00
X 75	Rear Door Side Rubber Weatherstrip - 83140H8400 X nn	1	\$ 120.00	\$ 120.00
X 76	Rear Door Body Side Rubber Weatherstrip RH - 83120H8400	1 X	\$ nn 90.00	\$ 90.00
X 77	Rear Door Window Run Channel Rubber Seal RH - 83541H8400 X	10	\$ nn 200.00	\$ 2,000.00
X 78	Rear Door Window Channel Division RH - 83520H8400 X nn	1	\$ 50.00	\$ 50.00
X 79	Rear Door Lower Garnish RH / CVT	1	\$ 130.00	\$ 130.00
X 80	Rear Door Electrical Wiring Harness Assy RH X nn	1	\$ 750.00	\$ 750.00
X 81	Rear Axle Assy ? / 1 BT	1	\$ 1,450.00	\$ 1,450.00
X 83	Rear Axle Mounting Bolt RH - 55117B9000 ? X nn	2	\$ 12.00	\$ 24.00
X 84	Rear Absorber Assy RH ? / 1 BT	1	\$ 250.00	\$ 250.00
X 85	Rear Absorber Bolt RH - 55117H2000 ? X nn	2	\$ 12.00	\$ 24.00
X 86	Rear Coil Spring Assy RH ? / 1 BT	1	\$ 450.00	\$ 450.00
X 87	Rear Wheelhub With Bearing Assy RH ? / 1 MC	1	\$ 340.00	\$ 340.00
X 88	Rear Wheelhub Bolt RH - 527552G000 ? X nn	5	\$ 12.00	\$ 60.00
X 89	Rear Wheelhub Bolt Washer RH - 52735F2000 ? X nn	1	\$ 12.00	\$ 12.00
X 90	Rear ABS Extension Cable RH - 91921H8300 ? X nn	1	\$ 120.00	\$ 120.00
X 91	Original KIA Stonic R15 Rim - 52910-H8400 / CVT	1	\$ 759.00	\$ 759.00
X 92	Rear Bumper - 86610H8410 (Black) X R	1	\$ 500.00	\$ 500.00
X 93	Rear Bumper Clips X nn	10	\$ 5.00	\$ 50.00
X 94	Rear Bumper Retainer RH X nn	1	\$ 35.00	\$ 35.00
X 95	Front Driver Seat Air Bag RH - 88920H8000 / DR	1	\$ 1,400.00	\$ 1,400.00
X 96	Front Driver Seatbelt Assy RH - 88820H8000WK / jmd	1	\$ 700.00	\$ 700.00
X 97	Front Passenger Seatbelt Assy LH - 88810H8000WK / jmd	1	\$ 700.00	\$ 700.00
X 98	Rear Passenger Seatbelt Assy RH - 89820H8000WK / jmd	1	\$ 1,100.00	\$ 1,100.00
X 99	Rear Passenger Seatbelt Assy LH - 89870H8200WK / jmd	1	\$ 1,100.00	\$ 1,100.00
X 100	Rear Passenger Seatbelt Assy (Center) - 89850H8100WK X nn	1	\$ 900.00	\$ 900.00
X 101	Roof Headliner / CR1	1	\$ 3,600.00	\$ 3,600.00
X 102	Roof Air Bag RH - 85020H8300 / BR	1	\$ 1,600.00	\$ 1,600.00
X 103	SRS Control Unit / MC	1	\$ 680.00	\$ 680.00
X 104	Front Door Air Bag Sensor RH X / MC	1	\$ 180.00	\$ 180.00

48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2203-120 TG
DATE : 3-Mar-2022
POLICY NO. : P10616316R00
VEHICLE REG. NO. : SLE110Y
VEHICLE MAKE : KIA STONIC 1.0 DCT

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

P-14,660.00
-10%
13,194.00

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
X105	Side Wall Air Bag Sensor RH <i>1 X 111</i>	1	\$ 180.00	\$ 180.00
Total Spare Parts				\$ 35,065.00
SPECIAL NETT				
106	Front License Plate with Frame <i>111</i>	1	\$ 40.00	\$ 40.00
Total Special Nett				\$ 40.00
LABOUR				
107	Spray Paint (Front Bumper, Front Fender RH, Front Fender LH, Front Door RH, Rear Door RH, Rear Fender RH, Rear Bumper, A-Pillar RH, Side Mirror RH & Tail Gate RH)	1	\$ 2,000.00	\$ 2,000.00
108	Remove, Refit, Repair and Replace Accident Affected Parts	1	\$ 2,400.00	\$ 2,400.00
109	Repair & Respray Side Wall RH	1	\$ 600.00	\$ 600.00
110	Remove, Refit & Replace Rear Axle	1	\$ 350.00	\$ 350.00
111	Remove, Refit & Replace Rear Undercarriage RH	1	\$ 300.00	\$ 300.00
112	Transfer Door Fitting and Window Mechanism to New Door	2	\$ 50 100.00	\$ 200.00
113	Remove, Refit Seats, Roof Headliner & Related Parts (Airbags)	1	\$ 350.00	\$ 350.00
114	Remove & Refit Upholstery, Garnishes, Trimming To Facilitate Repair	1	\$ 250.00	\$ 250.00
115	Repair Front Seat Leather & Cushion (Damaged Area)	1	\$ 350.00	\$ 350.00
116	Computerized Wheel Alignment	1	\$ 80.00	\$ 80.00
117	Transfer Tyre To New Rim & Rear Wheel Balancing RH	1	\$ 100.00	\$ 100.00
118	Reset Fault Code, ECU, ABS, SRS Etc	1	\$ 150.00	\$ 150.00
119	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
120	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00

Estimate prepared by: Ken Ho

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour	\$ 7,260.00
Amount Before Excess	\$ 42,365.00
Add GST @ 7%	2,965.55
Total Amount Payable	\$ 45,330.55

3100

SUP

Rear Fender shield Special clip x5 (missing) *Steve (LKK) 4/3/22, 1.9pm*
Rear Inner Trim RH \$1980 (photo)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ARC

Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

Supplementary Estimate

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2203-120-TG (SUP)

DATE : 31-Mar-2022

POLICY NO. : P10616316R00

VEHICLE REG. NO. : SLE110Y

VEHICLE MAKE : KIA STONIC 1.0 DCT

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Fendershield Special Clips <i>1PC (Door Trim)</i>	5	\$ 5.00	\$ 25.00
2	Rear Inner Trim RH <i>1 BR (Front RH Door Trim)</i>		\$ 1,980.00	\$ 1,980.00
Total Spare Parts				\$ 2,005.00
SPECIAL NETT				
Total Special Nett				\$ -
LABOUR				
Total Labour				\$ -
Amount Before Excess				\$ 2,005.00
Add GST @ 7%				140.35
Total Amount Payable				\$ 2,145.35

Estimate prepared by: Ken Ho

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

P-13,194.00
N-40
L-3100
Supp-626
= 16,960.00