



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2201647

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 23/03/2022
Reference CS3/III22002032/Tty3e2
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SLG 7183E
Insured Veh. SLL 8980M
Claim No. MFL2022D0001212
Policy No. D22MFL0000974
Accident Date 01/03/2022
Inspection Date 10/03/2022

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 10.03.2022 01.45pm	
- Dismantle Inspection 10.03.2022 04.57pm	
- After Repair Inspection 14.03.2022 10.59am	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM