

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

| | |
|---|---|
| To: India International Insurance Pte Ltd 64 Cecil Street #04-00 IOB Building Singapore 049711 | From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933 |
|---|---|

Attn: Zuhaidah Bte Samsuri

Date: 07 Mar 2022

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|-----------------------|
| Vehicle No | : SMR1871Y | Accident Date | : 03/03/2022 |
| Make | : TOYOTA PRIUS HYBRID | Policy No. | : D18MFL0003414_02 |
| Assignment Date | : 04/03/2022 | Excess | : S\$0.00 |
| Date of Inspection | : 04/03/2022 | Est. Duration of Repair | : 6 |
| Inspection At | : COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL) 205 BRADDELL ROAD SINGAPORE 579701 | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | |
|-----------------------------|----------------|
| Repairer's Estimate (Gross) | :S\$ 14,407.32 |
| Revised Amount | :S\$ 8,733.43 |
| Check Items (Estimated) | :S\$ 4,341.75 |
| Total | :S\$ 13,075.18 |

| | |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

Total Loss Consideration

| | |
|--------------------|-----------------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ 112,000.00 |
| COE / PARF Rebate | :S\$ 44,719.00 |

| | |
|-------------------|----------------|
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ 67,281.00 |

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.