



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 04.03.2022

MS First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

Attn: Motor Claims Dept

RE: ESTIMATE COST TO VEHICLE SMR2387Y HONDA SHUTTLE HYBRID

Registration Date: 26/12/2019

To Supply

1) 1pc right rear fender	X R	\$	1,010.90
2) 1pc right rear fender cowling	X nn	\$	89.00
3) 1pc right rear fender glass moulding	X nn	\$	110.00
4) 1pc right rear door	/ 00	\$	988.00 -
5) 1pc right lower rocker panel garnish	/ RR	\$	550.00 400 -

1388
-10%
1110.40

Sub total parts	\$	2,747.90
Less: 20% discount	\$	(549.58)
	\$	2,198.32

To supply S.Nett parts

1) 1pc right rear wheel cap	X nn	\$	195.00
2) 1pc right rear fender cowling clip	X nn	\$	15.00
3) 1tube sealant	X nn	\$	40.00

Sub total S/Nett parts	\$	250.00
------------------------	----	--------

L/charges

1) To remove & refit right rear fender glass, replace moulding & sealant	\$	60.00 X
---	----	---------

- | | | |
|--|----|------------|
| 2) To transfer right rear door glass, mechanism parts | \$ | 40.00 X |
| 3) To tuff kote affected area | \$ | 60.00 30 |
| 4) To cut/ welding right rear fender, remove right rear door, right lower rocker panel garnish, repair rear bumper, replace necessary parts. | \$ | 800.00 500 |
| 5) To putty, respray painting rear bumper & rear right fender inner & outer, right rear door inner & outer and lower rocker panel garnish To polish | \$ | 900.00 800 |

1330

= 2440.40

L/S - 1952.32

= 1950

Sub total L/charges	\$	1,860.00
Estimated Grand Total	\$	4,308.32

Steve (LKK)

4/3/22, 300p

WL PL

L/S

My PL by

4 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: