

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III22002043/GPA3Q2**Date:** 30/06/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0000637\_02

**Claimant Vehicle No :** FBN7865C**Insured Vehicle No :** FBN7900J

Date of Loss: 24/02/2022

Nature of Claim: TP

Claim No: MFL2022D0001189

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBN7865C**

Make &amp; Model: YAMAHA YBR125, 124cc (M)

Engine No: E3F5E045288

Reg. Date: 10/12/2018 (Man. Year: 2018)

Chassis No: LBPRI1028J0010586

Colour: Red

Odometer: 32352 km

Engine Capacity: 124 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 2.75-18

Rear Tyre Size: 2.75-18

Front Left Side: Timsun 6 mm

Rear Left Side: Timsun 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,211.63	1,211.63	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	270.00	250.00	20.00	7.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,481.63</b>	<b>1,461.63</b>	<b>20.00</b>	<b>1.35</b>
<b>+ GST 7.00/7.00% (S\$)</b>	103.71	102.31	1.40	1.35
<b>Nett Amount (S\$)</b>	<b>1,585.34</b>	<b>1,563.94</b>	<b>21.40</b>	<b>1.35</b>
<b>+ Loss of Use (3.0 x S\$25.00/day) (S\$)</b>		75.00		
<b>Nett Liability (S\$)</b>		<b>1,638.94</b>		

INSPECTION

Date of Assignment: 04/03/2022

Date Inspected: 08/03/2022 Inspected At:

Kang Car Repairers Pte Ltd (HQ)

No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki

Bukit

Singapore 417883

Estimated Period of Repair: 3.0 days

**Adjuster:** XING GUO QIANG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 06 Jun 2022)	
<b>Parts:</b>	N/A	YAMAHA YBR125 124cc (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBN7865C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER	Deformed	39.00 FL	*39.00 FL
2	1		*COVER TAIL 2	Deformed	50.00 FL	*50.00 FL
3	1		*HANDLEBAR	Bent	32.00 FL	*32.00 FL
4	1		*GRIP ASSY	Cut	12.00 FL	*12.00 FL
5	1		*LEVER 2	Cut	12.51 FL	*12.51 FL
6	1		*BLUE LIGHT	Distorted	35.00 FL	*35.00 FL
7	1		*ORANGE LIGHT	Distorted	35.00 FL	*35.00 FL
8	1		*FRONT UPPER CRASHBAR	Cut	400.00 FS	*400.00 FS
9	1		*FRONT LOWER CRASHBAR	Cut	400.00 FS	*400.00 FS
10	1		*RHR CRASHBAR	Cut	250.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>1,265.51</b>	<b>1,265.51</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	53.88	53.88
<b>Total Parts (\$)</b>	<b>1,211.63</b>	<b>1,211.63</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REPLACE ACCIDENT PARTS	New	150.00	150.00
2	LABOUR ALIGNMENT	New	120.00	100.00
<b>Gross Labour Cost (S\$)</b>			<b>270.00</b>	<b>250.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >