

VERTEX EURO MOTORS PTE LTD

3 Ubi Road 4 Singapore 408608
 TEL: (+65) 6742-9368 FAX: (+65) 6742-5281
 RCB NO:201535856D

M/S : LI XIN RAN
 BLK 688C WOODLANDS DR 75
 #06-42
 SINGAPORE 733688

Estimate No: **WQT1602539**
 Date: 02 Mar 2022
 Policy No:
 Veh Reg No: **SML1963Y**
 Make/Model: **SEAT ARONA FR 1.0**
TSI 116 7AT
 Chassis No: **VSSZZZKJZMR065595**
 Engine No: **DKJ 105947**
 Reg. Date: 08/02/2021
 Payment Term: **COD**

ATTN:

Your Ref No: **SML1963Y**
 Claim Type: **Third Party**
 Accident Date:

Estimate Repair Cost to Vehicle No :SML1963Y

Description	Quantity	List Price	Amount
		S\$	S\$
Others			
1 BUMPER REINF RR *	1 PC	620.00	?bt ✓
2 BUMPER SPONGE RR CTR	1 PC	100.00	?cra ✓
3 BUMPER BKT RR LH INN	1 PC	60.00	? } nnt
4 BUMPER BKT RR RH INN	1 PC	60.00	? } nnt
5 BUMPER BKT RR LH OTR	1 PC	80.00	? } nnt
6 BUMPER BKT RR RH OTR	1 PC	80.00	? } nnt
7 STRIP-BUMPER RR LH	1 PC	150.00	? nec ✓
8 STRIP-BUMPER RR RH	1 PC	150.00	? nec ✓
9 SENSOR BKT NO.6 *	1 PC	60.00	nec ✓
10 SENSOR BKT NO.5 *	1 PC	60.00	nec ✓
11 SENSOR BKT NO.4 *	1 PC	60.00	nec ✓
12 SENSOR BKT NO.3 *	1 PC	60.00	nec ✓
13 SENSOR BKT NO.2 *	1 PC	60.00	nec ✓
14 SENSOR BKT RR LH OTR *	1 PC	60.00	nec ✓
15 O-RING-P/SENSOR *	6 PCS	30.00	nec ✓
16 BUMPER RR	1 PC	1,400.00	de ✓
17 B/REFLECTOR LH	1 PC	50.00	x nnt ✓
18 B/REFLECTOR RH	1 PC	50.00	x nnt ✓
19 BUMPER SPOILER RR	1 PC	650.00	de ✓
20 BUMPER SPOILER TRIM RR-KATANA SILVER	1 PC	550.00	de ✓
21 TRIM PANEL BUMPER RR LH-silver	1 PC	330.00	x nnt ✓
22 TRIM PANEL BUMPER RR RH-silver	1 PC	330.00	?nt ✓
23 BUMPER TOW CAP RR	1 PC	55.00	x nnt ✓
24 BOLT-SPOILER	2 PCS	6.00	nec ✓
25 RIVET	2 PCS	4.00	nec ✓
26 LID RR	1 PC	2,600.00	bt ✓
27 LID HINGE L/R	2 PCS	410.00	? ✓
28 LID LOCK MICRO SWITCH RR	1 PCS	180.00	x } nnt
29 LID PUSH BUTTON W CAMERA	1 PC	860.00	x } nnt
30 T/LAMP LH INN	1 PC	520.00	x } nnt
31 T/LAMP RH INN	1 PC	520.00	x } nnt
32 T/LAMP LH OTR	1 PC	640.00	x } nnt
33 T/LAMP RH OTR	1 PC	640.00	x } nnt
34 LID LOGO 'ARONA' *	1 PC	80.00	nec ✓
35 LOGO-'S' LID	1 PC	100.00	nec nec ✓
36 LOGO "FR" RR	1 PCS	70.00	nec ✓
37 NUMBER PLATE REAR	1 PC	80.00	x nnt ✓

VERTEX EURO MOTORS PTE LTD

3 Ubi Road 4 Singapore 408608
 TEL: (+65) 6742-9368 FAX: (+65) 6742-5281
 RCB NO:201535856D

M/S : LI XIN RAN
 BLK 688C WOODLANDS DR 75
 #06-42
 SINGAPORE 733688

Estimate No: **WQT1602539**
 Date: 02 Mar 2022
 Policy No:
 Veh Reg No: **SML1963Y**
 Make/Model: SEAT ARONA FR 1.0
 TSI 116 7AT
 Chassis No: VSSZZKJZMR065595
 Engine No: DKJ 105947
 Reg. Date: 08/02/2021
 Payment Term: COD

ATTN:

Your Ref No: SML1963Y
 Claim Type: Third Party
 Accident Date:

Estimate Repair Cost to Vehicle No :SML1963Y

Description	Quantity	List Price	Amount
38 WINDSCREEN RR - photo	1 PC	1,330.00	1,330.00
39 W/SCREEN SEALANT	2 PC	80.00	160.00
40 LABOUR TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	1	180.00	180.00
41 LABOUR TO INSTALL REAR WINDSCREEN	1	480.00	480.00
42 LABOUR TO TO INSTALL SOLAR FILM	1	400.00	400.00
43 LABOUR TO REMOVE, REPAIR, REINSTALL RR LID,RR BUMPER,IRON PANEL 650.	1	2,600.00	1,950.00
44 LABOUR TO RESPRAY RR LID, RR BUMPER,IRON PANEL 600	1	2,000.00	1,800.00
45 LABOUR TO CARRY OUT DIAGNOSTIC CHECK	1	180.00	180.00
46 SUNDRIES	1	120.00	40.00
		19,185.00	19,185.00
		Total	S\$ 19,185.00
		Add GST @ 7%	1,342.95
		Total Amount Payable	S\$ 20,527.95

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND FIVE HUNDRED TWENTY SEVEN AND CENTS NINETY FIVE ONLY

For VERTEX EURO MOTORS PTE LTD



AUTHORISED SIGNATURE

Tan Jiah @ 97495749 / 62563561
 Wp' 7/3/22 @ 220pm
 Resurvey before part
 05 days 7 days
 tanjiah@lkhauto.com

8790
 4450
 \$13,240 #
 7 days #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company