

# VERTEX EURO MOTORS PTE LTD

RCB NO:201535856D  
3 Ubi Road 4 Singapore 408608  
TEL: (+65) 6742-9368 FAX: (+65) 6742-5281

**TAX INVOICE NO:**

**WS1609277**

Owner's Information		Service Advisor	Job Card No		
A/C: C0148 CHINA TAIPING INSURANCE (SINGAPORE) PTE.LTD.  3 ANSON ROAD #15-00 SPRINGLEAF TOWER SINGAPORE 079909		RAYMOND TING SING WEI	JB1609167		
	Registration No.	Make/Model		Date of Invoice	
	SML1963Y	SEAT ARONA FR 1.0 TSI 116 7AT		22/04/2022	
	Mileage (km)	Next Mileage	Next Service Date	Date In	Time In
	18048			28/03/2022	9:25 AM
	Chassis No.		Engine No.	Promised Date/Time	
	VSSZZKJZMR065595		DKJ 105947	04/04/2022 5:30:00 PM	

Service Description	Quantity	Unit Price	Amount
		SS	SS
BUMPER REINF RR	1 PC	620.00	620.00
BUMPER SPONGE RR CTR	1 PC	100.00	100.00
STRIP-BUMPER RR LH	1 PC	150.00	150.00
STRIP-BUMPER RR RH	1 PC	150.00	150.00
SENSOR BKT NO.6	1 PC	60.00	60.00
SENSOR BKT NO.5	1 PC	60.00	60.00
SENSOR BKT NO.4	1 PC	60.00	60.00
SENSOR BKT NO.3	1 PC	60.00	60.00
SENSOR BKT NO.2	1 PC	60.00	60.00
SENSOR BKT RR LH OTR	1 PC	60.00	60.00
O-RING-P/SENSOR 10-3600	6 PCS	5.00	30.00
BUMPER RR	1 PC	1,400.00	1,400.00
BUMPER SPOILER RR	1 PC	650.00	650.00
BUMPER SPOILER TRIM RR-KATANA SILVER	1 PC	550.00	550.00
TRIM PANEL BUMBER RR RH-silver	1 PC	330.00	330.00
RIVET 25-500	2 PCS	2.00	4.00
BOLT-SPOILER 25-1000	2 PCS	3.00	6.00
LID RR	1 PC	2,600.00	2,600.00
LID LOGO 'ARONA'	1 PC	80.00	80.00
LOGO "FR" RR 1-240	1 PCS	70.00	70.00
LOGO-'S' LID	1 PC	100.00	100.00
WINDSCREEN RR	1 PC	1,330.00	1,330.00

# VERTEX EURO MOTORS PTE LTD

RCB NO:201535856D  
3 Ubi Road 4 Singapore 408608  
TEL: (+65) 6742-9368 FAX: (+65) 6742-5281

**TAX INVOICE NO:**

**WS1609277**

<b>Owner's Information</b>		<b>Service Advisor</b>	<b>Job Card No</b>
A/C: C0148 CHINA TAIPING INSURANCE (SINGAPORE) PTE.LTD.  3 ANSON ROAD #15-00 SPRINGLEAF TOWER SINGAPORE 079909		RAYMOND TING SING WEI	JB1609167
	<b>Registration No.</b>	<b>Make/Model</b>	<b>Date of Invoice</b>
	SML1963Y	SEAT ARONA FR 1.0 TSI 116 7AT	22/04/2022
	<b>Mileage (km)</b>	<b>Next Mileage</b>	<b>Next Service Date</b>
	18048		28/03/2022
	<b>Chassis No.</b>	<b>Engine No.</b>	<b>Promised Date/Time</b>
	VSSZZZKJZMR065595	DKJ 105947	04/04/2022 5:30:00 PM

Service Description	Quantity	Unit Price	Amount
		<u>SS</u>	<u>SS</u>
W/SCREEN SEALANT	2 PC	40.00	80.00
LABOUR TO REMOVE AND REINSTALL RREAR PARKING AID.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	1	180.00	180.00
LABOUR TO INSTALL REAR WINDSCREEN	1	480.00	480.00
LABOUR TO REMOVE,REPAIR AND REINSTALL RR LID,RR BUMPER,IRON PANEL	1	1,950.00	1,950.00
LABOUR TO RESPRAY RR LID,RR BUMPER, IRON PANEL	1	1,800.00	1,800.00
LABOUR TO CARRY OUT DIAGNOSTIC CHECK 25-1500	1	180.00	180.00
SUNDRIES 25-4800	1	40.00	40.00
		TOTAL	<b>SS 13,240.00</b>
		ADD GST @ 7%	926.80
		<b>GRAND TOTAL</b>	<b>SS 14,166.80</b>

SINGAPORE DOLLAR FOURTEEN THOUSAND ONE HUNDRED SIXTY SIX AND CENTS EIGHTY ONLY

Remark: 1.)ACCIDENT CLAIM.(TP CLAIM)SNM22D201512/C02/GBK4689E/LEEPG  
2.)REPLACE FRT W/BLADE REQUEST BY CUSTOMER



Customer's Signature/Co. Stamp

E. & O. E.

Service Advisor's Signature