

VERTEX EURO MOTORS PTE LTD

3 Ubi Road 4 Singapore 408608
 TEL: (+65) 6742-9368 FAX: (+65) 6742-5281
 RCB NO:201535856D

M/S : LI XIN RAN
 BLK 688C WOODLANDS DR 75
 #06-42
 SINGAPORE 733688

Estimate No: WQT1602539
Date: 02 Mar 2022
Policy No:
Veh Reg No: SML1963Y
Make/Model: SEAT ARONA FR 1.0
 TSI 116 7AT
Chassis No: VSSZZKJZMR065595
Engine No: DKJ 105947
Reg. Date: 08/02/2021
Payment Term: COD

ATTN:

Your Ref No: SML1963Y
Claim Type: Third Party
Accident Date:

Estimate Repair Cost to Vehicle No :SML1963Y

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
Others			
1 BUMPER REINF RR *	1 PC	620.00	
2 BUMPER SPONGE RR CTR	1 PC	100.00	
3 BUMPER BKT RR LH INN	1 PC	60.00	
4 BUMPER BKT RR RH INN	1 PC	60.00	
5 BUMPER BKT RR LH OTR	1 PC	80.00	
6 BUMPER BKT RR RH OTR	1 PC	80.00	
7 STRIP-BUMPER RR LH	1 PC	150.00	
8 STRIP-BUMPER RR RH	1 PC	150.00	
9 SENSOR BKT NO.6 *	1 PC	60.00	
10 SENSOR BKT NO.5 *	1 PC	60.00	
11 SENSOR BKT NO.4 *	1 PC	60.00	
12 SENSOR BKT NO.3 *	1 PC	60.00	
13 SENSOR BKT NO.2 *	1 PC	60.00	
14 SENSOR BKT RR LH OTR *	1 PC	60.00	
15 O-RING-P/SENSOR *	6 PCS	30.00	
16 BUMPER RR	1 PC	1,400.00	
17 B/REFLECTOR LH	1 PC	50.00	
18 B/REFLECTOR RH	1 PC	50.00	
19 BUMPER SPOILER RR	1 PC	650.00	
20 BUMPER SPOILER TRIM RR-KATANA SILVER	1 PC	550.00	
21 TRIM PANEL BUMPER RR LH-silver	1 PC	330.00	
22 TRIM PANEL BUMPER RR RH-silver	1 PC	330.00	
23 BUMPER TOW CAP RR	1 PC	55.00	
24 BOLT-SPOILER	2 PCS	6.00	
25 RIVET	2 PCS	4.00	
26 LID RR	1 PC	2,600.00	
27 LID HINGE L/R	2 PCS	410.00	
28 LID LOCK MICRO SWITCH RR	1 PCS	180.00	
29 LID PUSH BUTTON W CAMERA	1 PC	860.00	
30 T/LAMP LH INN	1 PC	520.00	
31 T/LAMP RH INN	1 PC	520.00	
32 T/LAMP LH OTR	1 PC	640.00	
33 T/LAMP RH OTR	1 PC	640.00	
34 LID LOGO 'ARONA' *	1 PC	80.00	
35 LOGO-'S' LID	1 PC	100.00	
36 LOGO "FR" RR	1 PCS	70.00	
37 NUMBER PLATE REAR	1 PC	80.00	

VERTEX EURO MOTORS PTE LTD

3 Ubi Road 4 Singapore 408608
 TEL: (+65) 6742-9368 FAX: (+65) 6742-5281
 RCB NO:201535856D

M/S : LI XIN RAN
 BLK 688C WOODLANDS DR 75
 #06-42
 SINGAPORE 733688

Estimate No: WQT1602539
Date: 02 Mar 2022
Policy No:
Veh Reg No: SML1963Y
Make/Model: SEAT ARONA FR 1.0
 TSI 116 7AT
Chassis No: VSSZZKJZMR065595
Engine No: DKJ 105947
Reg. Date: 08/02/2021
Payment Term: COD

ATTN:

Your Ref No: SML1963Y
Claim Type: Third Party
Accident Date:

Estimate Repair Cost to Vehicle No :SML1963Y

Description	Quantity	List Price	Amount
		S\$	S\$
38 WINDSCREEN RR	1 PC	1,330.00	
39 W/SCREEN SEALANT	2 PC	80.00	
40 LABOUR TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	1	180.00	
41 LABOUR TO INSTALL REAR WINDSCREEN	1	480.00	
42 LABOUR TO TO INSTALL SOLAR FILM	1	400.00	
43 LABOUR TO REMOVE, REPAIR, REINSTALL RR LID,RR BUMPER,IRON PANEL	1	2,600.00	
44 LABOUR TO RESPRAY RR LID, RR BUMPER,IRON PANEL	1	2,000.00	
45 LABOUR TO CARRY OUT DIAGNOSTIC CHECK	1	180.00	
46 SUNDRIES	1	120.00	
		<u>19,185.00</u>	19,185.00
		Total	S\$ 19,185.00
		Add GST @ 7%	1,342.95
		Total Amount Payable	S\$ 20,527.95

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND FIVE HUNDRED TWENTY SEVEN AND CENTS NINETY FIVE ONLY

For VERTEX EURO MOTORS PTE LTD

 AUTHORISED SIGNATURE