

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22002047/AGNY3E2

Date: 04/08/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001968223
Claimant Vehicle No :	SLZ654J	Insured Vehicle No :	YP4169R
Date of Loss:	19/02/2022	Nature of Claim:	TP
		Claim No:	270268

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ654J	Engine No:	HIDDEN
Make & Model:	MITSUBISHI SPACE STAR, 1.2 (A)	Chassis No:	MMCXTA03AJH021103
Reg. Date:	01/04/2018 (Man. Year: 2018)	Odometer:	58843 km
Colour:	Silver		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,608.81	1,698.62	2,910.19	63.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,790.00	1,310.00	2,480.00	65.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,398.81	3,008.62	5,390.19	64.18
Approved Total (Overridden) (S\$)		2,400.00		
Nett Amount (S\$)	8,398.81	2,400.00	5,998.81	71.42

INSPECTION

Date of Assignment:	04/03/2022	
Date Inspected:	07/03/2022	Inspected At: Kt Motorwerk (HQ) Blk 3012 Bedok Industrial Park E, #01-2020 Singapore 489978
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jul 2022)
Parts:	143	MITSUBISHI SPACE STAR 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ654J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER RH	Repair	987.50 FL	*- FL
2	1		*REAR FENDER INNERCOWLING RH	Deformed	135.80 FL	*135.80 FL
3	1		*REAR DOOR RH	Dented	1,025.80 FL	*1,025.80 FL
4	1		*REAR DOOR INNERTRIM RH	Not Necessary	385.90 FL	*- FL
5	1		*REAR DOOR WEATHERSTRIP RH (DOOR)	Torn	163.20 FL	*163.20 FL
6	1		*REAR DOOR WEATHERSTRIP RH (FRAME)	Not Necessary	165.30 FL	*- FL
7	1		*REAR DOOR OUTER HANDLE RH	Damaged	125.90 FL	*125.90 FL
8	1		*REAR DOOR INNERLOCK RH	Damaged	295.80 FL	*295.80 FL
9	1		*REAR DOOR OUTER MOLDING RH	Not Necessary	198.60 FL	*- FL
10	1		*REAR DOOR STICKER RH	Necessary	85.30 FL	*85.30 FL
11	1		*SIDESKIRT RH	Repair	498.20 FL	*- FL
12	1		*REAR RIM RH	Not Necessary	853.60 FL	*- FL
13	1		*SET REAR FENDER INNER COWLING CLIPS	Necessary	30.00 FS	*20.00 FS
14	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	30.00 FS	*- FS
15	2		*PANEL JOINT SEALANT	Not Necessary	60.00 FS	*- FS
16	1		*SET SIDESKIRT CLIPS	Not Necessary	30.00 FS	*- FS
17	1		*SET REAR DOOR INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,100.90	1,881.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	492.09	183.18
Total Parts (\$\$)	4,608.81	1,698.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	New	1,600.00	500.00
2	TO RESPRAY AFFECTED AREAS	New	1,600.00	600.00
3	TO TUFFCOAT AFFECTED AREAS	New	200.00	80.00
4	TO REMOVE / REFIT / REPLACE REAR DOOR MECHANISM	New	120.00	80.00
5	TO REMOVE / REFIT REAR INTERIOR UPHOLSTERY	New	150.00	50.00
6	WHEEL ALIGNMENT BEFORE AND AFTER	New	120.00	0.00
Gross Labour Cost (\$)			3,790.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >